

CROW WING COUNTY S-101
COUNTY SURVEYOR - 1981 TIES

BOOK S-101

CORNERS NOT VISITED

- X-1 THIS CORNER SET BY WARREN FOREBERG #4846 BY LOST METHOD BETWEEN NW & SW COR. SEC. 31 EXISTING S.W. COR. SEC. 31 IS IN ERROR
- Z-1 IN MY WORK IN SEC. 1 44-29 I FOUND A 2" PIPE 4' HIGH AT THIS CORNER. THIS PIPE POSSIBLY SET BY OWNER TO S.E. I FIND IT TO BE WRONG - NEW CORNER NOT SET AT THIS TIME. [FOREBERG USED EXISTING PIPE IN HIS SUBDIVISION OF SEC. 31-45-28]
- Z-3 }
Z-5 } LOOKED FOR THESE PIPE
Z-7 } IN WINTER OF 1980 FOR WORK IN SEC. 1, 44-29 NOTHING FOUND.

BOOK S-101

Page 54
MAY 1, 1981
RAY

- (OFFICE)
- R-6/7 } THESE M.C.'S ARE
R-6/7 } NOW WITHIN PLAT OF PORTAGE PASS DEVEL. COMPANY - HAVE NO VALUE IN MY OPINION.
- E-14/15 THESE M.C.'S BETWEEN
E-14/15 SEC. 3 & 10 ARE ON MALKERSON'S ISLAND (ISLAND ALL IN ONE OWNER - SHIP.)
- SEC. 3 HAS BEEN SUBDIVIDED CORNERS HAVE NO VALUE IN MY OPINION.
- H/J-17 THESE M.C.'S BETWEEN
H/J-17 SEC. 10 & 11 CROSS WITH CHURCH ISLAND - ALL IN ONE OWNER SAID NO VALUE IN MY OPINION.

BOOK S-101

L/M-9 M.C.

T45N R28W

NORTH SIDE CROOKED LAKE

FOUND F.P. 3/10 place
as shown.

NO EVIDENCE OF
ORIGINAL TIES.

TIES FIT CLOSELY
TO THOSE RECORDED
IN BOOK 235/45 W.S.N.

DID NOT TAKE DIST
SOUTH OR NORTH TO
VERIFY THIS AS ORIG.
M.C. LOCATION

TIME 2 HR.

BOOK S-101

L/M-9 M.C.


T45N R28W

Page 53
April 30, 1981

Ray

Home

Clear, warm



BOOK S-101

N - 7/8 m.c.

17

East side coked lake

20

T45N R28W

Ed Walz (owner to north) showed us

pipe approx 3' high 15' out in lake.

SAID ICE HAD PULLED PIPE MANY TIMES - HE HAD RESET.

NO TIES FOUND THIS IS ALL LAWN AREA w/ many hot rocks. FOUND PIPE ALONG SHORE TO SOUTH IN GOOD SHAPE.

TIME 1 1/2 HR.

BOOK S-101

N - 7/8 m.c.

17

20

T45N R28W

Ed Walz (owner to north) showed us

pipe approx 3' high 15' out in lake.

SAID ICE HAD PULLED PIPE MANY TIMES - HE HAD RESET.

NO TIES FOUND THIS IS ALL LAWN AREA w/ many hot rocks. FOUND PIPE ALONG SHORE TO SOUTH IN GOOD SHAPE.

Page 51
April 30, 1981

Ray

Homer

clear, warm

BOOK S-101

M/N-9 M.C. 7/16

SOUTH side crooked lake.

Find I.P. in place
w/ help of Frank
Lundgren (owner to
west) He had covered
pipe w/ fill and put
axel shaft inside.

From south this is
30'± short from
original m.c. distance.
Original ties are

Aspen.

Area has been filled
in 3 to 4' deep from
west w/ junk -
Locator useless -

1 1/2 hrs.

BOOK S-101

M/N-9 M.C. 7/16

TUSN 228W

CROOKED
LAKE

HOUSE

N.E. COR.
CONCRETE
SIDEWALK

17

O.K. MARK
NORTH SIDE
T. POLE

M63W

46.71

2' I.P. 6" DEEP

100.29
528.5
BIRCH
CANY

R.K. East
side pole

Page 59
Apr. 130, 1981

Ray

Home
clear, warm

BOOK S-101

N-3 1/4 COR.

18
19

T45N R220W

I TAPE EAST FROM

LAST CORNER (N-1)

2724 ±. Swamp tie

@415' ± fits good.

THIS LINE VERY

DIFFICULT AS THERE

CUT OVER LAND &

BRUSH.

FIND 2 very large

WHITE PINE still standing

(90'S Garrison found w.p.

still standing.)

BLAZE AREA ON LARGER

TREE ROTTED AWAY,

OTHER TREE SHOWS SCAR

BUT I DON'T THINK IT IS

ORIGINAL.

NO POST FOUND USING

THIS TREE AND NO

OTHER TREES OR STUMPS

NEAR

3 HIES ±

BOOK S-101

N-3 1/4 COR

18
19

T45N R220W

Page 49.
APR. 1 28, 1981

Ray

Homer

Clear, warm

BOOK S-101

N-1 Sec. Cor.

13 | 18
24 | 19

T45N
R29W

I TAPE NORTH FROM
LAST CORNER (P-1)
2640. @ 1900' had
to offset east 200'
to fit swamp tie.
no corner or ties
found.

3 APR 25 1961

BOOK S-101

N-1 Sec. Cor.

13 | 18
24 | 19

T45N
R29W

Page 48

April 28, 1961

Ray

T45N
R29W

clear - warm

NO. 447

WELBONE

BOOK S-101

P.1

1/4 COR.

24 19

45-29 45-28

TO LOOK FOR THIS CORNER

WE BEGIN AT THE SW

COR. SEC. 19. (R-1)

TAPE & COMPASS NORTH

EXISTING FENCE ON

LAST 1/4 mile seems

to run east of north.

STRICKER OLD E-W ROAD @

2640 and W fence.

VISITED WITH Adolph

Bordwell - HE purchased

NE-SE - 24-45-29 from county

in (?) George Kinney sent

man out to run Twp. line.

He came back and corrected

IT to its present fence

location;

NO CORNER FOUND

2 HR.

BOOK S-101

P-1

1/4 COR. 24 19


45-29 45-28

Page 47
April 28, 1981

Ray

Home

Clear, warm



Page 46
April 28, 1981

BOOK S-101

19
30

R-4/5 M.C.

T45N R28W

Ray

Homer

Clear, cool

BOOK S-101

19
30

R-4/5 M.C.

T45N R28W

I spent considerable
time here a couple
years ago and did not
find corners. Nothing

found today.

Shore logs going
south from this line

are occupied and have
some pipe. I believe
this is from a survey
of Holmstrom.

1 Hr.

BOOK S-101

S/T-1 W.C. 25 x 30

T45N R28W

2.5 ch. North of 1/4 cor.

Did not go to this
location AS 1/4
corner is in place
(C.W.C. monument)
SOUTH OF THIS

Time 0

BOOK S-101

S/T-1 W.C.

T45N R28W

Page 45
April 24, 1981

Homer

Rain

Clear Cool

BOOK S-101

R-3 1/4 COR.

T45N R28W

19
30

To look for this corner
we begin at the N.W.
corner Sec. 30 (R-1)
This is a nail set in
a root of a oak tree
and has good ties.
We tape a compass
east - swamp culls
fit good. 1/4 cor.
Location between
swamps on north and
south.

No corner found

Find many pine stumps

NOTE: HOLMSTROM HAS DONE
WORK SOUTH OF THIS
CORNER 1 CENTER SECTION
5 1/4 ARE IN PLACE AND HAVE
BEEN USED!!
TIME 3 hrs.

BOOK S-101


R-3 1/4 COR.

T45N R28W

19
30

Page 44
April 24, 1981

Ray
Homer
Clear, cool



BOOK S-101

X/Y-9 m.c.

32/33

T4SN R28W

If tape north from
2-9 (page 42) to
shore of Rice Lake
Swamp calls fit
No evidence of
fence found on
page 42.

NO corner found

TIME 2 1/2 HR.

BOOK S-101

X/Y-9 m.c.

32/33

T4SN R28W

Page 43

April 22, 1981

Ray

Homer

Cold, rain

BOOK S-101

Z-9 Sec. Cor.

45-28

32 | 33

5 | 4

44-28

Can't west from
Z-11 (page 41) 2640'
The first 1320 along
blue paint and ribbon
line. Swamp calls
fit good.
Corner falls in a
barren - burned over
swamp. No tamarack
trees or stumps in
area.

Found remains of
OLD FENCE (3 posts)
going north - 100' east
of our position!

NO CORNER FOUND

TIME 2 1/2 HR.

BOOK S-101

Z-9 Sec. Cor.

45-28

32 | 33

5 | 4

44-28

Ray
Homer
Cold, rain

Page 42

April 22, 1981

BOOK S-101

2-11 1/4 COR. 33-45-28
4-44-28

I tape west from
S.E. corner sec. 33
2640 ~ Fir swamp
calls very good.
Find blue ribbon
@ 2640 and orange
paint on trees.
Fresh logging around
this location.

No corner found

TIME 2 1/2 HR.

BOOK S-101
2-11 1/4 COR. 45-28
33

Page 41
April 22, 1981
Ray
Homer
Cold, rain

44-28

23.50
56

51
52
53
54
55
56

BOOK S-101

V/W - S m.c. 31/32

I taped south from
N.E. corner sec. 31
(in place) along edge
of field and old fence
800'± to edge of
swamp and found 1"
I.P. w/ fresh ribbon.
Can't on old fence to 924'
and find nail w/ ribbon,
on shore of lake.

I believe this to be
work of Furesberg (#4840)

I do not tie out I.P.
@ 800' as I believe this
survey in error due to
use of I.P. @ S.W. corner
of sec. 31 which I find
to be in error.

TIME 2 HRS.

BOOK S-101

V/W - S m.c. 31/32
TUSK RZBWPage 40
April 20, 1961Ray
Homer
clear, warm

BOOK S-101

U/V-5 M.C. 30/29
745N R28W

4-20-81

Found I.P. on shore,
tipped over, may have
been dozed out. Found
I.P. to N.W. along shore 193'±
(12254) and pipe S.E.
along shore 30'± and south
173.50± along sec. line.

As this M.C. is within the
boundary of Lot 1, Block
ONE - LITTLE PENNEROSA
It can be set from lot
corners very easily.

Did not reset


TIME 1HR.

BOOK S-101

U/V-5 M.C. 30/29
745N R28W

Page 39
April 20, 1981

Ray
Homer
clear, warm



BOOK S-101

V-7 1/4 COR.

T43N R28W

This corner seems to
fall in the N.W. 1/4
of large concrete
underpass - nothing
found!

29
32

BOOK S-101

V-7 1/4 COR.

T45N R28W

29

32

Page 38

April 20, 1981

Ray

Homer

Clear, warm

TIME 1 1/2 HRS.

BOOK S-101

V-51 Sec. Cor. 31/32

T45N R22BW

Found C.W.C. section
corner monument-Flush
with pavement surface

57.91

TIME 1 HR.


BOOK S-101

V-5 Sec. Cor. 31/32

T45N R22BW

Page 37
April 20, 1981

Ray
Homer
clear, warm



99.89
100.38
27.54
22.7.81

BOOK S-101

Z-14/15 M.C. } 34

T45N-R28W } 3

Found 1" I.P. 2" high
[dove down flush] on
Ice ridge

No Evidence of orig. trees

Tape 663± to lake, from
1/4 cor. to east

TIME 1 1/2 HR.

21

BOOK S-101

Z-14/15 M.C. } 34

T45N-R28W } 3


Page 36

April 20, 1981

Ray

Homer

clear, warm



BOOK S-101

X-17 1/4 COR. 34 35

T45N 228W

Found 1 3/4" pipe 2" high
in east ditch blyw.
#18. [we set it down
flush with gr.]

Harold Collins survey
2 April 1973 (w.s.w.)

TIME 1 HR.


BOOK S-101

X-17 1/4 COR. 34 35

T45N 228W

Page 35
April 20, 1981

Ray
Homer
clear, warm



99.23
2.32
120.54

O/P-9 M.C. 20/21
T45N R28W

FOUND 2" I.P. w/oval
cap stamped as
shown. 18" high
Tipped south 910'±

Bath of L. Knudson 1926
tie trees in place -
rough check Brg. & dist.
Did not use as trees
are old:


Conc. Map. 1/16 corner
(w.s.u.)
shown on sec. card as
B1.1 - did not check this
dist.

Time 1 1/2 hr.

O/P-9 M.C. 20/21
T45N R28W

Apr. 17, 1981

Ray
Homer
clear, warm
windy



BOOK S-101

P/Q-9 M.C.

T43N R23W

20/21

Found I.P. Laying
down. This is now
in the front yard
of new house and
ice ridge & shore
have been disturbed.

Survey work has been
done both east and
west from this M.C.
along shore and
would not be a problem
to reset if needed.

maghan surveys (OMA)

Time 1/2 Hr.

BOOK S-101

P/Q-9 M.C.

T43N R23W

20/21

Page 33

April 17, 1981

Ray

Home

clear, cool

windy

BOOK S-101

R-8/9 M.C.
T45N R28W

Found "I.P." in place
on end of fence
10" high

I don't think this
is in the original
M.C. position but
on south line of
Sec. 20

Time 1 hr.

BOOK S-101

R-8/9 M.C.
T45N R28W


T45N R28W

20

COOKED

LAKE

(HANKS' BAY)



Page 32
April 17, 1981

Ray
Homer
Clear, cool
windy

Lawrence Maghan

BOOK S-101

R-11 1/4 COR. $\frac{31}{28}$

T45N R28W

NOTHING FOUND

Ed Treska stopped
and talked to us.
owns NE 1/4 NW 1/4.
Said he had been
told ditch line to
south was on property
line. We also looked
for 1/16 cor to east
but unable to find.

Time 2 1/2 hrs.

BOOK S-101

R-11 1/4 COR.


$\frac{31}{28}$ T45N R28W

Page 31
April 17, 1981

Ray

Homer

Cool, windy



BOOK S-101

W/X-9 m.c. 32k33
T45U R28W

South from Sec. Cor.

66 66' to swamp.

396 330' out

792 396' to swamp

924 132' from spruce

1353 429 to m.c.

1' 1353

Tape south from
NW COR. SEC. 33 TO
shore of Rice Lake
NO CORNER FOUND

Swamp edges indefinite
Aspen only tie.

Time 3 HRS.

BOOK S-101

W/X-9 m.c. 32k33
T45U R28W

Cloudy, cool

Page 30
April 16, 1981

Ray
Homer

BOOK S-101

T-9 1/4 COR. T45N E28W

1/16 NW	1328.65	404.973	90-11-00
	1328.64		
Random nail	359-56-10		
1/16-1/4	1324.36	403.666	90-04-30
	1328.64	404.971	90-02-50

See page 26


THIS 1/4 COR. SET FROM
EXISTING 1/16 COR. AND
NW COR. SEC. 28

Time spent 2 1/2 HR.

BOOK S-101


T-9 1/4 COR. 29 1/2 28

T45N E28W



Page 29
April 16, 1981

Ray
Homer
Cloudy, Cool



BOOK S-101

Z- 23/24

Find pipe on shore
w/ no visible ties
Tied out as shown.

Stark may have set
this pipe while doing
work for Madson.

1 HR

BOOK S-101 3/4

Z- 23/24 m.c.?


Pipe on shore
round lake

Page 28

April 15, 1981

Ray

Header
Clear, warm,
windy



BOOK S-101

Z-23 : South 1/4 Sec. 36

T45N R28W

Find pipe in place
in swamp w/existing
tie trees - no
other trees near.

I BELIEVE THIS PIPE SET
DURING MORRIS SURVEY (OMA)

2 1/2 HR.

BOOK S-101

Z-23 1/4 COR

T45N R28W

5 1/4 COR SEC 36

45-28

Find pipe in place
in swamp w/existing
tie trees - no
other trees near.

I BELIEVE THIS PIPE SET
DURING MORRIS SURVEY (OMA)

2 1/2 HR.

Page 27


APRIL 15, 1981

36

RAY

Homer

Clear, warm
windy



BOOK S-101

T-9 1/4 COR. 29 x 28
T45N R28W

April 14,

Dug out steel fence
POST (HORIZONTAL) ON
WEST SHOULDER of
road. Found I.P.
37± west of &
many hot rocks

Being unable to find
This corner I will
set it from existing
1/16 and section corner
TO THE NORTH

SEE PAGE 29

1 1/2 HZ.

BOOK S-101

T-9 1/4 COR. 29 x 28
T45N R28W

Page 26
April 14, 1981
Ray

Homier
Clear, cool

BOOK S-101

V-16/17 m.c.
T4SN RZ8W

Find I.P. in place
and existing
tie trees.


1 Hour

BOOK S-101

V-16/17 m.c.
T4SN RZ8W

Page 25
April 14, 1981

Ray
Homer
Clear, cool



BOOK S-101

U/V-17 M.C. 2/26

North side Wilson Lk.

Looked for this

corner on March 24,

1981 AND LOCATED

HOT SPOTS!

Returned this DATE

AND DUG OUT ONLY

HOT ROCKS

NO HPS FOUND (open pasture)

NO CORNER FOUND

2 1/2 HE.

BOOK S-101

U/V-17

THSN 228W

M.C. NORTH SIDE

WILSON LAKE

Page 24

April 14, 1981

Ray

Homer

Clear cool

T-21 1/4 cor. 26 25

T45N 220W

Find pipe in place
w/ grown over tie
trees. Open ties
and made one new
tie as shown.

Book 107/14 (w.s.u.)

1 to

T-21 1/4 cor 26 25


T45N 220W

April 14, 1981

Clear

Clear, Cool

Clear, Cool



BOOK S-101

P/Q -17 m.c.

NORTH SIDE BAY LAKE

T45N R22BW

I find capped pipe
in place and make
ties as shown.

I HAVE USED THIS PIPE
AND FOUND IT 393.84'
SOUTH OF V₂ COR.
GOVT DIST 401.94'

no other ties found.

1 hr


BOOK S-101

P/Q -17 m.c.

T45N R22BW

Page 22
April 14, 1981

Ray
Homer
Clear - Cool



BOOK S-101

Q/R-17 M.C.

SOUTH BAY LAKE

T45N R22BW

I find the capped
pipe in place on
N-S fence line
and tie out as
shown:

Gov't dist is 891

1 1/2 HR.

BOOK S-101

Q/R-17

M.C. 22-23

T45N R22BW


Page 21

APRIL 14, 1981

Ramy

Home

Clear - cool



P-17	Sec. Corp.
------	------------

3222

27	26
----	----

T-451	22800
-------	-------

As I use this existing corner to tape north and find no visible ties I record the information shown.

 $\frac{1}{2} \text{ hr.}$

BOOK S-101

R-17 Sec. Cont.

12822 12822

2223

272

子

2" capped I.P.
12" High
TIPPED WEST 0.30 ±

15A.6

Gravel Road

8" Ash

10" Norway

Cap punch
marked

22	23
27	26

Page 20

Apr. 14, 1981

Ray

1000

clear-cool

BOOK S-101

M/N-25 M.C. 13 18 T45U R28W

I tape south from approx
1/4 cor. distance checks.
Found old ribbon from
Forestry (Aitkin)

In talking w/ Mr. Setherly
(owner to west) Forestry
had run line for wood
permit - had found
nothing.

Nothing found

Some old pine stumps in
area

3 hr.

BOOK S-101

M/N-25 M.C. 13 18
T45U R28W

M.C. North side
Birch Lake

Page # 19
April 9, 1981

Ray
Homer
Clear, warm

BOOK S-101

52-7-1348

1/4 col. T45 N

122822

I tape east from	
old fence corner	
1320'± along old	
fence to location	
for 1/4 corner.	
Found fence wire	
as shown - no	
ties found - "	
no corner found	

3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

BOOK S-101

U-25 13x18

1/A cor. T45N1228W


60
11

April 9, 1981

2025

Hermer

clear, warm



BOOK S-101

J-23 1/4 COR. 12
T45N R28W 13

I tape east from
C.S.A.H. #10, 1320't
along fence line
and find corner of
fence.

No corner or ties
found - Tied fence
corner as shown
as it is in bad shape.
no trees near.


I taped on east from
this point to sec.
COR. J-25 as I wished
to use J-25 to go
south - WMS unable to
find J-25 or any visible
ties! ALICE PETERSON -
MAY KNOW OF LOCATION -
NOT HOME today

2 1/2 hr.

BOOK S-101

J-23 12
13

1/4 COR.
T45N R28W



Page 17
April 9, 1981
Ray
Homer
clear, warm

BOOK S-101

V/W-17 M.C. 34/35
T45W R22E W

FIND 3/4" I.P. in place
on ICE RIDGE. w/
cap # 3091

THIS PIPE SET FOR
COLLINS SURVEY (DMA)


1/2 HR.

BOOK S-101

V/W-17 M.C. 34/35
T45W R22E W

Page 16
March 24, 1981

Ray
Homer
Clear, Warm



BOOK S-101

T/U - 21 M.C. 26/25

T45N R220W

(25.80 CH. N OF SEC. COR.)

FIND EXISTING 2" I.P.

8" high and 1 1/2" pipe

22.60 North as shown.

Evidence of old brush

line east from 1 1/2" pipe.

Tied out 2" I.P. as shown.

I BELIEVE THESE TO BE
I.P.'S USED FOR FLESNER
SURVEY TO EAST. (P.M.A.)

1 1/2 HR.

BOOK S-101

Page 18
March 24, 1981

T/U - 21 M.C. 24/25


T45N R220W

South side

channel

(Partridge to turtle)

[25.80 Ch. North sec. cor.]



NO. 447

NATIONAL

BOOK S-101

T/U-21 M.C. 26/25

NOTHING FOUND

THIS AREA NOW PLANTED
AS GREENWOOD ISLE
HAS NO VALUE

Birch & Aspen orig. ties

1 HR.

BOOK S-101

T/U-21 M.C. 26/25

NORTH SIDE OF

CHANNEL

(Part ridge to turtle)

[32.65 ch. North
of sec. cor.]

Page 14
March 24, 1981

Ray

Homer

Clear, warm

BOOK S-101

S/T 21 M.C. 26/25
(52.20 CH. N OF SEC. COR.)

I FIND EXISTING PIPE
AND EXISTING BIRCH
AND MAPLE TIE TREES
AS IN BOOK 107/9 W.S.N.
MADE NEW TIE AS
SHOWN. Pine stumps now
gone.
DID NOT OPEN OLD TIES
AS THIS IS DEVELOPED
LAKE SHORE. NEW TIE
TREE WAS NOT
BLAZED - DIST. IS TO
FACE
THIS AREA NOW PLANTED
AS GREENWOOD FASE

1 HR.

BOOK S-101

S/T - 21 26/25

M.C. ON SOUTH
SIDE PART RIDGE
LAKE - 100 FT
OF 1/4 COR.

(52.20 N OF SEC. COR.)

PART RIDGE LAKE

26

34 ft
1 1/2" pipe - 3" high

25

5860
5914
18" Birch
OLD DBL GLAZE
(DIST. TO TIE IN
TOP GLAZE)

532E
3.93

570E
27.23

ROCK WALL

24" Maple
old DBL GLAZE
(did not open)

15" Red Oak
new tie
(Face)

Page 13
March 24, 1981

Ray

Homer
clear, warm

BOOK S-101

X-21 EAST 1/4 COR.
SEC. 35-45-28

I measure south from
N.E. corner sec. 35
on old brush line.
Swamp calls all check

Find existing 1 3/4"
capped pipe w/ plastic
core stamped 309
and tie trees as
shown.

Original tie not found.

3 hrs.

BOOK S-101


45-28

X-21

1/4 COR. 35 36

Clear, Warm

Page 12
March 24, 1981



BOOK S-101

$$\begin{array}{r} 25 \\ 2 \overline{) 50} \\ \underline{50} \\ 0 \end{array}$$

M.C. ON EAST LINE OF
SEC. 26 T4S N R2W
ON NORTH SIDE
PART RIDGE LAKE
(67.50 CH. NORTH OF SEC.

FOUND I.P. IN PLACE
W/ EXISTING TIE
TREES.

TIES AGREE CLOSELY
W/TH THOSE IN BOOK
226/46 W.S.N.

Time

BOOK 3-101

$$\frac{R}{s} \frac{z}{2}$$


M.C. 26092

24

 	 
--	--

Page 11
March 17, 1981

25



23 | 24

R-21

SEC. COR

26

25

T4SN R28W

FOUND CROW WING COUNTY
CAST IRON MONUMENT
IN PLACE - NO
VISIBLE TIES.

MADE TIES AND
RECORDED INFORMATION
SHOWN AT RIGHT.

THIS CORNER SET BY
O.M.A. during survey
for Calkins

Original pine ties would
fall in road area. Did
not look.

Time 1/2 hr.

23 | 24

R-21

SEC. COR

26

25

T4SN R28W

-C.S.A.H. #10

C.S.A.H. #10
(F.L.C.S.H.)
MonumentS. 28° 00' E
98.78S 70° E
98.7850.47
37.0950.47
37.09

C.S.A.H. #10

Power Pole
(Face)

6" Red Oak

Power Pole
(Face)

Ray

Homer

Cool

BOOK S-101

R-23 North 1/4 cor
Sec. 25
T45N R28W

Found Iron pin AND
the trees in place.

As I used this corner
to tape east I
recorded the following
information.

THIS CORNER USED FOR
U-S 1/2 line survey in
Sec. 25 (D.M.A.)

TIME: 1/2 hr.

BOOK S-101

24

R-23

1/4 cor 25
T45N R28W

11" Red Oak



24

N 55 W
34.39

N 40 W
50.00
31.00

12" R.O.

NATIONAL

NO. 447



Iron pin - 6" deep
approx. 1/2 old
road.

edge woods

OLD FIELD

25

8" White Oak



N 11 E
25.00

Page 2
March 17, 1981

Ray
Homer
Cook

BOOK S-101

QR-25 m.c. South side
of Birch Lake 25 1/2 x 19

I tape NORTH ON
EXISTING FENCE LINE
TO SHORE OF BIRCH
LAKE, Fence in ground
most of way.

Corner falls on ice
ridge by lake.
Pieces of wire found
on ridge - some grown
into oak tree -
no evidence of orig.
ties

No corner found -
No corner set.

Time 1 1/2 hr.

BOOK S-101

QR-25 M.C.

24 x 19
45-28 45-27

Page 5

MARCH 17, 1981

Ray

Harmer

Cook

BOOK 9-101

R-25 T4S W R28W

SEC. COR.

3-13-81

I began at the S.E. corner of sec. 25 and taped north (rough) on compass brg. (6° decl) hit E-W fence at 5280, taped west to N¹/₄ cor. (E.Kis.) of sec. 25 2650'

3-17-81

Discussed info w/ county surveyor D.M.A. Decided to set this corner.

Fences are straight part on trees and part on ground (woven wire)

No evidence of orig.

Aspen ties:

Pipe set in base of rotted off corner post,

2 hrs ±

BOOK 9-101

R-25 SEC. COR.

45-28 24 19 15-27 30

5" Maple

24

2650 ± to N¹/₄

572W 23.81

6" Maple

25 T4S W R28W

7" Ash

19

7" Maple

1586E 15.80

T4S W R27W

30

SET 3/4" I.P. 2" High @ fence corner

Page 94
MARCH 17, 1981

Ray Homer Cook

19

30

31.55

31.17

5280 ± to sec. cor.

NATIONAL

NO. 447

BOOK S-101

V-25

SEC COR.

Southwest COR. SEC 25

T45N - R20W

FOUND I.P. and

DBL. BLAZED TIE

TREES IN PLACE

AS I STARTED ON

THIS CORNER TO RUN

NORTH ON TWP LINE

I RECORDED THE

INFORMATION SHOWN

Time - 1/2 hr. ±

BOOK S-101

V-25

SEC. COR.

Page # 6
March 13, 1981
Ray

Horner
Clear - Warm

28 25 30
45-27

30

7" Maple

25

NORTH

24.40

1 1/2" I.P.
12" high

BLAZED LINE

16.6
17.6

57.8E
20.60

9" Maple

5" Maple

31

45-27

36

45-28

BOOK 8-101

V-17/18 M.C.

T45N R28W

Found 2" I.P. in place

Found existing blazed trees

Ref. book W.S.N. 107/26

From info on WSN section

CARD THIS SEEMS TO

FIT GARRISON DIST. OF

2412.5' WEST OF 1/4 COR.

Garrison ties of 1912 AND

CUTO ties of 1921 not

found.

W.S.N. survey for calkins and

PLESNER USED THIS PIPE

Time 1 Hr. ±

BOOK 8-101

V-17-18

T45N R28W

M.C. East side Wilson Lake.

Page #5
March 13, 1981
Ray A.

Homer W.
clean, warm

15" White Oak

26

Wilson


Lake

2" I.P. 15" high

Tipped N30E 0.36'

25' white pine

18.00
100.55
118.55



BOOK S-101

V-21 Sec. Cor. 26/25
745N R28W 35/36

Found 2'4" I.P. Monument
12" high, Verified by
existing the trees.

Ties agree w/ information
on section card. W.S.N.

Book 107/9 WSN.


Time spent 1 hr

BOOK S-101

V-21 26/25
Sec. Cor. 35/36

745N - R28W

Match 15, 1987
Ray A.
Homer W.
elder, WSN



BOOK S-101

T-25 East 1/4 cor.

Sec. 25 T45N

R25W

Rough chain & compass

from southeast corner

section 25, swamp

calls fit good,

intersect fence (E&W)

on north line of section

25 at 290' west of

corner. Look for 1/4 cor.

145' east of our compass

line. No corner found.

Corner set from original

Burr Oak B.T. in 1929 by

L. Knudsen; no new ties

made.

Possible Oak B.T. found

but no visible evidence.

Did not set corner.

Time spent 4 hrs ±

101 3 1

March 13, 1981

Clear, warm Ray A.

Hammer W.

March 17, 1981

Ray A.

Hammer W.

BOOK S-101



30

25

140'

line

edge

swamp

Found 36" oak

tree which was

blown down. Blay

area rotted

away

CONTRACT
S-101

INDEX

NO. SURVEYOR
RAYMOND L. ANDERSON

PAGE

CORNER DESC.

52

H/T-13

53

L/M-9

54

X-1

Z-1

Z-3

Z-5

Z-7

R-6/7

R-6/7

E-14/15

E-14/15

H/T-17

H/T-17

COMPASS DEC'L 60 W

ALL TIES HORIZ. TO BOTTOM

FACE BLAZE UNLESS

OTHER WISE NOTED

● = COR. TO BE CROSS INDEXED

● = COR. CROSS INDEXED

BOOK S-101

INDEX

CONTRACT No.
S-101

SURVEYOR
RAYMOND L. ANDERSON

CORNER DESC.

PAGE


2	T-25	-45-28	27	Z-23	T45N R28 W
3	V-21	"	28	Z-23/24	"
4	V-19	"	29	T-9	"
5	V-17-18	"	30	W/X-9	"
6	V-25	"	31	R-11	"
7	R-25	"	32	R-8/9	"
8	Q-25	"	33	P/Q-9	"
9	R-23	"	34	O/P-9	"
10	R-21	"	35	X-17	"
11	R/S-21	"	36	Z-14/15	"
12	X-21	"	37	V-5	"
13	S/T-21	"	38	V-7	"
14	T/U-21	"	39	U/V-5	"
15	T/V-21	"	40	V/W-5	"
16	V/W-17	"	41	Z-11	"
17	J-23	"	42	Z-9	"
18	L-25	"	43	X/Y-9	"
19	M/N-25	"	44	R-3	"
20	R-17	"	45	S/T-1	"
21	Q/R-17	"	46	R-4/5	"
22	P/Q-17	"	47	P-1	"
23	T-21	"	48	N-1	"
24	U/V-17	"	49	N-3	"
25	V-16/17	"	50	M/N-9	"
26	T-9	"	51	N-7/8	"

BOOK S-101

BOOK S-101
BOOK S-101

CONTRACT NO.
5-101

RAYMOND L. ANDERSON
NO. 10798



NO. 447

TELEPHONE

BOOK S-101