

CROW WING COUNTY S110  
COUNTY SURVEYOR - 1981 TIES

No. S-110

★

No. S-110

A

INDEX

| PAGE | CHARTER | TWP, RANGE |
|------|---------|------------|
| 1    | C-17    | T136 R29   |
| 2    | C-21    | T136 R29   |
| 3    | C-25    | T136 R29   |
| 4    | C-5     | T136 R28   |
| 5    | C-13    | T136 R29   |
| 6    | V-13/14 | T136 R29   |
| 7    | V/W-13  | T136 R29   |
| 8    | R-19    | T136 R29   |
| 9    | N/O-21  | T136 R29   |
| 10   | N-21/22 | T136 R29   |
| 11   | E-23    | T136 R29   |
| 12   | X-13    | T136 R29   |
| 13   | A-13    | T136 R28   |
| 14   | A/B-13  | T136 R28   |
| 15   | P-23    | T136 R29   |
| 16   | B/C-17  | T136 R28   |
| 17   | B/C-13  | T136 R28   |
| 18   | M/N-21  | T136 R29   |
| 19   | N-20/21 | T136 R29   |
| 20   | P-21    | T136 R29   |
| 21   | C-25    | T136 R28   |
| 22   | Z-23    | T136 R29   |
| 23   | Z-22/23 | T136 R29   |
| 24   | Y/B-17  | T136 R29   |





No. S-110

B

INDEX

| PAGE | CORNER  | TWP, RANGE |
|------|---------|------------|
| 25   | X-17    | T136 R29   |
| 26   | W/X-17  | T136 R29   |
| 27   | X/Y-17  | T136 R29   |
| 28   | W/X-17  | T136 R29   |
| 29   | V-17/18 | T136 R29   |
| 30   | V-19/20 | T136 R29   |
| 31   | J-15/16 | T136 R28   |
| 32   | N-12/13 | T136 R28   |
| 33   | W-11    | T136 R28   |
| 34   | J-23/24 | T136 R28   |
| 35   | V/W-25  | T136 R29   |
| 36   | X/Y-25  | T136 R29   |
| 37   | X-5     | T136 R28   |
| 38   | V-4/5   | T136 R28   |
| 39   | V-4/5   | T136 R28   |
| 40   | Z-7     | T136 R28   |
| 41   | X-9     | T136 R28   |
| 42   | R-11/12 | T136 R28   |
| 43   | R-11/12 | T136 R28   |
| 44   | R-10/11 | T136 R28   |
| 45   | V-14/15 | T136 R28   |
| 46   | Z-19/20 | T136 R28   |
| 47   | Y/2-21  | T136 R28   |
| 48   | Z-21    | T136 R28   |

No. S-110

INDEX

| PAGE | CORNER  | TWP, RANGE |
|------|---------|------------|
| 49   | E-20/21 | T136 R28   |
| 50   | E-22/23 | T136 R28   |
| 51   | E-21/22 | T136 R28   |
| 52   | E-24/25 | T136 R28   |
| 53   | E-25    | T136 R28   |
| 54   | X-5     | T138 R28   |
| 55   | V-11    | T138 R28   |
| 56   | R-25    | T138 R28   |
| 57   | V-13    | T138 R28   |
| 58   | X-13    | T138 R28   |
| 59   | P-3     | T138 R28   |
| 60   | L-13    | T138 R29   |
| 61   | J-15    | T138 R29   |
| 62   | J-7     | T138 R29   |
| 63   | W/X-13  | T136 R28   |
| 64   |         |            |
| 65   |         |            |
| 66   |         |            |
| 67   |         |            |
| 68   |         |            |
| 69   |         |            |
| 70   |         |            |
| 71   |         |            |
| 72   |         |            |

No. S-110



0110

1/4 COR  
T 136-R29 COMMON 3-2

FOUND 1" SOLID IRON  
WITH SMASHED TOP  
4" BELOW GRADE

NEW WOOD STAKE  
WITH SURVEY RIBBON,  
TWO BLAZED TREES  
WHICH HAVE BEEN  
BRUSHED OUT THIS  
SUMMER.

BT TAGS IN  
6" TWIN BIRCH  
8" H. OAK  
POWER POLE / TRANSFORMER

1 hour

C-17 NO. S-110 6-30-81  
D. LANDECKER  
B. MOBERG  
T136 R29

CO. RD #16

OLD 371

8" R. OAK

N 51.58° W

27.10'

6" TWIN BIRCH

S 25° W

EAST

78.00'

8" J. PINE

DRIVE

FRANZEN  
HOUSE

24' EAST TO E. OLD 371

11' EAST TO SHOULDER




(26' WIDE BIT ROAD)

DOUBLE GLAZES

ALL MEASUREMENTS

TAKEN TO DISC APPROX

3' HIGH



1/4 COR.

COMMON 2-1

T136-R29

1 1/2 CORNER

FOUND 1'6" X 1'6" ROCK  
WITH 2" CROSS

CROSSED IN CENTER

ON JOB 6-30-81

TALKED TO MIKE SCHULTE

MAN, REC. SURVEYOR JENKINS,

IS USING ROCK, WAS SETTING

SEC. 2, T136-R29, CENTER OF SECTION

NEW SURVEY DOWN ROAD

MAYBE SAME AS C-17

NAIL PLACED AT CENTER

LINE AND INTERSECTION  
FENCE.

STRAIGHT WEST OF NAIL LIES

LARGE ROCK 1 1/2' X 1 1/2'

WITH 2" CROSS IN ROCK.

SLIGHTLY EXPOSED TO ROAD  
SURFACE

7.40' NAIL

TIES MADE TO ROCK

C-21 NO.

S-110

6-30-81

D. LANDECKER

B. MOBERG

12

T136 R29

WATERED FIELD

1" A. OAK

1" A. OAK

PASTURE

5" ROCK

NEW FENCE STRUNG BETWEEN TREES

PASTURE

12" ROCK

TIES MADE TO ROCK

24' WIDE ROAD BED GRAVEL

7.40' EAST OF ROCK

DOUBLE BLAZES IN TREE

DISC IN TIES 3' HIGH

C-25 No. 8-110 8-30-51  
D. LANDER  
B. MOSENG

T136 R29

13

1/4 COR.

Common 1 T136 R29

6 T136 R29

2 Low

TALK TO LONG TIME  
FRIEND APPOINT  
SWENSON. CLAIMS  
THERE WAS NEVER A  
CORNER AS HE COULD REMEMBER  
FENCE LINES WERE JUST  
THERE AND NOTHING TO GO  
BY.

HE THOUGHT TREE LINE WAS  
1/4 LINE BUT MEASURED  
ABOUT 500' SOUTH OF  
WERE COUNTER OF TRUCK  
SHOWED 1/2 MILE.

NO EVIDENCE OF EAST  
WEST LINES.

NORTH SOUTH IS  
TWP. ROAD  
APPEARS TO BE ANGLE  
PT AT 1/4 IF ROAD  
WAS USED AS LINE

OLD FARM (SWENSON) TO  
WEST OF LOCATION  
OLD GRAVEL PIT TO EAST

2 1/2 hours

T. 136 R. 28

1/4 corner C-5

TALKED WITH

OWNER OF LAND IN

NE 1/4 SECTION 6

TOM EISNERT

SAID HE HAD LOOKED

MANY TIMES FOR CORNER

BUT COULD FIND NONE

TOLD US ABOUT FENCE

INTERSECTIONS

FOUND REMAINS OF  
FENCE RUNNING EAST

WEST FROM C-3

TOWARD C-5

ALSO FOUND CORNER

AT THIS LOCATION

BUT NO MONUMENT

No. S-110

C-5  
T. 136-R. 28

K. MILLER  
B. BART

7-27

14

N

REMAINS OF FENCE

FENCE CORNER

FENCE IN TREES, STUMPS

AND ON GRASS

PARTLY LEFT

MANY

T136 R29  
1 1/2 acres  
1/4 COR  
COMMON 4-3

FOUND 2" CAPPED IRON  
PIPE 0.50' BELOW  
SURFACE GRAVEL ROAD


FITS & GRAVEL ROAD

MARTIN MELIN LONG TIME  
LOCAL RESIDENT IN  
ADJACING SEC 4  
CASS CO. SAID  
SECTION 4 WAS SURVEYED  
IN 1924 or 1925  
THAT ALL PROPERTY  
OWNERS WERE ASSEST FOR

COST FROM CASS CO.  
CASS CO. SURVEYOR  
(MONUMENTED WITH CONC. IN 1924)

FOUND HOUSE WAS ON  
SECTION LINE SO SOLID 3  
ACRES TO PROPERTY OWNERS

C-13  
T136 R29  
No. S-110  
6-30-81  
D. LANDICKER  
B. PROBERG  
15



DOUBLE BLAZES  
DISL IN TREES 3' HIGH  
(2' SOUTH OF EXTENSION OF THE  
NORTH SIDE HOUSE RANGE LINE  
AT 146.8 IS COR LOCATION



T 136-R29

1 1/2 hours

MC

COMMON 27-34

CLARENCE HERTIG

LAND OWNER

SHOWS V-13-14

V-W-13

ALSO SAID

SURVEYOR IN 1953 (DA)

WAS HERE.

3091

FOUND WITH CAP

2" IRON

2' ABOVE GROUND

4" x 3" OBLONG


STAMPED

|    |    |
|----|----|
| 19 | 12 |
| 27 | 34 |
| 4  | 31 |

V-13-14 No. S-110 D. LANDECKER  
 MC T136-R29 B. MOBERG 16

6:30-81

LAKE  
 MAYO



DOUBLE BLAZE  
 DISC IN TREE  
 APPROX 3' HIGH

NO. 447

W. TELME

T136 R29

1 down

MC

Common 33-34

FOUND 2" IRON PIPE 2' ABOVE  
WITH OBVIOUS CAP GRND

LYING DOWN SLIGHTLY  
BENT STRAIGHT UP AND  
PUSHED IN GRND FEW  
INCHES, TO FIRM UP  
POSITION

ONE EX THE TREE LEFT  
CLARENCE HEATIS  
REMEMBERS WHEN OLD  
BT TREE BLEW OVER  
IN WIND, OTHER BLAZE  
TREE CLOSED UP SO IT WAS  
CUT OPEN TO DETERMINE  
IT WAS A BLAZED TREE  
CHECKED DA. BEARING  
309' DIST OK

33 34

TO IRON  
SCRIBED

No. S-110

V-W-13


T136 R29

6-30-81

D. LANDECKER

B. MOBERG

17



2 from

T136 R29

Common 23-26

1/4 cor.

FOUND 1/2" IRON PIPE

MYRON

LANDecker SET 5 1/4

WHEN SUBDIVIDING

SW 1/4 SECTION 23 (1981)

USED N 1/4 AND EX. CENTER

AS LINE ALSO USED

SW COR AND POINT ON SOUTH SECTION

LINE TO SET INTERSECTION

AT 5 1/4 CORNER.

FITS WELLY SECTION

SUBDIVISION DONE BY

JOHN CURO 1921

ANGLES & DIST.

SEE T136

PIPE CAPED

N 8° E 42.25

PIPE WITH CAP

BROKE OFF

N 8° E 39.85

N 45° W  
SEC 23  
136 29  
45'

No. S-110

R-19

T136 R29

7-1-81  
D. LANDECKER  
B. MOSBERG

18

N

WOODS

PA 15

10" PIPE EX BLAZE

8.5' 10"

N 51° W

61.35'

23.35'

E 60 R29

567' 90

83.66'

525'

10"

5' 8" 10"

WOODS

DOUBLE BLAZES

DISC IN ALL TREES

APPROX 3' HIGH

7-1-81  
D. LANDECKER  
B. MOBERG

No. S-110

12-0-21

T136 K29

T136 R29

2 hours

MC Question

Completed 23-24

EX 2" IRON WITH CBearing

CA P. Scribed

|     |      |   |       |
|-----|------|---|-------|
| WIT | CAR. | 1 | H1917 |
|-----|------|---|-------|

ACCORDING TO SECTION

SUB. DAVE BY J. CURR

1921 HE SET WITNESS

COR. 40' SOUTH OF

21


Pile of cans & Galketig

10' NORTH ON LINE.

Top iron

|     |     |
|-----|-----|
| WIT | COR |
|-----|-----|

23 1 24



T136 R29  
3 hours

MC

COMMON 13-24

FOUND REMAINS OF  
OLD FENCE

± 50 NORTH OF WOOD  
LINE.

FENCE CONTINUES  
OUT IN LAKE.  
CORNER POSSIBLY WOULD  
BE IN WATER.  
ALTHOUGH IT SEEMS THE  
WATER MAY BE  
RECEDING.


No. S-110

N21-22

T136 R29

7-1-81  
D. LANDECKER  
B. MOBERG

110



2 Nov

7136 R29

FOUND 1/2" IRON PIPE  
FLUSH TO GROUND

POWER LINE WAS PUT  
IN AROUND 1973, THEY  
AT THAT TIME THEY  
CLEARED ALL STUMPS  
AND TREES, IT  
APPEARS AS THOUGH 1938  
BT TREES FROM HIGHWAY  
DEPT. WERE TAKEN OUT  
IN PP R/W

IN 1974 MYRON LANDECKER  
SUBDIVIDED SECTION  
AND RESET N1/4 CORNER  
WITH 1/2 IRON


011-8 ON  
1/4 COR  
COMMON 1-2

No. S-110  
E23

7136-29

3

D. LANDECKER  
B. MOBERG  
7-6-81



011-3 .0M  
1/4 COR

T 136 R 29  
2 home


OLD TIME RESIDENT  
CLARENCE HERTIG  
SECTION 34, REMEMBERS  
WHEN FENCE CO. WAS  
THERE HE REPLACED IT  
WITH A RAILROAD TIE.  
ALSO SHOWED US AN  
AERIAL PICTURE BY  
CROWNING CO. AG. IN 1960'S  
SHOWED A FIELD SOUTH  
OF CORNER AND WOODS

NOW RAILROAD TIE  
REMAINS. AND NW PAPER  
COMPANY HAS PLANTED  
PINES IN FIELD IN  
ANOTHER FEW YEARS  
F LINE WILL BE  
HARD TO DETERMINE

No. S-110  
X-13

T 136 R 29

EUGENE SOBIECK ALSO  
KANS TMC RESIDENT REMEMBERS  
WHEN WIFE DAD SAID  
RAILROAD TIE WAS  
APPROX CORNER, NOT SURE  
HOW CLOSE  
HAS LIES IN ANTONING  
CARS CO.



7-6-81  
D. L. HANDECKER  
B. MOBERG

011-2 BM

SEC COKE

~~7136 R28~~  
7137 R28

7136 R28

FOUND 1/4" IRON PIN  
FLUSH WITH &  
BLACKTOP ROAD

MYRON LANDECKER HAS  
USED CORNER IN SEVERAL  
SURVEYS FROM 1976-1981

1 hour


D. LANDECKER  
B. MOBERG

No. S-110

A-13

7136 R28

7-6-81 113



DOUBLE BLAZES  
ALL TIES HAVE DISC  
3' HIGH.



011-2  
MC  
Command 433

T-136 R28

Found 1 1/2" IRON PIPE

PROPERTY OWNERS ON WEST  
SIDE CLAIM THE IRON  
HAS BEEN THERE FOR  
FIFTY YEARS THATS HOW  
LONG THEY HAVE OWNED  
THE LAND.

1 Iron


No. S-110  
A/B-13

D. LANDECKER  
B. MOSER  
7-6-81

T-136 R28

114

REDDEN WOOD



PT ON LINE  
WITH RANGE LINE  
OF SHED

ALSO STRAIGHT SOUTH

± 53'

OSGAWINNAKEE LAKE

NO BLAZES IN TREES  
ALL TIES HAVE DISC APPROX  
3' HIGH

T136 R29  
2 hrs

1/4 cor.  
Canton 24-25

Nothing  
position,

FOUND AT THIS

AREA HAS BEEN LOGGED  
OF APPROX. 3 YEARS AGO.

ALSO COUNTY TAX AGENCY  
LAND HAS RECENTLY  
BEEN MARKED WITH  
BLUE KIDDEAN APPEARS  
TO BE CULMING PERMIT  
AREAS.

EAST-WEST SECTION HAS  
BEEN CLEARED BY  
BULLDOZER. MORBERGS  
RESIDENTS OF SECTION  
24 (ALL) REMEMBER  
WHEN GRAND FATHER  
FOLLOWED OVER FENCE  
AND CLEARED LINE  
10-15 YRS AGO.

No. 9-110  
R-23

T136 R29

7-6-81

115

AREA WHERE CORNER  
RIGHT LAND AREA'S  
TO HAVE BEEN PLACED  
IN TO CROSS SURROUND

NO. 447

WILSON



7136 R28

FOUND 2" IRON PIPES  
1' ABOVE GROUND  
IRON WAS SLANTING  
TOWARD EAST FROM  
SOFT GROUND. STRAIGHTENED  
AND DROVE IN MORE  
SECURE

OLD RIBBON STILL  
ON IRON

2 hours

011-3

Mc

COMMON 4-3

No. S-110  
B/C-13

7136 R28

D. LANDECKER  
B. MOBERG

7-7-81

POINT LINE GOES  
THRU POINT

"BA" MARKER

OSAWA LAKE

"BIRCH

12 28E

N 75° E

29.25

240 55° W

6" HIGH

240 55° W

5" ASH

SMALL

BLAZE MARK

4' HIGH

ALL CLOSED

UP.

DOUBLE BLAZES

ALL TIES HAVE DISL APPROX

3' HIGH

011-8

Mc

13-14

COMMON

+136 R29

2. *Suburban*

SIGHTING WITH THE FENCE  
ACROSS TO SOUTH OF  
CLOVERLEAF LAKE  
WE SEARCHED AREA.  
NO MARKING OF ANY  
KIND COULD BE FOUND.

TALKED TO MOBERGS  
PROPERTY OWNERS IN  
SEC 23 + 24. THEY  
HAVE NO IDEA ABOUT  
THESE CORNERS.

ALSO TALKED TO  
WILLIAM MINIM OWNER  
IN SEC 13 HE ALSO  
HAS NEVER SEEN ANY  
CORNER AROUND  
CLOVERLEAF LAKE

PLAND ECKER  
B. MOBERG

7-7-81

118

No. S-110

M/N - 21

+136 R29

11-8-81  
M/C

T136 R29 Common 14-23

USING OLD SURVEY

BY J.W. CURO I MEASURED

1322.15 + 273.69

TO THE OLD SHARELINE

OF CLOVER LEAF LAKE.

FROM N<sup>1</sup>/<sub>4</sub> SECTION 23

A BULLDOZED PATH AND

FENCE LINE WERE

ALONG NORTH LINE OF

SECTION 23. FENCE

CONTINUES ON INTO WATER.

AGAIN LIKE IN M/N-21

TAKEN TO:

BOB MOSEBERG

W. MINING

TO SAME INDICATIONS

APPEARS AS THOUGH BULLDOZ

TRAIL MIGHT HAVE TAKEN

CORNER OUT.

No. S-110  
N-20/21

T136 R29

D. CANDECKER  
B. MOSEBERG

2-7-81

SEE SECTION 23

SUBDIVISION BY

J.W. CURO 1981

T136 R29  
WITNESS TO VY CORN  
COMMON 23-24

FOUND 2" PIPE WITH  
OBSCURE CAP, ETCHING ON  
CAP. 0.40' ABOVE GROUND


2 hrs

SEE COPY OF SURVEY  
BY J. W. CULRO 1921

P-21 No. S-110  
B. ZART  
7-27-81  
120

T136 R29

ALL TIES HAVE DOUBLE BLAZES  
AND DISC APPROX 3' HIGH.



11-2 OM 15-9

1/4 cck

Common 1-6

1 down

T136 R28

IN 1974 MYRON LANDECKER  
DID A SECTION SUBDIVISION  
OF SEC 1 T136 R28

NO 1/4 MONUMENT WAS  
FOUND. POSITION WAS  
ESTABLISHED BY SINGLE PROA  
MEASURE.

AGAIN

NO MONUMENT WAS FOUND  
OR SET

No. S-110

C-25

T136 R28

D. LANDECKER  
M. LANDECKER

7-9-1981

121





D. LANDECKER  
B. MOBERG

No. S-110

2-22/23

7-9-81

123

T136 R29

FOUND 5x 1/2" IRON PIPE  
W/ CAP 3091, 2" HIGH

REDWOOD FENCE 4' HIGH  
BUILT DIRECTLY OVER  
IRON

ANOTHER 1/2" PIPE 3091  
ON LINE FROM MC - 1/4 COR.


END OF FENCE  
5' FARTHER WEST

45' ± TO WATERS EDGE


1 hour

NO BLAZES IN TREES

MEASURE TO  
SE COR.  
FOUNDATION




WITH DISC ONLY  
4" W. PIPE



4" SPRUCE  
WITH DISC ONLY

MEASURE  
TO NW  
COR. FOUNDATION



No. S-110

1/8 - 17

T136 R29

D. DANDECKER  
B. MOBERG

2-9-81

124

WEST TWIN  
LAKE


TALKED TO PROPERTY  
OWNER ON WEST SIDE  
OF PENINSULA  
SAID THAT LAND WAS  
PLATED AND THAT HE'S  
NEVER SEEN ANY POINT  
ON SECTION LINE.

HE SHOULD ME A COPY  
OF PLAT.  
APPEARS AS NO TIES  
WERE MADE TO SECTION  
LINE.

Reborn

SECTION 34  
SECTION 35

HWY 371



T136 R29

1/4 COR  
COMMON 55x34

FOUND EX 2" IRON PIPE  
6" HIGH

TWO EX BLAZE TREES  
WITH (BRASS)

BY BASE OF TREES

1 hour

DOUBLE BLAZES  
ALL NEW TIES  
HAVE DISC APPROX 3' HIGH


No. S-110

X-17

T136 R29

7-9-81 125

D. LANDECKER  
B. M. OBERG



No. S-110

W/K-17

D. LANDECKER  
B. MOBERG

7-9-81

126

T136 R29

011-8 ON

MC

Common


34-38

T136 R29

FOUND 2" IRON PIPE  
1" ABOVE GROUND

6' ± HIGH WATER  
9' ± WATER 7-9-81  
TOWARD NORTH

1 down



DOUBLE ISLANDS  
ALL TIES HAVE DISC  
APPROX. 3' HIGH

8" J. PINE

D. LANDECKER  
B. MOBERG

7-9-81

127

NO. S-110

X14-17

T136 R29

TYPE OF

IN SURE IRON  
IS THE SAME AS  
X-17 AND W/K-17.  
IT ALSO HAS BEEN  
IN WATER FOR A  
LONG TIME.

AND IRON ON ROCKS  
BY SHORE LINE, WHERE  
WE FOUND IT.

011-B ON

MC

T136 R29 COMMON 34-35

MEASURED 601'

FROM X-17 SOUTH

USING COMPASS

MEASURED TO FARTHEST

POSSIBLE SPOT ON

LAKE SHORE MEASURING

ABOUT 525' TO WATERS  
EDGE.

LOOKING AROUND

WE DISCOVERED

A 2" IRON, ABOUT

4' OUT IN WATER

LYING ON SIDE.

CANT IMAGE LAKE

SHORE CHANGING MUCH

UNLESS IRON WAS RIGHT

ON EDGE, AND IT SLIPPED

OUT AND ROLLED ON ROCKS

TO DEEPER WATER.



3  
9  
1  
0

7136 P29

Common 26-35

|           |         |                |
|-----------|---------|----------------|
| FOUND     | 3" PIPE | WITH           |
| OBSCURING | TOP     | WITH SCRUBBING |
| IN.       |         |                |

WAS PROBABLY SET BY  
J. C. RO 1940 WHEN  
PLAT OF POWNOWN POINT  
WAS ESTABLISHED

3 NEW BUZE TREES APPROX.  
2-3 YRS OLD WERE THERE

OLD FENCE RUNNING DOWN TO MC IS EXISTING THE LAST POST 2" ANGLE IRON WITH 45° SUPPORT IS ABOUT 0.50 FEET WEST AT BASE, THEN TOP LEANS OVER MC BY ABOUT 1.0' TO EAST

~~Force~~

500-1-1

No. S-110


8/17/18

7136-229

D. LANDBECKER  
B. MOBERG

$$18-51-2$$

29



DOORBEL BLADES  
WITH DISK AND TIES



1 1/2 hours

T136 R29

MC

COMMON 26-35

PART OF  
BEVERLY BENCH

FOUND 1"x1" SQUARE  
IRON PIPE I DO NOT  
BELIEVE THIS TO BE  
CORNER SA I DID NOT TIE  
OUT.

LOOKS AS THOUGH  
ACCESS ROAD MIGHT BE  
TOTALLY BUILT IN PLAT

SECTION LINE MIGHT BE IN  
CENTER OR ON NORTH SIDE.

WIDSETH, SMITH, NOTHING  
SAID THEY HAD INFO ON  
THIS CORNER

No. S-110

V-19/20

T136 R29

D. LANDECKEN  
B. MOBERS

7-15-81 30

30' SHEEP FENCE

EAST  
TWIN  
LAKE

ACCESS

6" X 6" SQUARE IRON  
LIGHT METAL

PART  
BEVERLY BENCH

NO. 447

W. T. BROWN

2 hours

T136 R28

Common 10/15

MC

IN 1959 DEAN ANDERSON #3091  
SURVEYED THE PLAT OF  
'FIRST ADDITION TO WEAVERS  
POINT'

A TIE WAS MADE TO WY CORNER  
AS THE ANGLE POINT TO  
SURVEY LINE WHICH FELL  
IN LOT 7 BY LAKE.  
WE FOUND A  
5" X 5" X 1.0 MONUMENT.  
WAS FOUND AND APPEARED  
TO HAVE BEEN MOVED.  
THINKING TO LOT OWNER OF  
S. 6, 7 HE SAID MONUMENT  
HAD BEEN MOVED.

USING PLAT IRONS WE  
RESECTED POSITION  
AND AT 1' DEPTH FOUND  
PART OF THE MONUMENT.

WE PLACED A 1/2" IRON PIPE  
1.0 BELOW GRND, DIRECTLY  
OVER IRON WE REPLACED  
CONC. MONUMENT.

No. 8-110

7-15-16 J-15

T136 R28

7-15-81

31

COR. 15 MARKED AS  
1/4 COR. SO LOGGED  
AS SUCH M.C. @ 40.60 -  
MONUMENT TOP

SCRIBBING ON

CALLS 1/4 10  
15 C

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NW  
WOOD CORNER OF  
SMALL BUILDING

NO. 447

WELBYNE

8" BURR  
8" OAK

28.43  
580 W

85.05 W

55.00 W

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

5.61 S

MEASURED TO NW  
WOOD CORNER OF  
SMALL BUILDING

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

MEASURED TO NE  
WOOD CORNER OF  
SMALL ADDITION

DOUBLE BURNED  
AND DIS IN TIES

D. C. ANDERSEN  
B. ROBERTS

7-15-81

32

NO. S-110

N-12/13

T-136 P-28

1 hour  
11:16 AM  
MCC

Common 16-21

CORNER FALLS IN  
PLAT OF 'FIRST ADDITION  
TO BREEZY POINT  
ESTATES'

DUE TO THE CONSTRUCTION  
OF BREEZY POINT CONDOS,  
MOST PLAT IRONS TOWARD  
LAKE SHORE AND EAST-WEST  
R/W OF SHOREVIEW LANE  
ARE PROBABLY GONE.

PLAT DOES CONTAIN A  
DISTANCE TIE TO MC  
WHICH IS PROBABLY HOW  
IT WOULD HAVE TO BE  
RESERVED.

1 shown

T136 R22

1/4 COR

COMMON 16-21

NOTHING WAS FOUND  
AT THIS POSITION.

IN 1948 D. ANDERSON  
FOUND CEMENT POST IN  
1948.

NO APPARENT MATH  
TIE WAS MADE IN PLAT OF  
'TWENTY SECOND ADDITION TO  
BREEZY POINT ESTATES'

USING SCALE TO FIGURE  
DISTANCE BETWEEN LOT 20-21  
WE MEASURED BACK AND  
FOUND NOTHING.

APPEARS AS THOUGH LOT  
OWNER 19-20 HAS DUG  
A LOT OF HOLES IN THIS  
AREA EITHER FOR WARMS  
OR DIRT FOR GARDEN.

No. 3-110

N-11

T136 R22

D. L. ANDERSON  
S. MOORE

7-15-81

33

1 down

T136 R28

MC

COMMON 12-13

FOUND EX. LARGE SPIKE  
FLUSH TO GROUND.

1/2" IRON PIPE 51.10' N50°W

OLD BT TREE

SURVEYED BY D. ANDERSON  
FOR 'BURPELL'

LOT LINE DISPUTE

M. LANDECKER DID SURVEY IN  
SECTION 12 7-9-79

FOUND SPIKE TO BE  
CLOSE FOR LINE USING  
OTHER POINTS EAST ON  
SOUTH LINE OF SECTION  
12.

THE 5/4 CORNER FOR  
SECTION 12 MIGHT ALSO  
BE ABLE TO BE SET FOR  
THIS IS APPROPRIATE WHERE  
THE WATER LINE IS NOW.

No. 3-110


J-23/24

T136 R28

D. LANDECKER  
B. MOBERG

2-15-81

34



DOUBLE BARRER AND DISA  
IN ALL TIES

42 down

OLIVER COR

MC

T136 R29

COMMON

31, 136, 29

31, 136, 29

APPROX

1-5-81

NOYARD LANDLOCKER DED

A SURVEY TO ESTABLISH

WEST LINE SEC 31, T136, R29

FOR A SURVEY ADJACENT

TO LINE.

FOUND EX IRON PIPE PART

OF GATE FOR NW COR SEC 31.

FOUND EX COUNTY MON. AT

SW COR SEC 31.

ALSO FINDING LARGE SPIKE

± 10' FROM SHORELINE

AND ± 80 EAST OF OLD

FENCE LINE (DID NOT USE)

ALSO FOUND 1/2" IRON

845.16 SOUTH OF NW SEC COR

(DID NOT USE)

CONTINUE

EXPLANATION FOLLOWING

PAGE X/4-25

No. S-110

V/W -25

T136 R29

NW

SEC. 40 R 31

4" IRON PIPE

4.5' HIGH

PART OF GATE

21.65

LARGE SPIKE

± 10' FROM SHORE

0857

T136 R29

SEC 31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

D. LANDLOCKER

B. MOBERG

7-23-81

135

SEC. 40 R 31

4" IRON PIPE

4.5' HIGH

PART OF GATE

21.65

1" IRON

845.16 SOUTH

OF SEC COR.

0857

T136 R29

SEC 31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

31

CULLEN LAKE

35.29

± 10' FROM SHORE

± 10' FROM SHORE

COUNTY MON.

SW SEC COR 31

(SEE PRECEDING PAGES)

MIC

T136 R29  
1/2 hour

Common 36-31

TO ESTABLISH OUR SURVEY  
WE USED NORTH AND  
SOUTH SECTION CORNERS  
FOR WEST LINE SECTION  
31, T136, R28

TODAY WE FIND 2" IRON  
LOCATED 1-5-81

WAS A BRACE POLE  
FOR A WOOD DUCK HOUSE.

MEASURED EAST 35' TO  
LOOK FOR MIC  
IN AREA.

OLD SURVEYS SHOW  
DISTANCE FROM SOUTH  
SECTION CORNER  
NORTH TO MIC AT 1471.8  
AND 1460.4

THIS SEEMS TO FALL  
IN LAKE

SEE DEAN ANDERSON SURVEY  
1958

No. S-110


X/Y-25

T136 R29

D. LANDECKER  
B. MOBERG

7-23-81

36



FOUND A 14" ELN WHICH  
WOULD BE ABOUT 5 80° E  
OF MIC WITH POSSIBLE GAZE  
AND TIN CAN NAILED IN BLAZE  
BEEN THERE A LONG TIME

D. LANDRECHT  
B. NEESKEG

No. S-110

X-5

7-23-81

37

7-136 R28

11-13

1/2 hour

1/4 con  
Common 3/1/32

FOUND NOTHING AT  
THIS POSITION,  
TALKED TO

HI ANDERSON ORD, NEARBY  
HAS BEEN HERE FOR  
55 YEARS. WIVES  
FATHER BOUGHT LAND  
AND SUBDIVIDED INTO  
PLAT OF 1

'CULLEN LAKE OUTING CLUB'

CLAIMS ROAD WASN'T  
BUILT TILL 1930'S

APPEARS TO BE A BAD  
CUT AND FILL SITUATION  
AT LOCATION SO POINT  
PROBABLY WOULD HAVE  
BEEN KNOCKED OUT.



D. LANDECKER  
B. MOBERG

No. S-110

V- 4/5

7-23-81

138

111-13 OM

EAST

M/G

COMMON 30-31

7136 R28

NOTHING FOUND AT  
THIS LOCATION.

PUBLIC ACCESS HAS  
BEEN BUILT ON  
SECTION LINE PROBEY  
WAS DESTROYED THEN.

A FENCE RUNNING EAST-  
WEST APPEARS TO  
BE 33' NORTH OF  
CORNER LOCATION.  
PROBEY R/W OF ROAD

PUBLIC  
ACCESS

CAMP  
RAMP

GULLENHILL

LAKE

FENCE

33'

E. TWP  
R2001

1 hour

T136 R28

WEST MC

COMMON 30-31

NOTHING

FOUND FOR CORNER

IRONS MARKING LINE

BETWEEN 30-31

TO V-3

CLOSEST IRON  $\pm 100$

WEST OF MC LOCATION

FOUND LARGE 30" ELM  
POSSIBLE TIE TREE  
ONLY TREE LARGE ENOUGH  
TO HAVE BEEN AROUND  
DURING DRG, PLS.

No. S-110


V-4/5

T136 R28

D. LANDRECHER  
B. MOWBILES

7-23-81

39



1/2 hour

T136 R28

1/4 cor

Corner 32-5

NOTHING FOUND AT THIS

LOCATION

NOTES ON OPPOSITE  
PAGE.

No. S-110

2-7

T136 R28

D. LANDECKEN  
B. MUEBERG

7-23-81

40

WOOD LINE  
CHANGE

PINE TREE LINE

PLANTATION  
IS 20' N

REMAINS  
OF OLD  
FENCE

E BLACK TOP  
ROAD

25'

OLD STUMP

WITH AXE CUTS IN FACING NORTH

DOESN'T FIT ANY TIES

USING FENCE AND ROAD

INTERSECTION STUMP IS

ABOUT 20° SW

x

No. S-110

X-9

2234

7156 228

---

子

7" x 12" x 12" x 12"

REMAINS  
OLD FILE

W  
A

[illegible]

2

天

K21.62

天

CLANDERER  
B. MOBERG

7-23-81

No. S-110

R-11/12

T-136 R28

0110 AM

WEST MC

COMMON 21-28

T136 R28

NO CORNER FOUND AT

THIS LOCATION.

APPEARS WHEN ROAD  
WAS BUILT THAT THEY  
PUT IN ABOUT 5'-6'  
OF FILL.

PLAT OF 'EDGEWATER  
BEACH'

WILL RESET MC

42

|          |        |       |
|----------|--------|-------|
| T136 R28 | Common | 21-28 |
|          | 457    | MC    |

|       |              |
|-------|--------------|
| FOUND | 1" IRON PIPE |
|-------|--------------|

0.30 BELOW GND

FITS PLATS  
TO NORTH AND  
SOUTH.

**No. S-110**


R-11/12

T/36 P38

D. LANDSCAPE  
B. MOBILES

7-23-81

43



shown

T-136 R28

MC

Common 21-28

SEARCHED USING USGS TAP  
TO FIND AREA

MANY LARGE OAKS AROUND  
FOUND OAK ABOUT 15"  
DEAD WITH PROBEGL  
BLAZE CUT OPEN WITH  
AXE. MARK WAS SMOOTH  
NO CUTS IN IT.

TREE WAS HOLLOW.

BLAZE FACED EAST  
MEASURED BUT

COULD NOT LOCATE ANY  
IRON.

MY FEELING IS THAT IF  
IRON WAS SET IN 1921  
BY CURO. THAT AREA  
HAS NOT BEEN DISTURBED  
SO IT SHOULD STILL  
BE THERE.

No. S-110

R-10/11

T-136 R28

D. CANDECKEN  
B. MORGAN

7-23-81

144

2 hours

MC

T136 R28

COMMON 27 x 34

7-1-71

H.D. GISH HAD  
SURVEY BY DEAN ANDERSON  
(BOOK 179 PAGE 28 GISH TRACT)

FOUND 2" IRON FLUSH TO  
GROUND IN CONCRETE.  
2" WELL POINT PUT IN IRON  
AS MARKER.

H.D. GISH SHOWED US  
SURVEY BY D. ANDERSON 1971  
T 320 EAST TO SHORE PELICAN  
LAKE

D. LANDECKER  
B. ROGERS

No. S-110

V-14/15


T136 R28

MEASUREMENTS TAKEN TO  
BUILDING CORNERS ON CORNER  
OF WOOD SIDING ALL  
ABOVE GROUND.

SEC 27

NO. 447

ON SECTION LINE



SEC 34

T 75  
BOOK 179  
PAGE 28



2 down

7136 R28

MC

Common 32-5

FOUND 1" x 1" BOLT (SQUARE)

1.5' LONG.

USED PLAT TO FIND

CORNER FIT MEASUREMENTS WELL.

CORNER IS IN PLAT OF  
SUNSET BEACH LOT 1  
MOST WESTERN BOUNDARY

No. S-110

2-19/20

7136 R28

D. LANDECKER  
S. MUEBERG

7-28-81

146

PECCAN LAKE

MEASURED  
TO CORNER  
CONC. BLOCK WALL  
+9' PLAT  
SUNSET  
BENCH

PLAT  
"MARKER"  
BEACH

N 55° E  
114.70

68.25  
575.00 W

N 70° E  
99.70

540°  
79.20

LOT

MEASURED TO  
BUILDING COR. NE

UD 3.0'

GRAY ASPHALT  
SIDING

MEASURED TO  
NW COR. CABIN  
2.0' HIGH ON  
SIDING

CABIN

LOT

2 down

T136 R28

MC

COMMON 35-36

FOUND 1" IRON

GROUND

2' ABOVE

USING PLAT OF SUNSET  
BEACH.

WE FOUND A VARIETY  
OF IRONS AND BEST  
WE COULD TELL THIS  
SEEMED TO FIT LOCATION  
OF MONUMENT

MEASURING SOUTH 239 ±  
WE FOUND 4"x4" WOOD  
POST MARKING SECTION COR  
SEEMS TO FIT PLAT.

No. S-110

Y/2-21(5)


T136 R28

K. MILLER  
B. ZART

7-27-81

47

DOUBLE BLAZES AND DISC IN ALL  
TIES



DOUBLE BLAZES AND DISC  
3' HIGH IN ALL TIES

No. S-110

2-20/21

T136 R28

K. MILLER  
B. ZART

7-27

149

MC

COMMON 35-2

T136 R28

found

NOTHING FOUND AT  
THIS LOCATION

USING PLAT OF  
SUNSET BEACH WHICH  
SHOWS NO CORNER  
AT THIS LOCATION.

SEARCHED FOR OLD TIES  
NONE WERE FOUND.

7136 R28

1 hour

TALKING TO ADJOINING  
OWNER IN PLAT OF  
'NORTH HAVEN' COULD  
NOT FIND IRON ON  
SECTION LINE. FOR MC  
LOCATION.  
COULD BE RELOCATED  
BY PLAT.

MC 1  
COMMON 36-1

No. S-110

E-22/23

7136 R28

K. MILLER  
B. PART

7-30-81

50.

T136 R28

Q chow

MC

Common 36-1

FOUND 1" PUNCHED IRON  
0.30 ABOVE GROUND

FOUND BY USING THE PLAT  
OF 'NORTH HAVEN' 1928

THE LAST DIST. ON  
PLAT DOESN'T CHECK TO  
IRON.

TIED IRON OUT

NO COULD BE RELOCATED  
BY PLAT.

No. S-110


2-21/22

T136 R28

K. MILLER  
B. BART

151

N



ALL TREES HAVE DOUBLE BARKS  
AND DISC 3' HIGH

NOT A HADEY  
11/10/1

T136 R28

1 house

FOUND 1" IRON

0.80 BELOW GROUND

TWO EXISTING BT STUMPS  
WITH BT TAGS  
DID NOT MEASURE TO  
STUMPS

MC

COMMON 36-1

No. S-110


Z-24/25

T136 R28

K. MILLER  
B. ZART

7-30-81

L52



T 136 R28

2 hours

SEC. COR

36 31

1 6

FOUND 1' x 4" CAST IRON  
MONUMENT  
1.5' ABOVE GROUND.

ALL TREES HAVE DOUBLE  
EXISTING BLAZES WITH  
BT TAGS.

WE PLACED A DISC IN  
SIDE FOR MEASUREMENT.

No. S-110


Z-25

T 136 R28

B. BART  
K. MILLER

653

N



(1)




T138 R28  
2 hours

14 car  
COMMON 31-32

NO MONUMENT FOUND AT THIS  
LOCATION.

FENCE INTERSECTION  
AND STRAIGHT TRAIL TO  
NORTH.

FENCE EAST OF & TRAIL  
APPROXIMATELY 15'



No. S-110

X-5

T138 R28

D. LANDER  
B. MOBERG

7-29-81

54

29

30

31

32

OLD  
FENCE

TRAIL

HWY #1

1/4 CORNER

T138 R28 COMMON 28-33

R. Jones

NO MONUMENT FOUND AT  
THIS LOCATION.

INTERSECTION OF  
HWY #1 RUNNING EAST-  
WEST AND TWP ROAD  
RUNNING NORTH-SOUTH.  
TWP ROAD SOUTH FROM  
CORNER LOCATION.

No. S-110

V-11

T138 R28

D. LANDECKER  
B. MOBERG

2-29-81

55

N

XXXXXX

CO RD #1

TWP ROAD GRAVEL

T138 R28  
2

SEC COR  
138 28 24/19 138 27  
25/30

FOUND 3" IRON PIPE WITH  
3" CAP ETCHED

24 19  
—  
25 30


ALSO 45° 45' IRON LYING ON SIDE  
4' AWAY TO WEST

IRON IS 0.80' ABOVE GROUND

No. S-110

R-25  
T138 R28

D. LANDICKER  
B. MOISER  
7-29-81  
56



DOUBLE BLADE  
AND 4.5' HIGH  
IN TIES

SEC 1 COR

T138 R29

38/27

33/34 1/2

2 hours

85' / 100' W

FOUND THREE 45°-42'

IRONS.

USED THE W45°W AND

S 45°W IRON AND RESET

CORNER WITH 1"x1" SQUARE

IRON PIPE WITH 1/2" PIPE

INSIDE, MEASURING 42'

FROM EACH.

N 45°E-42' WAS BENT

AND 42' — FIT FOR

ANGLE AND DISTANCE. AT BASE

TWO TREES BLAZED FACING

NORTH 25' APART DIDNT

SEEM TO HAVE ANY SIGNIFICANCE.

NO OTHER MONUMENT AT  
THIS LOCATION.

POSITION FITS E OF TRAIL  
AND IS 62' EAST OF CREEK

No. 8-110


✓-13

T138 R29

D. L. ANDERSON  
B. MOBERG

2-30-81

157



T138 R28

2 brown

NO MONUMENT  
FOUND AT THIS  
LOCATION.

N-S ROAD 20' WIDE GRAVEL

TALKED TO SEVERAL  
LAND OWNERS. NO  
KNOWLEDGE OF ANY RECENT  
SURVEYS OR ANY MIGHT  
INDICATE THEY WOULD  
HAVE NEEDED  
THIS POSITION

1/4 COR.

COMMON 33-34

No. S-110

T138 R28

X-13

D. LANDECKER

D. LANDECKER  
B. Moberg

7-29-81

158

T138 R29

2 horses

$\frac{1}{4}$  cor  
common 21-22

FOUND 1" PIPE  
WITH  $1\frac{1}{2}$ " IRON CAP  
FLUSH WITH GROUND  
IN E OF TRAIL,

57' ± NORTH OF FENCE  
CORNER AND EDGE OF  
FIELD TO EAST.

MRS.

OWNER HP. HULKE  
POINTED OUT LOCATION  
OF IRON.

No. S-110

R-13


T-138 R29

D. LANDECKER  
B. MOSER

7-30-81

59

↑



TRAIL 3  
12' WIDE

DOUBLE BLAZE  
AND DISC IN TIES

NO. 1001

NO. 445

TRAIL 3

14 cor

T138 R29

2 hours

Commenced 16-45

NO MONUMENT FOUND  
AT THIS LOCATION

TALKED TO FLOYD GLOVER  
LONG TIME RESIDENT

SAID NO IRON OR  
MONUMENT HAS  
BEEN THERE FOR  
LAST 60 YEARS

SAYS EAST-WEST  
FENCE HAS BEEN  
THERE ALSO FOR  
60 YEARS

BOTH FENCES LINE  
UP TO SAME SPOT  
IN ROAD.

No. S-110

L-13

T138 R29

D. L. ANDERSON  
B. M. BERS


7-30-81

60

NO. 445

W. T. B. M. E. N. E.

Co. Rd. 41



T138 R29 1/4 COR  
Common 10-15'

FOUND 2" IRON PIPE  
FLUSH WITH E GRAVEL  
ROAD.

LOOKS LIKE IRON  
WITH OBLONG CAP BUT  
CAP WAS BROKE OFF.

ALSO FOUND  $N 45^{\circ} W - 42'$   
IRON LYING ON SIDE  
IN ROAD DITCH 20'  
AWAY. (TOOK AWAY)


ONE EX TIE TREE  
 $N 75^{\circ} E 62.52'$  10" R. OAK  
THREE BLAZES

No. S-110

J-15  
T138 R29

D. LANDECKER  
S. MUEBERS

7-30-81  
[61]





SEC. COR

T138 R29

1 brown

FOUND 2" IRON FLYSH WITH  
E GRAVEL ROAD  
APPEARS ALSO THAT OBLONG  
CAP HAS BEEN BROKE OFF

ALSO FOUND TWO GOOD  
TIE IRONS

SCRIBED

S 45° W 42'

S 45° E 42'

ALSO EX TIE TREE

14" R. OAK N 15° W 64.60'

No. S-110

J-17

T138 R29

D. LANDECKER  
B. MOBERG

7-30-81

162

FIELD

12" 5" PIN  
EX 11" F.  
14"

N 15° W 42.05  
S 45° W 42.05  
S 45° E 42.05

E CO. RD #38

S 45° W 42.05  
S 45° E 42.05  
S 45° W 42.05

S 45° W 42.05  
S 45° E 42.05  
S 45° W 42.05

S 45° W 42.05  
S 45° E 42.05  
S 45° W 42.05

S 45° W 42.05  
S 45° E 42.05  
S 45° W 42.05

S 45° W 42.05  
S 45° E 42.05  
S 45° W 42.05

TRAIL

DOUBLE BUNDLES  
AND DISC IN TIES

D. LANDECKER  
B. MORSE

7-28-81

63

No. S-110

W/X-13

T136 R28

MC

COMMON SB-34

T136 R28

1 1/2 hours

WE DID NOT FIND  
AREA OF LOCATION FOR  
THIS POINT.

MUST BE A PLAT  
IN SECTION ON PECAN  
LAKE.

WIDSETH SMITH, NOTHING  
SAID THEY DID HAVE  
INFO ON CORNER.