

CROW WING COUNTY S112
COUNTY SURVEYOR - 1981 TIES




INDEX

Contract No.
5-112

Surveyor
Widseth, Smith, Nolting

Page	corner	Page	corner
1	N $\frac{1}{4}$, 32-44-30	25	S $\frac{1}{4}$, 33-44-30
2	NE, 32-44-30	26	S $\frac{1}{4}$, 32-44-30
3	E $\frac{1}{4}$, 29-44-30	27	
4	N $\frac{1}{4}$, 33-44-30	28	E $\frac{1}{4}$, 2-44-31
5	E $\frac{1}{4}$, 32-44-30	29	SE, 2-44-31
6	SE, 32-44-30	30	E $\frac{1}{4}$, 1-44-31
7	W $\frac{1}{4}$, 31-44-30	31	N $\frac{1}{4}$, 1-44-31
8	S $\frac{1}{4}$, 31-44-30	32	SE, 1-44-31
9	SE, 31-44-30	33	Void
10	E $\frac{1}{4}$, 31-44-30	34	SE, 3-44-31
11	E $\frac{1}{4}$, 33-44-30	35	N $\frac{1}{4}$, 10-44-31
12	SE, 33-44-30	36	M.C. 34-44-31
13	SE, 34-44-30	37	E $\frac{1}{4}$, 9-44-31
14	SE, 35-44-30	38	N $\frac{1}{4}$, 20-44-31
15	E $\frac{1}{4}$, 35-44-30	39	E $\frac{1}{4}$, 18-44-31
16	S $\frac{1}{4}$, 36-44-30	40	SE, 7-44-31
17	SE, 36-44-30	41	E $\frac{1}{4}$, 31-44-31
18	N $\frac{1}{4}$, 36-44-30	42	SE, 31-44-31
19	NE, 36-44-30	43	E $\frac{1}{4}$, 30-44-31
20	E $\frac{1}{4}$, 25-44-30	44	SE, 30-44-31
21	S $\frac{1}{4}$, 35-44-30	45	N $\frac{1}{4}$, 32-44-31
22	E $\frac{1}{4}$, 36-44-30	46	NE, 32-44-31
23	E $\frac{1}{4}$, 34-44-30	47	NE, 29-44-31
24	S $\frac{1}{4}$, 34-44-30	48	



90.5.40.055

Page Corner

49	N ¹ / ₄ , 17-44-31
50	E ¹ / ₄ , 8-44-31
51	M.C., 9 ¹ / ₂ -44-31
52	N ¹ / ₄ , 19-44-31
53	W ¹ / ₄ , 19-44-31
54	W ¹ / ₄ , 30-44-31
55	NW, 31-44-31
56	W ¹ / ₄ , 31-44-31
57	SW, 31-44-31
58	SE, 35-44-32
59	S ¹ / ₄ , 35-44-32
60	S ¹ / ₄ , 34-44-32
61	M.C., 34-44-32
62	M.C., 23 ¹ / ₂ -44-32
63	N ¹ / ₄ , 35-44-32
64	E ¹ / ₄ , 35-44-32
65	M.C., 26 ¹ / ₂ -44-32
66	E ¹ / ₄ , 20-44-31
67	E ¹ / ₄ , 34-44-32
68	M.C., 34 ¹ / ₂ -44-32
69	SE, 34-44-32
70	E ¹ / ₄ , 26-44-32
71	SE, 32-44-31

NO. 447

WELDON

June 24/81

M. Foertsch
P. Skogen

T. 44 W. R. 30 W.

NO. 147

W. 147

V-7, 1/4 Sec. Cal.
T. 44 N., R. 30 W.

29
32

No evidence of original corner and
B.T.'s find. No evidence of subsequent
surveys find.

Assumed 1/4 Cal. location as E-W
gravel surface Twp. Rd. & fence line
flapth. No monu. find. in place.
There exists a 6' gap between
the fence lines.

Numerous Magnetic Rocks.

No excavation was made.

Time Spent = Approx. 1 Hour

V-7, 1/4 Sec. Cal.
T. 44 N., R. 30 W.

29
32

Farm Bldgs.

House

Yard

4' drive

20' E

Edge Rd.

Gravel Rd.

592' W

Edge Rd.

N 92° E

Assumed 1/4 Cal. location

1/2 Overhead Power

Cultivated

Field

Pasture

502' E

Black = Ficks

Field line

June 24 '81
M. Fertsch
P. Skogen

69° Sunny, Windy

Subventure Fence

Cultivated Field

1-9, Sec. Cor.

29 28

T. 44 N., R. 30 W.

32 33

No evidence of original or subsequent corner restoration found

No evidence of existing monu. found.
Assumed $\frac{1}{2}$ U.S. Co. Hwy No. 9 $\frac{1}{2}$
at E-W Twp Rd. as Sec. Cor.

Numerous Magnetic rocks were dug up.

No further excavation was made

Time Spent = Approx 1 Hour

1-9, Sec. Cor.

29 28

T. 44 N., R. 30 W.

32 33

70° Sunny - Windy

Cultivated Field

Cultivated Field

Assumed Sec. Cor.

9' S 35° W
9' Twp Rd.

N 20° E

Assumed Sec. Cor.

Cultivated Field

Cultivated Field

Field Entrance

T-9, 1/4 Sec. Col.
T.44 N., R.30 W.

29-28

No evidence of original Gov't Canal or subsequent corner re-surveyation find.

1/4 Sec. Col. is evidenced by a 1 1/4" I.P., 7" below grade, 6' East of N-S & Co. Hwy. No. 9, Standing & functional fence line West and remnant fence line East.

No further excavation was made.


- On surface of Hwy. above 1 1/4" I.P., existed a mazz nail which was used as the NW Cor. of property in SW 1/4 Sec. 28 - Stated to me by resident of farm place to the SE of 1/4 Sec. Col.

Time spent = Approx. 1 Hour

T-9, 1/4 Sec. Col.
T.44 N., R.30 W.

June 24 '81 3
29-28 M. Fartsch
P. Skogren

75° PM 11 C.M.



28
33

V-11, 1/4 Sec. Cor.
T. 44 N. R. 30 W.

No evidence of original Gov't corner
or subsequent corner restoration found.

Found no existing monumentation. Assumed
1/4 Sec. Cor location as at E-W
Twp. Rd. and N-S fence lines.

Numerous Magnetic Pests were dug up.

No excavation was made.

Note: Found 1 1/4" x 8" I.P. lying in
North ditch. Corner probably was
graded out.

Time Spent - Approx. 1 Hour

June 24 '81 4
M. Fortsch
P. Skogen
730 PM 4:14 PM

V-11, 1/4 Sec. Cor.
T. 44 N. R. 30 W.

Garage

House

Yard

Woods

Woods where fence

Woods

Assumed 1/4 Sec. Cor.
N 86° E of Garfield Rd.

Barb wire fence

Woods

NO. 447

W. B. L. 1/2

X-9, 14 Sec. Cor.
T 24 N. R. 30 W.

32-33

No evidence of original Gov't Co. docs	
subsequent co. restoration	End.

Find no existing monumentation. Assume
"H Sec Col. location as of H-S-C Co.
Hwy. No. 9 & Fence line West of Edge of
woods. This same fence line & Edge of
woods also shows up on U.S.G.S.
quad map.

Numerous magnetic rocks. Dug out
in vicinity of assumed "4 Sec. Col."
location.

No road excavation was made.					
------------------------------	--	--	--	--	--


Time Spent = Approx. 2 weeks

June 25 '81
32 + 33 M. Boerl'sh.

P. Skaperd

T. 27 H., R. 30 W.

10° Pithy. Elderly, Windy



Z-9, Sec. Col.
T. 44 N., R. 30 W.

32 33
5 4

No evidence of original Gov't Col. or subsequent Cal. restoration find.

In 1922, records show Culo setting a 34"x10" iron and also setting iron monument as reference ties. The rd. in the area of the Sec. Col. appears to have been upgraded considerably. This probably explains the reason for all of Culo's work being obliterated.

Assumed Sec. Col. location as being of N-S Co. Hwy. No. 9, fence lines E + W.

Numerous magnetic rocks were dug up in vicinity of assumed Sec. Col.

No road excavation was made.


Time spent = Approx. 1 1/2 hrs

Z-9, Sec. Col.
T. 44 N., R. 30 W.

32 33
5 4

June 25 '81
M. Foertsch
P. Skogen

70° Partly cloudy. Windy



No Rd. excavation was done

Time Spent = Approx. 1/4 hr.

5005

Cultivated	Field
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

Z-3, 1/4 Sec. Col.
T. 44 N., R. 30 W.

31
6

No evidence of original Court Cor. Rd.

No existing Monumentation found.

Assumed 1/4 Sec. Col. is evidenced

by fence lines N 1/2 S & E-W

dirt Rd. not maintained, grown

over with grass. The existing Rd.

is not built in center of R/W

fences. Sec line possibly runs

E-W on North side of E-W Rd.?

Numerous magnetic rocks dug up.

No excavation was made.

Time Spent - Approx. 1 1/2 hrs

Z-3, 1/4 Sec. Col.
T. 44 N., R. 30 W.

31
6

Appears to be permanent

fence line, evidenced by

looks piled in a straight

line

N 1/2 S line and small ditch

like grain into the ditch

50 ft

64

20 ft

58 ft

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

N 85° E

22 ft

Assumed 1/4 Sec. Col.

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

65 Sunny, Calm

Z-S, Sec. Col:
T. 44 N., R. 30 W

Z-5, Sec. Col.	31	32
T. 44N. R. 30W	6	5
No evidence of original Gov't. Col. Fol.		

No existing monumentation	End.
---------------------------	------

Assumed 'Sec. Can. Fence lines E-W # 2 of H-S gravel Rd. All evidence of ties on Sec. Can. has been destroyed.

Numerous magnetic rocks dug up.


No Pdc excavation was made.

Time spent = Approx. 1 1/2 Hrs.

Z-S, Sec. Col:
T. 44 N., R. 30 W

31	32	M. Foeritzsch
6	5	P. Skogen

June 26 '81 9



X-13, 1/4 Sec. Cor.
T. 44 N. R. 30 W.

33-34

No evidence of original Cor. find.

No existing monumentation evident.

Assumed 1/4 Sec. Cor. as 1/4 N-S ditto
Top Rd. = fence line E + W, fence line
to East being respondent with buried
wire and a field line also evident.

Numerous magnetic picks were dug up.

No Rd. excavation was made.

Note: fence lines E + W are 2640' ±
North of existing monument @ SE Cor. Sec. 33

Time Spent: Approx. 1 Hr.

X-13, 1/4 Sec. Cor.
T. 44 N. R. 30 W.

33-34

75° Sunny, Windy

House

Yard

Cultivated
Field

Assumed 1/4 Sec. Cor.

N 87° E

Remnant fence line
Buried wire
Field line

Edge of Low Area

Overhead Power Line
Edges of Rd.
110' ± W.
4' ditto Top Rd.
Edge of Rd.

NO. 447

W. TELEPHONE

S 87° W

Pasture

502' ±

120' ±

Z-13, Sec. Cor.
T. 44 N., R. 30 W.

33 34
4 3

No evidence of Orig. Govt survey find.

Sec. Cor. is evidenced by a 3/4" I. Pipe
5" below grade in 4 N-S gravel Top Pt.
No fence lines and no field lines exist
E or W. The type of Monu. find @
this location is the same type
Cuto rolled Col in 1921. All Cuto's
ties had been destroyed.

Numerous magnetic rocks dug up.

No further R.R. excavation was made.

Note: Exist. monu. @ Sec. Cor. is
2640'± South of E-W fence line @
1/4 Sec. Cor. location.


Note: Distances meas. to Bottom
Blazes in trees.

Time Spent: Approx 1 Hr.

Z-13, Sec. Cor.
T. 44 N., R. 30 W.

33 34
4 3

June 24-31
M. Farnsworth
P. Skogen



Z-17 Sec. Cor.
T. 44 N., R. 30 W.

34 35
3 2

No evidence of Orig. Gov't Survey find.
Sec. Cor. is evidenced by a Oval top monument, 4" below grade, 6' South of E-W of dist. Twp. Rd., Fence line N.E.S. find. both standing by monument. S. monument has recently run a line West from the monument.

No further Rd. excavation was made.

Note: Dist. Meas. to Bottom Blazes in trees

Time Spent: Approx. 1 Hr.

34 35
3 2

76° Sunny, Calm

Wald, Run down fence, Partially still standing

Woods


Woods

Woods

Woods

Remnant fence, Buried -

Z-17, Sec. Cor.
T. 44 N., R. 30 W.



Z-21, Sec. Col.
T. 44 N., R. 30 W.

35 36
2 1

No evidence of Orig. Gov't Survey End.

Sec. Col. is evidenced by a 1 1/2" I. Pipe mon. 8" below grade, & N-S gravel surface Twp. Rd. & gravel surface Twp. Rd. East, & fence line west.

No further Rd. excavation was made.


Note: Ties in trees were made to bottom place in tree. One of the tie trees was existing.

Time Spent: Approx. 1 Hr.

Z-21, Sec. Col.
T. 44 N., R. 30 W.

35 36
2 1

M.C.
P. Skogen



X 21, 1/4 Sec. Cor.
T. 44 N. R. 30 W.

No evidence of Org. Gov't. Survey Prod.

Assumed 1/2 Sec. Cor. location as of
glacial surface Temp. Rds. W. S.
Pence line North. End. 6" to 8" thick
Causing Approx. 10' buried 12"
below surface 14000 Nuts SE across
"T" in old section 3' Rds. Also, there
has recently been dark brown, red
in. laths, etc. and other stuff.

1-10. 2d. circulation was made.

Time Spent: Approx 1 hr.

X-21, 14 Se... 1st.
T. 44 N. R. 30 W.

[illegible]

650 P. 11, cl. 1.

constant temperature
isobaric process

work

Assumed 44.5% Col.

4 Drive	↑	↓
Edwards	↓	↑

Delivered

Z-23, 1/4 Sec. Cal.
T. 44 N., R. 30 W.

36

No evidence of Dig. Court Survey find.

1/4 Sec. Cal. is evidenced by a 6" dia. Rd. Conc. Monu., 4" below grade. 7' South of E-W & gravel surface. Top Rd. Fence lines N.E.S. In 1922, Curo called for a 3 1/4" x 10" iron, which he set as a temp. Cal. His ties have also been destroyed.

No further Rd. excavation was made.

Numerous mag. rocks in this area.

Time Spent: Approx. 1.20

Z-23, 1/4 Sec. Cal.
T. 44 N., R. 30 W.

36

June 29 '81 16
M. Cartsch
P. Skogen

650 Prt. H. Cldy

Burb Wire Fence
Good Condition

Woods

Woods
8" Basswood

12" Red Oak

42.25' W
42.25' N

1185° E

1/4 Sec. Cal.

6" dia. Conc. Monu. 4" below grade

220°

Farm Yard

Wooden Wire Fence

(Woods)

18" Red Oak

Woods

All the trees have top & bottom
blazes with dist. meas. to bottom
place

Z-25, Sec. Col.
T. 44 N., R. 30 W.

36 31
1 6

No original Gov't Survey evidence
End.

Sec. Col. is evidenced by a $3/8" \times 8"$
Spk. 3" below grade, 2' North of E-W
& Twp. Rd., Remnant Fence line North
plot. 2's of Co. Hwy. No. 23 E & S.
In 1918, Cuba set a $3/8" \times 36"$ Iron
tubing from Orig. B.T.'s. His name & ties
have been destroyed. It appears that
when the plat was built in this
area all evidence was destroyed. It
also appears that probably the Sec.
Col. was used as the P.T. of the
Culver.

No further excavation was made.

Numerous neg. rocks in this area.

Time Spent: Approx. 2 hrs.

Z-25, Sec. Col.
T. 44 N., R. 30 W.

36 31
1 6

700 Sunny, Windy

Remnant Fence line
with growth into tree.
5" to 6" into Oak, Nothing
standing.

12" Bur Oak
12" Bur Oak

Overhead Power line

Sec. Col., Find Spk.

3" below grade 2' North
of E-W & Twp. Rd.

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

504' E

June 29 '81 17

M. Boertsch
P. Skogen

U-23, 1/4 Sec. Cor.
T. 44 N., R. 30 W.

25
36

No original Gov't Survey evidence
Fnd.

Assumed 1/4 Sec. Cor. location as
at E-W Co. Hwy. No. 104 &
Fence lines N & S.

According to Julius Palak, 1/2 Palak
resident at SW-SE Sec 25, he
had no knowledge of there ever
being a manure @ the 1/4 Sec. Cor.
location.

Humorous mag. rocks dug up


No Rd. excavation was made

Time spent: Approx 1 hr.

U-23, 1/4 Sec. Cor.
T. 44 N., R. 30 W.

25
36

June 29 '81
M. Foertsch
P. Skogen



V-25, Sec. Cor.
T. 44 N., R. 30 W.

25	30	June 21st 19
36	31	M. Bertsch
		P. Skogen

MOLO I $\times$ $\swarrow$ Partially standing
Fence, Poor Condition
16" $\swarrow$ Open field
Burr Oak $\swarrow$
Woods

Hand-drawn sketch of a geological outcrop showing two rock units. The upper unit is labeled "Burr Oak" and has a dip of 25° W. The lower unit is labeled "Burr Oak" and has a dip of 72° W. The contact between them is marked with "x" symbols.

SSE W
100' Co Hwy. No. 104
(Gravel Surface)
SSB
90°
72° S
Nail
Pipe
x

SSE E
End R-R Spk. 3"
below grade
Edge of Rd.
Nail
Pipe
x

Overhead Power

Barb Wire Fence	Good Condition
-----------------	----------------

Pasture

2-19

1/4 Sec. Cor.

T. 44 N., R. 30 W.

35

2

No Orig. Court Survey Evidence Fnd.
of Subsequent Cor. evidence Fnd.

Assumed 1/4 Sec. Cor. location is
evidenced by "T" Int. of fence lines
N. 1/2 E. fence lines are in poor
condition, partially standing, barb
wire fence.

Owner of SE 1/4 Sec. 35-44-30, Peter
Thesing, had no knowledge of
monu. ever being in place.

Time Spent: Approx. 1 Hr.

2-19

1/4 Sec. Cor.

T. 44 N., R. 30 W.

35

2

75° Sunny Windy

Pasture

110° W

Edge of Woods

Open water

Assumed 1/4
Sec. Cor. location

508° E


Woods

7-2-81 and

June 29, 81

M. Facetsch

P. Skogen



X-25
1/4 Sec. Cont.
T. 44 N., R. 30 W.

36-31

Ho. Orig. Cont Survey Evidence Fnd.

Assumed 1/4 Sec. Cont. - Rough
Chained South 2640' ± along
Fence line from Monu. Fnd. @
NE Cor. Sec. 36-44-30 location.
Searched an area 200' ± in dia.
of assumed 1/4 Sec. Cont. location
and find no evidence of an E-W
line. Woods are very thick!

Time Spent: Approx. 2 Hr.

X-25
1/4 Sec. Cont.
T. 44 N., R. 30 W.

36-31

7-2-81 22
36-31 M. Faetsch

P. Skogen

200 Survey

24 Hdt. Abn. 104

NE Cor. Sec. 36

Standing Fence
Crown into Trees
8' x 6' 10"

Remnant Fence line
None standing, all
wire pulled except
for pieces Crown into
Oak & Elm 8' x 6' 10"

Woods

Assumed 1/4 Sec. Cont.
location

Woods

5090 E

NO. 447

ENCLOSURE

2-15
1/4 Sec. Cor.
T. 44N. R. 30W.

34
3

Meas. 870' ± west from Hwy.
Very boggy - couldn't get to
Approp. witness post location.


Allen Cahoon - 20 yr. resident of
SE-50- Sec. 34-44-30 stated that
the Twp. hired surveyor from
Berkus - Hackensack to stake the
align on Twp. Rd. to East. Did
this work middle part of June 1981.
He stated the surveyor has before
the 2. Sec. corrs. Probably used
a straight line for Rd align.
purposes.

Time Spent: Approx. 2 hrs.

2-15
1/4 Sec. Cor.
T. 44N. R. 30W.

34
3

30° Sunny



7-2-81 24
M. Bertsch
P. Skogen

2-11

1/4 Sec. Col.

T. 44 N., R. 30 W.

33

4

No Orig. Gov't Survey Evidence Fnd.

1/4 Sec. Col. location was inaccessible due to low flica.

William Caughy, owner of SW 1/4 Sec. 33-44-30, had no knowledge of a fence or even a Fe. Car. at

1/4 Sec. Col. location. He had been living to the N. S. ditch & remnant fence for his East Bdry. -

2-11

1/4 Sec. Col.

T. 44 N., R. 30 W.

33

4

Hay Field

2 damage ditch

Hay Field

MOBON

50706

woods

woods

1/4 Cor. location

Time Spent: Approx. 1 Hr.

2-7

14 Sec. Cont.

T. 44 N. R. 30 W.

32

5

Possible Gov't B.T. Evidence.

Gov't notes call for 6" Oak,

N 84° W 89.10'.

In NW Quad of assumed 1/4

Sec. Oak location exists 3, 24" to

30" Oak stumps. It appears

that the harvested woods in this

area was large Oak trees.

Numerous stumps exist.

No more was found.

No stumps exist in SE Quad.

Time Spent: Approx. 1 Hr.

2-7

14 Sec. Cont.

T. 44 N. R. 30 W.

32

5

300 Sunny

7-281

M. Foertsch 26

P Skager

- Harvest Woods -

28" to 30" Oak stump.

24" Oak stump.

102° W

105' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

NO. 447

507° W

Assumed 1/4 Sec. Cont.

102° W

105' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

103' W

Pasture

Pasture

7-6-81

28

27

M. Gertsch

P. Skopen

T. 44 K. R. 31 W.

NO. 447

WELSH

C-21
1/4 Sec. Cor.

$$\frac{1}{2}$$
[illegible]

'14 Sect. Cor. is evidenced by a 1/2" solid
Iron, 0.15' below grade, & gravel Typ.
Red. North, 4.5' East of E. Co. Hwy. No. 123.

No Rd. excavation was done.

Note: Tie flies have top and bottom
blazes with dist. meas. to bottom
blaze.

Time Spent =	Applo.	1 Hr.
--------------	--------	-------

C-21
1/4 Sec. Cor.
T-44 H., R 31 W.


C-21

$$\frac{1}{2}$$

7-6-81

2.8

7-6-81
M. Foertsch
P. Skogen



Sec. Cal.
T. 46 N., R. 31 W.

2 1
11 12

Sec. Cal.
T. 46 N., R. 31 W.

2 1 M. Fortsch 29
11 12 R. Skogen

1-6-31

No. Orig. Gov't Survey Evidence Fnd.


Sec. Cal. is evidenced by 1 1/4" I. Pipe,
10" below grade, 16' East of 4 N-S
Co. Hwy. No. 123, 4 gravel Rd. West.

WSN Shows 3 of the existing ties
in these records. The tie made to
the SW Co. House is a new tie.

No further Rd. excavation was made.

Note: There exists a P.K. nail with
a faded painted "X" in 4 N-S Co. Hwy.
No. 123, 16' West of Sec. Cal. "X"
probably was used as a photo pt.
@ one time.

Time Spent = Approx. 1 Hr.



G-21

1/4 Sec. Cor.

T. 44 N., R. 31 W.

11-12

No Orig. Gov't Survey Evidence or
Subsequent Corner Restoration Found.

1/4 Sec. Cor. is evidenced by a
New Wing Co. Cast Iron Monum. 4"
below grade at N-S Co. Hwy. No.
123, fence line west.

No Rd. excavation was made.

The trees have top & bottom blazes.
Dist. are meas. to bottom blazes.

Gov't. dist. South to a stream was
429'. Meas. dist. is 340'. I think
that in clearing Co. Hwy. No. 123, the
course of the stream had been altered.

Time Spent: Approx. 1 hr.

G-21

1/4 Sec. Cor.

T. 44 N., R. 31 W.

7-6-81

30

11-12 M. Fortbach

P. Skogen

830 Sunny, Windy

Pasture

Barb Wire

Fence (W.S.I.)

5" Top Pile

Pasture

Woven Wire

Fence

5830 W

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

N 101° 30' E

6" Highway

E-13

Sec. Col.

T. 44 N., R. 31 W.

4 3
9 10

No Orig. Court Survey Evidence And.

Sec. Col. is evidenced by a "2" I. Pipe
in 6" x 6" Conc. 13" below grade, 4 N-S
gravel Rd., 4 Trail West, 13' North of
4 Trail East. 2 WSN Ties (2/76)
still exist. Ties to bottom blaze in
Tree.

No Rd. excavation was made.

Time Spent = Approx. 1 Hr.

E-13


Sec. Col.

T. 44 N., R. 31 W.

4 3
9 10

7-6-81
M. Foertsch 32
P. Skogen

890 Sunny, Windy



114511
Cor.

114511 Col.

T. 44 H., R. 31 W.

No Original Gov't Survey Evidence Fnd.

1/4 Sec. Col. is enclosed by a low
lying Co. Cast Iron Monu. 6" below
grade, 2' South of E-W 4th Trail.
Exist. B.T. Taps (U.S.N.) standing =
in good condition.

No excavation was made.

Time Spent: Appox. 1 hr.

61-7

1/4 Sec. Cor.

T. 4411, P. 31W.

83°	Sunny	Windy
-----	-------	-------

11/4 Sec. Col.	is exchanged by a Cow
----------------	-----------------------

Young Co. Cast Iron Manu. Co. below

glade, 2' South of E-W of Trail.

Ex 1st.	B.T. Tags (W.S.H.)	standing =
---------	--------------------	------------

in good condition.

No excavation was made.

Time Spent: Appox. 1 hr.

61-7

1/4 Sec. Cor.

T. 4411, P. 31W.

83°	Sunny	Windy
-----	-------	-------

11/4 Sec. Col.	is exchanged by a Cow
----------------	-----------------------

Young Co. Cast Iron Manu. Co. below

glade, 2' South of E-W of Hall.

Ex 1st.	B.T. Tags (W.S.H.)	standing =
---------	--------------------	------------

in good condition.

No excavation was made.

Time Spent: Appox. 1 hr.

E-17
Sec. Col.

T-44 N. R. 31 W.

3	2
10	11

No Orig. Gov't. Survey Evidence Fnd.

Sec. Col. is evidenced by a 1" I. Pipe in Conc.

1936 - Co. Highway Dept. records show Impl. same type of mon. It appears that different P Poles have been set since then. Exist P Poles in this area don't fit their calls.

2176 - WSN records show pipe in Conc. Impl. Bot & ties exist.

1920 - Cuno ties appear to be destroyed

Time Spent: Approx. 1 1/2 hrs.

E-17
Sec. Col.

T-44 N. R. 31 W.

3	2
10	11

7-6-81 34
M. Foertsch
R. Skogen

90° Sunny, Breeze

Woods
Blush Line

Woods
Jack Pine S

12" Jack Pine
D. 12" Jack Pine
W. 12" Jack Pine
S. 12" Jack Pine

5840 W. 0'
921' 1/2 Gov't
890' 1/2 Meas -

1" I. Pipe in Conc.

5410 S
2448 S

(WSN)
Exist.
OT Tag
8" I. Pipe

Woods

(WSN)
Exist.
7" Red Oak
Stamp.

H 320
79.107 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

H 170
11.770 W

E 15

1/2 Sec. 10.

T. 44 N. R. 31 W.

3

10

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. evidenced by a 1" Pipe in conc. Flus with Windy. Telegram fence line South (Fence shown 4" to 6" into Jack Pine.)

1911 - Knudsen called for setting wire

1911 - B.T.'s - 1911 ties have been destroyed or rotted beyond recognition.

WSN Records show 2 Jack Pine + P.P. for

Ties - Fnd. 2 pine stumps with B.T. Ties.

P.P. has been replaced.

1/2 Sec. 10. It very well.

Time Spent: Approx. 1 1/2 hrs.

E 15

1/2 Sec. 10.

T. 44 N. R. 31 W.

7-7-81

M. Foertsch

P. Skogen

150 Sunn. Flus

woods

1/2 Sec. 10. Evidence Fnd.

43"

Deadhead Pencil

21" 21" 21"

NO. 447

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

1/2 Sec. 10. Evidence Fnd.

Gov't M.C. 2 C/D-13
West Line Gov't Lot 4, Sec. 13
T. 44N., R. 31W.

4-3

Location of M.C. 2 Falls in
river. W.C. to M.C. set by
Roger A. Mustonen #11946.
Plat of Pine Bluffs colls for
W.C. as being in place @ time of
plat (WSN)

Gov't M.C. 2 C/D-13 7-7-81 36
West Line Gov't Lot 4, Sec. 3 M. Faertsch
T. 44N., R. 31W. P. Skogen

4-3 750 Sunny, Windy

M.C. location falls

99' in River

Mississippi River

22' 1/2" #11309

33.0'

West Line of
Plat of Pine Bluffs
- Lot 1 -

Pine Bluffs -

West Line of
Plat of Pine Bluffs
- Lot 1 -

33.0'

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Remnant Fence -
Brushed Wire -

51' 1/2" 10.65

1 1/4" I.P. Pipe

West
W.C. 69 1/4" I. Pipe set
(at Mustonen #11946)

Time Spent: Approx. 1 Hr.

1771

U.S. Orig. Gov't Survey Exhibit No.


1/4 Sec. 36. is evidenced by an 8" 8"
Sq Conc. Mon. with 14" iron rod, Alaska
with approx. 13 East of 4 but on Lone
with proj. 4 rd. from the North -
Mustonen shows more. Impl. on his
survey of W. Lone - NW 1/4 - Sec 10 & W. Lone
Sec. 3 - 44-31.

Time Spent:	1 1/2 Hrs.
-------------	------------

— 4411, R. 2111.

P. Skogen

34° Sunny - Windy



NO. 447

ENVELOPE

N-7

14 Sec. Cor.

T. 44 N. R. 31 W.

17

20

No Out. Cor. + Survey Evidence And.

14 Sec Cor. is evidenced by a Cast Iron Co. Cast Iron, 15" below grade in E-W gravel Rd.

1918 - WSAH estab. S. 14 Cor. Sec. 17 @

Midpt. in E & W. Only evidence being fence line South only

running South 30'. No evidence North. Aerial photos show nothing.

Set Cast Iron Menu @ host in E.

No Rd. elevation was made.

Time Spent: Approx. 1 1/2 hrs.

N-7

14 Sec. Cor.

T. 44 N. R. 31 W.


7-7-81

38

M. Gertsch

F. Spengen

84° Sunny - Windy



T-5

Sec. Col.

T. 44 N., R. 31 W.

7

18

No. Orig. Coast Survey Evidence Found

Sec. Col. is evidenced by a Claw Wing

C. Coast Iron Manu. Flusk with wind.

Remnant Fence line West @ top edge of West ditch bank.

Also End. 2 existing B.T.'s but

WSN records don't show these?

Time Spent: Approx. 1 1/2 hrs.

T-5

Sec. Col.

T. 44 N., R. 31 W.

7


18

20° Sunny - Wind

Woods

Overhead Power

0'



Woods

X-5
1/4 Sec. Cor.
T. 44 N. R. 31 W.

14 Sec. Cor.

T. 4411, R. 31 W

No	Orig.	Gov't.	Survey	Evidence	End.
116	Orig.	Gov't.	Survey	Evidence	End.

1895-Whately	Ind.	1/4	Post	Toplace
--------------	------	-----	------	---------

1922- Cuto set 5 Mond. Cal. -

Find NW oval top monu. leaned up against a tree. Find. NE SE oval top monu's flush with gnd. in good condition.	Find SW oval top monu. bent badly.
---	------------------------------------

Strengthened the SW manv. Reset the
Hut Manv. @ N 45° W 45.00' Reset the
Y 4 Sec Cap. from the NE + SE @ 45.00 ft.
Set a 12" x 18" I. Pipe 6" below grade.

End. segment fence line west consists trap
buried wire only. 55' North of the
1/4 Sec. Cor. location.

No Pl. excavation was made.

Time Spent: April 2 4:15

5-X

1/4 Sec. Cor.

7. 44. R. 31 W

No Orig. Gov't. Survey Evidence Ind.

1895-Whitely Fnd. $\frac{1}{4}$ Post Exp.

1922- Curo set 5 Mon. Cal. -

End. H & J Oval top menu. I earned up
against a tree. End. H & E. SE oval top
menu's flush with gnd. in good condition.
End. S & J oval top menu. bent badly.

Straplightened the SW Manu., reset the HW Manu. @ N 45° W 45.00' reset the 1/4 Sec. Cap. from the NE + SE @ 45.00 ft. Set all 1/2" x 18" F. Pipe 6" below grade.

Find fragment fence line west corner's tower of
buried wire only, 55' North of the
1/4 Sec. Cor. location.

No Rd. excavation was made.

Time Spent: April 2 4:15.

7-10-81

31+32 M. Foerlsch

P. Skogen

70° Sunny - 22/1m

Woods

Exist. Oval top
Marine.
Stamped
H 15 E

1 1/2" x 18" T. Pipe
6" below grade -

1st Oval top
Menn
Stamped
545E
45

Woods

Exist. Oval top
Monk - Stamped
545 W
45
Badly Bent 18"

Badly Bent 13"
out of Grnd. Dist.
Meas. to Monu. @
Grnd. level.

woods

Z-5

Sec. Cor.

T. 44 N., R. 31 W

31 32

6 5

No. Orig. Court Survey Evidence Fnd.

1922- Cwd set 5 monu. Cor. -

- Sec. Cor. is evidenced by Cwd's

4 Oval top ref. monu's. In place

No. existing monu @ Sec. Cor.

location. Set $1\frac{1}{2}$ " x 18" I. Pipe 6" below

grade, using Cwd's NW, NE & SE ref.

monu's. The ref. monu. in the SW

quad. appeared to be out of position

in relation to the other 3 monu's. The

monu in the SW quad. was bent over

and 24" above quad.

Numerous mag. rocks

No Rd. excavation was made

Time Spent: Approx. 2 Hrs.

Z-5

Sec. Cor.

T. 44 N., R. 31 W

31 32

6 5


7-10-81 42

M. Foerster

P. Skogen

76° Sunny - Slight Wind

Edge of Low Area



Edge of Low Area

T-5

1/4 Sec. Col.

T. 44 N. R. 31 W.

30-29

No Orig. Gov't Survey Evidence And.

1/4 Sec. Col. is evidenced by a 1/2" I. Pipe set by WSN 5-81 from Exist Owl top menus. In 1922 Cuo set a 5 menu. Col. A 1/2" I. pipe was set from 3 of his 4 set. menus and replace 1/4 Sec. Col. 2 1/2" in the 2 H-S gravel Rd.

No Rd. elevation was made

Time Spent: Approx. 1/2 hr.

T-5

1/4 Sec. Col.


T. 44 N. R. 31 W.

43

29-30 M. Fartsch

P. Skogen

83° Sunny - Windy



30	29
31	32

End.

Monne.	Cornel.
--------	---------

T. Pipe

in	of - 4
----	--------

from 2 exist

Max's	
-------	--

05 Mglo

Time Spent: Approx 1/2 Hr.

vi-2


3161

W.D.

子

tsch
zei

4



V-7

1/4 Sec. Cor.
T. 44 N. R. 31 W.

29
32

No. Orig. Cor. Survey Evidence Find.

1/4 Sec. Cor. is evidenced by a
1/2" I. Pipe with # 13336 set by
W.S.N. 5-81. 1/4 Sec. Cor. was
set on straight line & split
dist. between the SW & SE Cols.
Sec. 29-44-31. 1/4 Sec. Cor. falls
4' North of E-W Twp. Rd.

No Rd. excavation was made.


Time Spent: Approx 1/2 Hr.

45 July 10, 1981
M. Foertsch
P. Skogen

V-7, 1/4 Sec Corner

T 44 N R 31 W

84° Sunny - Windy



7" Aspen with
Top and 2nd 1/4
Blaze marked
to existing 1/4
Tag in the
Bottom Blaze

Rebar pole
with existing
BT Tag
Found 1/2" Iron pipe with
KLS # 13336 0.1' Below
Grade Pipe is 4.0'
North of E. Road

1/4 Sec
Township Gravel Road

S 84° W

V-9

Sec. Cor.

T. 44 N. R. 31 W.

29 28

32 33

No Dig. Gov't Survey Evidence find.

Sec. Cor. is evidenced by a Spk. in

4 N-S Gravel Rd. 12" below grade.

WSN records show a round top

monu. find. Impl. and a spk. Set

3" above round top monu. The

exist. Spk. fits ties made to

the round top monu. A oval top

monu. lying in the ditch in NE

quad. is an indication of a 5 monu

cor. existing at one time. (Cuto 1922)

End round top Monu. 20" below grade.

Set 1" x 16" I. Pipe 4" below grade

above round top monu.

No Rd. excavation was made.

Time Spent: Approx. 1 1/2 hrs.

V-9

Sec. Cor.

T. 44 N. R. 31 W.

29 28

32 33

34° Sunny - Windy

No Dig. Gov't Survey Evidence find.

Sec. Cor. is evidenced by a Spk. in

4 N-S Gravel Rd. 12" below grade.

WSN records show a round top

monu. find. Impl. and a spk. Set

3" above round top monu. The

exist. Spk. fits ties made to

the round top monu. A oval top

monu. lying in the ditch in NE

quad. is an indication of a 5 monu

cor. existing at one time. (Cuto 1922)

End round top Monu. 20" below grade.

Set 1" x 16" I. Pipe 4" below grade

above round top monu.

No Rd. excavation was made.

Time Spent: Approx. 1 1/2 hrs.

NO. 447

W. E. D. W. E. D.

46

7-10-81

M. Bertsch

P. Skoger

29 28

32 33

34° Sunny - Windy

No Dig. Gov't Survey Evidence find.

Sec. Cor. is evidenced by a Spk. in

4 N-S Gravel Rd. 12" below grade.

WSN records show a round top

monu. find. Impl. and a spk. Set

3" above round top monu. The

exist. Spk. fits ties made to

the round top monu. A oval top

monu. lying in the ditch in NE

quad. is an indication of a 5 monu

cor. existing at one time. (Cuto 1922)


End round top Monu. 20" below grade.

Set 1" x 16" I. Pipe 4" below grade

above round top monu.

No Rd. excavation was made.

Time Spent: Approx. 1 1/2 hrs.



Power pole with existing 5" lag.

Field

8' 18'

NO. 447

Found 3" Round Top Monu. 20" below grade

5' 10" N

5' 10" S

5' 10" E

5' 10" W

5' 10" N

5' 10" S

5' 10" E

5' 10" W

5' 10" N

5' 10" S

5' 10" E

5' 10" W

5' 10" N

5' 10" S

5' 10" E

5' 10" W

5' 10" N

5' 10" S

5' 10" E

NE corner House

House

8" Oak Pole with existing Top Blue and 2nd Set lag in Bottom brace.

Under 2nd Set lag

Q

Sec. Cor.

T. 44. R. 31 W.

20	21
----	----

20	21
----	----

$$\begin{array}{r} 88 \\ 26 \\ \hline 29 \end{array}$$
$$\begin{array}{r} 88 \\ 26 \\ \hline 62 \end{array}$$

No Orig.	Gov't Survey	Evidence Fnd.
----------	--------------	---------------

✓ 1920 - Calo set $3\frac{1}{4} \times 10$ " Iron flange.

-Ties for made in 1920 are destroyed

- Apparently, at a later date CWO

Set a 5 mmol Col. @ the Sw. Col.

[illegible]

mon's agree with each other with

the Sud. pt. may be being out-
-led

Position.	End.	Spk. in	Q. H-S
1	0	1	1

Travel Yr.	Replaced Spk.	with
1911	1911	1911
1912	1912	1912
1913	1913	1913
1914	1914	1914
1915	1915	1915
1916	1916	1916
1917	1917	1917
1918	1918	1918
1919	1919	1919
1920	1920	1920
1921	1921	1921
1922	1922	1922
1923	1923	1923
1924	1924	1924
1925	1925	1925
1926	1926	1926
1927	1927	1927
1928	1928	1928
1929	1929	1929
1930	1930	1930
1931	1931	1931
1932	1932	1932
1933	1933	1933
1934	1934	1934
1935	1935	1935
1936	1936	1936
1937	1937	1937
1938	1938	1938
1939	1939	1939
1940	1940	1940
1941	1941	1941
1942	1942	1942
1943	1943	1943
1944	1944	1944
1945	1945	1945
1946	1946	1946
1947	1947	1947
1948	1948	1948
1949	1949	1949
1950	1950	1950
1951	1951	1951
1952	1952	1952
1953	1953	1953
1954	1954	1954
1955	1955	1955
1956	1956	1956
1957	1957	1957
1958	1958	1958
1959	1959	1959
1960	1960	1960
1961	1961	1961
1962	1962	1962
1963	1963	1963
1964	1964	1964
1965	1965	1965
1966	1966	1966
1967	1967	1967
1968	1968	1968
1969	1969	1969
1970	1970	1970
1971	1971	1971
1972	1972	1972
1973	1973	1973
1974	1974	1974
1975	1975	1975
1976	1976	1976
1977	1977	1977
1978	1978	1978
1979	1979	1979
1980	1980	1980
1981	1981	1981
1982	1982	1982
1983	1983	1983
1984	1984	1984
1985	1985	1985
1986	1986	1986
1987	1987	1987
1988	1988	1988
1989	1989	1989
1990	1990	1990
1991	1991	1991
1992	1992	1992
1993	1993	1993
1994	1994	1994
1995	1995	1995
1996	1996	1996
1997	1997	1997
1998	1998	1998
1999	1999	1999
2000	2000	2000
2001	2001	2001
2002	2002	2002
2003	2003	2003
2004	2004	2004
2005	2005	2005
2006	2006	2006
2007	2007	2007
2008	2008	2008
2009	2009	2009
2010	2010	2010
2011	2011	2011
2012	2012	2012
2013	2013	2013
2014	2014	2014
2015	2015	2015
2016	2016	2016
2017	2017	2017
2018	2018	2018
2019	2019	2019
2020		

x 24" T. Pipe, 3" below grade.

110 Rd. ex captation	was made.
----------------------	-----------

Time Spent: Applet 1 40s.

R-9

See Vol.

1441, 1431

20

20

28

28


24

24

M. Festsch

28 | 29 | P. Skoog

84° Small, light blue



E-11/12

Alameda Post bet. Sec. 4 & 9
T. 44 N. R. 31 W.

Search for m.c. not
completed!

W.H.

E-11/12

Alameda Post det. Sec. 4 & 9
T. 44 N. R. 31 W.

7-13-81


M. Fortsch,

P. Skogan

48

70 Suba - Light Wilm

C



and
K
K

W.H. Skogan
Alameda

T. - 7

1/4 Sec. Col.

T. 44 N., R. 31 W.

8

17

No Orig. Gov't Survey Evidence found

1/4 Sec. Col. is evidenced by a
Chas. Kling Co. Cast Iron 6" below grade,
5' South of E-W & Gravel Rd.

Set by DMA 6-76 @ a split dist.
between Sec. Cols.

No Rd. excavation was made.

Time Spent: Approx. 1 Hr.

T. - 7

1/4 Sec. Col.

T. 44 N., R. 31 W.

8

17

7-13-81

M. Foertsch

P. Skogen

730 Summit, Light Breeze

Woods

Bottom blaze
6" thick Pine

Bottom blaze
6" thick Pine

Edge of Rd

Edge of Rd

58° W

186° E

Gravel Rd

Chas. Kling Co. Cast Iron
Edge of Rd

30° E

5' S

Single wire
Elect Fence

Open
Field

58° S

5' S

5' S

Woods

The Trees have top & bottom blazes

G-9

1/4 Sec. Col.
T. 44 N. R. 31 W.

8-9

No Orig. Coast Survey Evidence Fd.

1/4 Sec. Col. is evidenced by a New
Wing Co. Cast Iron, Flush with
grnd. Monu. set by D.M.A. 6-76.
No visible fence lines.

Time Spent: Approx. 1 1/2 hrs.

G-9

1/4 Sec. Col.
T. 44 N. R. 31 W.

8-9

7-13-81 50

M. Foertsch
P. Skoger

80° Sunny - Light Wind

Woods

Exist
B.T. 109
8" Jack Pine

East Lig.
Set. 8-44-31

49°

West
11.00'

Exist
8" Jack Pine

New Wing Co. Cast Iron
Flush

5 51° S
14 85° E

Exist
B.T. 109
8" Jack Pine

3 18° 25'
5 10° 15'

New Tie
Bottom Place
8" Jack Pine

Woods

G-F-9 F/5-9
M.C. bet. Sec's 8 & 9
T. 44 N. R. 31 W.

8+9

No Dir. Govt. Survey Evidence Found

M.C. is evidenced by a 3" I. Pipe,
2" High with Alum Cap. #3091
Plastic Cork inserted thereon.
Set 6-7661 D.M.A.


Time Spent: Approx. 1 1/2 hrs.

G-F-9 F/5-9 7-13-81 51
M.C. bet. Sec's 8 & 9 M. Forstach
T. 44 N. R. 31 W. P. Skogen

800 Survey - Light Wind

Mississippi River

Levods



Woods

N-3

1/4 Sec. Cor.
T. 44 N. R. 31 W.

18

19

No Orig. Gov't Survey Evidence Fnd.

No manu. Fnd.

Assumed 1/4 Sec. Cor. location @ Int.
of ex E-W dirt Rd. & Remnant Fence-
line & Field line North.
Fnd. numerous pieces of barbed wire
fence buried in Rd.

No Rd. excavation was made.

Time Spent: Approx. 1/2 Hr.

N-3

1/4 Sec. Cor.
T. 44 N. R. 31 W.

18

19

Bob Pothly Elder, windy

Cultivated

Field

Cultivated

Field

Remnant Fence line
Buried wire & occasional
post standing - Also
Field line

Edge of Rd.

S 86° W

N 86° E

Assumed 1/4 Sec. Cor.

Edge of Rd.

O. H. Power line

Cultivated

8'

22'

8'

P-1

14 Sec. Cor.

T. 44 N. R. 31 W.

R. 32 W. R. 31 W.

24 + 19

No Orig. Court Survey evidence fnd.

14 Sec. Cor. is evidenced by a 1" Solid Iron, 15" below grade, in 4' H-S dirt Rd. 10' South of 2nd Field Rd. East.

No Rd. excavation was made.

Numerous pieces of barbed wire buried in Rd.

Time Spent: Approx. 1/2 Hr.

P-1

14 Sec. Cor.

T. 44 N. R. 31 W.

R. 32 W.


7-13-31

24 + 19 M. Bertsch

R. 32 W. R. 31 W. Skogen

82° Pth. 14. Survey. 1/2 Hr.

1/2 Hr.



NO. 447 TELEPHONE

T-1

14 Sec. Col.

T. 44 N. R. 31 W

25 - 30

R. 32 W. R. 31 W.

No Orig. Gov't Survey Evidence Fnd.

14 Sec. Col. is evidenced by a 1/2" I. Pipe

2" below glade, 4' East of N-S Glade

Rd. # 12254 inserted within pipe.

Menu. Pits. 2 Bull Oak tree trcs

WSN show in their records.

No Pth. excavation was made.

Time Spent: Approx. 1 Hr.

T-1

14 Sec. Col.

T. 44 N. R. 31 W.

25 - 30


R. 32 W. R. 31 W.

7-13-81

M. Foertsch

P. Skogen

33° RTH, 214° - Calm -



Time Spent: Approx. 1 Hr.

V-1

Sec. Cor.

T. 44N., R. 31W. R. 32W. 36 31 R. 31W.

25 30

No Orig. Gov't Survey Evidence Fnd.

Sec. Cor. is evidenced by a 1 1/4" Well pt. which was graded out and reset using exist. B.T. + Fenceline West, 6" below grade & 6' East of N-S & gravel Rd. Exist B.T. is in WSN's records.

No Rd. excavation was made.

Not Logged yet

Time Spent: Approx 1 Hr.


V-1

Sec. Cor.

T. 44N., R. 31W. R. 32W. 36 31 R. 31W. 330 311. 311. - 301m

25 30

1-13-81 W. Foerster 55



T. 44 N.	31	
36		
R. 32 W.	P. 31 N.	
1		6
		T. 43 N.

Subsidiary Expense Ind.		
-------------------------	--	--

60	1	2 1/2"	I.P.C.
----	---	--------	--------

المسألة الأولى

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

Landsera in white.

[illegible]

1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

wa = male

Time Spent: April 14th

T. 44 N.	35	36
----------	----	----

See. 105.

11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100. 101. 102. 103. 104. 105. 106. 107. 108. 109. 110. 111. 112. 113. 114. 115. 116. 117. 118. 119. 120. 121. 122. 123. 124. 125. 126. 127. 128. 129. 130. 131. 132. 133. 134. 135. 136. 137. 138. 139. 140. 141. 142. 143. 144. 145. 146. 147. 148. 149. 150. 151. 152. 153. 154. 155. 156. 157. 158. 159. 160. 161. 162. 163. 164. 165. 166. 167. 168. 169. 170. 171. 172. 173. 174. 175. 176. 177. 178. 179. 180. 181. 182. 183. 184. 185. 186. 187. 188. 189. 190. 191. 192. 193. 194. 195. 196. 197. 198. 199. 200. 201. 202. 203. 204. 205. 206. 207. 208. 209. 210. 211. 212. 213. 214. 215. 216. 217. 218. 219. 220. 221. 222. 223. 224. 225. 226. 227. 228. 229. 230. 231. 232. 233. 234. 235. 236. 237. 238. 239. 240. 241. 242. 243. 244. 245. 246. 247. 248. 249. 250. 251. 252. 253. 254. 255. 256. 257. 258. 259. 260. 261. 262. 263. 264. 265. 266. 267. 268. 269. 270. 271. 272. 273. 274. 275. 276. 277. 278. 279. 280. 281. 282. 283. 284. 285. 286. 287. 288. 289. 290. 291. 292. 293. 294. 295. 296. 297. 298. 299. 300. 301. 302. 303. 304. 305. 306. 307. 308. 309. 310. 311. 312. 313. 314. 315. 316. 317. 318. 319. 320. 321. 322. 323. 324. 325. 326. 327. 328. 329. 330. 331. 332. 333. 334. 335. 336. 337. 338. 339. 340. 341. 342. 343. 344. 345. 346. 347. 348. 349. 350. 351. 352. 353. 354. 355. 356. 357. 358. 359. 360. 361. 362. 363. 364. 365. 366. 367. 368. 369. 370. 371. 372. 373. 374. 375. 376. 377. 378. 379. 380. 381. 382. 383. 384. 385. 386. 387. 388. 389. 390. 391. 392. 393. 394. 395. 396. 397. 398. 399. 400. 401. 402. 403. 404. 405. 406. 407. 408. 409. 410. 411. 412. 413. 414. 415. 416. 417. 418. 419. 420. 421. 422. 423. 424. 425. 426. 427. 428. 429. 430. 431. 432. 433. 434. 435. 436. 437. 438. 439. 440. 441. 442. 443. 444. 445. 446. 447. 448. 449. 450. 451. 452. 453. 454. 455. 456. 457. 458. 459. 460. 461. 462. 463. 464. 465. 466. 467. 468. 469. 470. 471. 472. 473. 474. 475. 476. 477. 478. 479. 480. 481. 482. 483. 484. 485. 486. 487. 488. 489. 490. 491. 492. 493. 494. 495. 496. 497. 498. 499. 500. 501. 502. 503. 504. 505. 506. 507. 508. 509. 510. 511. 512. 513. 514. 515. 516. 517. 518. 519. 520. 521. 522. 523. 524. 525. 526. 527. 528. 529. 530. 531. 532. 533. 534. 535. 536. 537. 538. 539. 540. 541. 542. 543. 544. 545. 546. 547. 548. 549. 550. 551. 552. 553. 554. 555. 556. 557. 558. 559. 560. 561. 562. 563. 564. 565. 566. 567. 568. 569. 570. 571. 572. 573. 574. 575. 576. 577. 578. 579. 580. 581. 582. 583. 584. 585. 586. 587. 588. 589. 590. 591. 592. 593. 594. 595. 596. 597. 598. 599. 600. 601. 602. 603. 604. 605. 606. 607. 608. 609. 610. 611. 612. 613. 614. 615. 616. 617. 618. 619. 620. 621. 622. 623. 624. 625. 626. 627. 628. 629. 630. 631. 632. 633. 634. 635. 636. 637. 638. 639. 640. 641. 642. 643. 644. 645. 646. 647. 648. 649. 650. 651. 652. 653. 654. 655. 656. 657. 658. 659. 660. 661. 662. 663. 664. 665. 666. 667. 668. 669. 670. 671. 672. 673. 674. 675. 676. 677. 678. 679. 680. 681. 682. 683. 684. 685. 686. 687. 688. 689. 690. 691. 692. 693. 694. 695. 696. 697. 698. 699. 700. 701. 702. 703. 704. 705. 706. 707. 708. 709. 710. 711. 712. 713. 714. 715. 716. 717. 718. 719. 720. 721. 722. 723. 724. 725. 726. 727. 728. 729. 730. 731. 732. 733. 734. 735. 736. 737. 738. 739. 740. 741. 742. 743. 744. 745. 746. 747. 748. 749. 750. 751. 752. 753. 754. 755. 756. 757. 758. 759. 760. 761. 762. 763. 764. 765. 766. 767. 768. 769. 770. 771. 772. 773. 774. 775. 776. 777. 778. 779. 780. 781. 782. 783. 784. 785. 786. 787. 788. 789. 790. 791. 792. 793. 794. 795. 796. 797. 798. 799. 800. 801. 802. 803. 804. 805. 806. 807. 808. 809. 810. 811. 812. 813. 814. 815. 816. 817. 818. 819. 820. 821. 822. 823. 824. 825. 826. 827. 828. 829. 830. 831. 832. 833. 834. 835. 836. 837. 838. 839. 840. 841. 842. 843. 844. 845. 846. 847

No Orig. Gov't Survey Evidence

[illegible]

Coronet Rd. E 5230' West of East. SE

10

L: No. 10. Numerous pieces of

۱۰۰

10 Pl. excavation was made.

X/100

| Time | Speds. | Temp. | W. H. |
|------|--------|-------|-------|
| | | | |

7-21

Sec. Cor.

T. 44 H. R. 32 W.

| | |
|---------|------|
| 18-72-1 | 1777 |
|---------|------|

85

217

2.2.81. 6. Skopje.

1050 2.54 Cairn 1

...

2911

— 4 —

✓

MoLES

11

NO. 4.

TELEPHONE

old Peter - Portland
Landing

1

63

2

کے

Z-15 1/4 Sec. Cor.

34

T. 44 N., R. 32 W.

3

Found no evidence of original gov't survey.

We assumed the corner to be at the intersection of the roads east & south. This point is on a fence to the west. The dist to the bottom land west is about 26' longer than gov't measure.

A search was made no magnetic dips other than garbage & parts of fence were found.


1 hour spent at this location

Z-15 1/4 Sec. Cor.

34

T. 44 N., R. 32 W.

3




7/4/81

34

D. Rasmussen
T. Converse

480° F. 1/4 Sec. Cor.



5 90° E

Z-14/5 M.C.


34
3

T.44 N., R.32W.

Found 4" clay drain tile filled with conc. lying down on river bank by fence. Searched area & found 30" Bur Oak with large old definite blaze SW. We assumed this to be one of the original U.S. B.T.'s. Reset the conc. & clay man. from this B.T. It fell 1' 1/4 into river 2 feet north of steel fence post & 11 feet north of westerly extension of fence. We made 3 new B.T.'s as shown with top & bottom blaze facing corner. The distance east to our assumed sec. cor. is 13 feet short of gov't meas.

We found no other evidence

M.C. Monument





Time spent: 3 1/2 hours

Z-14/5 M.C.

31
3

T.44 N., R.32W.

+30" F. Pth. y. Clay



(S1-2) assumed sec. cor. 2-15

8/4/91

D.R. Gussman
T. Converse

61

V-19 1/4 sec. con.
T. 44 N., R. 32 W.

Found no evidence of original gov't survey.
It appears that east of the swamp the 2 fences north & south of road follow R/W line, where south fence enters swamp it angles NW possibly back to true section line.


State of Minnesota owns north of this line & George De Mosier owns south of it so there is no N-S property line.

No other evidence was found.

Time spent 1 1/2 hours

V-19 1/4 sec. con.
T. 44 N., R. 32 W.

26 84121 63
35 D. Rasmussen
T. Converse
+ 80°F. 4/14/64



67

T. 44 N., R. 33 W.

Found no evidence of original
Can't survey or any resurveys.


We assumed the corner at the intersection of roads north & west. we made our measurements from there. Roads are straight & are graded up 1 to 2 feet above surrounding ground.

No road excavation was done.
No magnetic dips found.

Time spent: $1\frac{1}{2}$ hr.

1981
D. Rasmussen
C. Nelson

+80°F hazy & breezy.



V-17/18 M.C. 26/35

T. 44 N., R. 32 W.

We measured west from the edge of swamp near 4 cor. to the river. Where we entered the bottoms we found a fence north of the one we had been following. The fence to the south appears to be property mine. A trail has been built across bottoms graded up 5'± from surrounding ground. The stump & tree shown are possible B.T.'s. Neither one is definite. The stump matches gov't mens. closely to north fence. The 26" W. oak would match gov't meas. if gov't meas. was 581 links - not 181 + if their bearing to it was NW instead of NE. Pictures were taken of both.

No other evidence was found.

Time spent (2 hrs.)

V-17/18 M.C. 35

T. 44 N., R. 32 W.


12/31

D. Rasmussen

C. Nelson

65

+80° F. hazy & breezy



53

N., R. B. Z. W.

Found no evidence of original
gov't survey or any resurveys.
George DeRosier owns all the
land in this area so no
property lines are near
to be maintained. Mr DeRosier
was not around so we were
not able to question him. We
talked to his wife & she had
no knowledge of any corner
or section lines.

We assumed the corner at
E & intersection.
No magnetic dips were found
at the road. was not excavated.

Time spent: 12 hour

X-17 $\frac{1}{4}$ sec. cor. 34 + 35

T. 44 N., R. 32 W.

Found no evidence of original
gov't survey or any resurveys.
George DeRosier owns all the
land in this area so no
property lines are near
to be maintained. Mr DeRosier
was not around so we were
not able to question him. We
talked to his wife & she had
no knowledge of any corner
or section lines.

We assumed the corner at
E & intersection.
No magnetic dips were found
at the road. was not excavated.


Time spent: 12 hour

18/5/81

D. Rasmussen

C. Nelson

Reading & Study + 2008



63

T. 44 N., R. 32 W.

[illegible]

family

assumed $\frac{1}{4}$ car
see X-17

Time spent: $1\frac{1}{2}$ hr.

Z-17

Sec. Cor.

34 35
3 2

T. 43N., R. 32W.

Found no evidence of original gov't survey or any resurveys. We assumed a location for the corner at the apparent intersection of 2 fence lines. Our measure to the edge of the swamp south could fit gov't meas. (Land rises gradually) Our meas. to the edge of swamp east is approximately 1 chain longer than gov't meas.

We ran a compass line east on an extension of our fence to the west. This line runs down to township road to the east. There is no visible line between the 2 properties shown in sketch but our line would be a good division line.

Occupant of north house did not have knowledge of the corner.

Time spent: 2 1/2 hours

Z-17

Sec. Cor.

34 35
3 2


T. 43N., R. 32W.

+70°F Cloudy

Cultivated

Cultivated

township road



Cultivated

3-4' wooded

10/81 T. Converse 69

T-21 $\frac{1}{4}$ sec. cor.

$$\begin{array}{r} 26 \\ + 25 \\ \hline \end{array}$$

T. 44 W., R. 32 W.

Found no evidence of original
gov't survey or any resurveys.
We assumed the corner to be
at the intersection of the E
of gravel road & the E of
the old road bed to the
south. Our measure to the
assumed sec. cor. south matches
exactly with gov't meas. Gov't
meas. to the edge of prairie north
was 2 chains. The gravel road
is at the edge of the present
prairie. The old road bed rises
2 to 3 feet above prairie.
The gravel road is at the
same grade as the surrounding
ground & the road bed is
3" deep. There is a remnant
fence running north from our
assumed cor.
No magnetic dips were found
No road excavation was made.

Time spent: 1 1/2 hour

| T-21 | 1/4 sec. cor. | 26 | 25 | 1/6/81 | T. Converse | 70 |
|------|---------------|----|----|--------|-------------|----|
|------|---------------|----|----|--------|-------------|----|

T. Converse 70

T. 44N, R. 32W.

+70°F Cloudy

10-15 years
W. Pines

Remnant fence

lines up roughly
with old road
bed lead

585'W

assumed
1/4 sec. cor.

200

- old road bed with large trees growing in it + pieces of fence.

like at approximate

2640 (meas. with EDM)

Open Drainage

assumed section

township rd.

T-2-1

Z-9

Sec. cor.

T. 44N., R. 31W.

32 33

5 4

T. 43N., R. 31W.

Found 2" pipe with a 4" diameter round cap (iron) 3' west of road & 0.50' south of powerline, 4" below grade of road. Found 4 witness monuments set by John Curo in 1922 according to county records. The corner may have been hit by road grader but is still in good condition. All witness monuments had been disturbed by farm equipment & will undoubtedly be disturbed in the future. The road is at about the same grade as the surrounding ground. The road bed appears to be 1' deep.

Time spent: 1 1/2 hours.

Z-9

Sec. cor.

T. 44N., R. 31W.

32 33

5 4

T. 43N., R. 31W.

+75°F Cloudy

8/6/81 D. Rasmussen
T. Converse 71

