

Crow Wing County Surveyor


No. S-116

PAGE

1	E/F-13	T-138N R29W
2	E-13/14	
3	D/E-13	
4	C-17	
5	B/C-17	
6	E-17	
7	E/F-17	
8	E-19	
9	E-15	
10	A-15	
11	L-17	
12	N-17	
13	E-21	
14	A-23	
15	A-25	
16	C/D-21	
17	N-19	
18	N-21	
19	G/H-17	
20	C-25	
21	V-17	
22	X-17	
23	X-13	
24	T-17	
25	V-15	T-138N R29W

26	Z-5	T-138N R28W
27	R-13	T-138N R29W
28	T-13	
29	R-15	
30	R-17	
31	P-17	
32	Z-13	
33	Z-21	
34	Z-23	
35	Z-24	T-138N R29W
36	Z-3	T-138N R28W
37	X-9	T-138N R28W
38	N-13	T-138N R29W
39	J-13	
40	G-13	
41	A-13	
42	J-19	T-138N R29W
43	J-21	T-138N R28W
44	V-17	
45	T-21	
46	T-25	
47	R-23	
48		
49	T-17	T-138N R28W
50	R-17	

51	P-17	T138N R28W
52	N-17	1
53	N-25	
54	R-21	
55	L-17	
56	J-17	
57	P-21	
58	R-19	
59	V-13	
60	V-9	T138N R28W
61	E-25	T138N R29W



NE	41.60
NW	41.60
SE	43.10
SW	42.35
SE 80°	9.40
NORTH	13.00
5' BEAM	4' BEAM

D. LANDBECKER
S. MOE

T/38 R29

21

Common 95%

2" 1/2	0.20"	4194
--------	-------	------

ABOVE GROUND

OLD FENCE TO SOUTH
STOPPING SHORT BY
50' + - FENCE IS
LYING ON GROUND

1865 66.5

T/38 R29

4/1/3

10-12-81

74' BALSAM
= DISC 0220 BLA 2-E

~~99
 96
 94
 92
 90
 88
 86
 84
 82
 80
 78
 76
 74
 72
 70
 68
 66
 64
 62
 60
 58
 56
 54
 52
 50
 48
 46
 44
 42
 40
 38
 36
 34
 32
 30
 28
 26
 24
 22
 20
 18
 16
 14
 12
 10
 8
 6
 4
 2
 0~~

18°
7W/N
ONK
EXISTING,
BLAZE

40
1975
To CORN

DOUBLE BUZZE AND DIGIT
IN ALL TREES

1 mi

T138 R29

MC

COMMON 3-10

FOUND 2" CAPPED IRON
48" LONG LYING ON
SIDE NEXT TO FENCE POST
10' IN LAKE.

SET UPRIGHT AND
DROVE INTO GRASSY AREA
20" ABOVE WATER

6.0' EAST TO ANOTHER IRON
2" 48" HIGH CONNECTED TO
FENCE

OLD WOVEN WIRE FENCE
EAST TO ROAD.

1865 9LS

D. LANDECKER

S. MOE


2

10-12-81

T138 R29

E - 13/14

N



DOUBLE BLAZE AND DISC IN
ALL TIES

1 1/2

T138 R29

COMMON 3-4

MC

FOUND 2" IRON PIPE

18 HIGH WITH SEVERAL
ROCKS AROUND BASE.

LANDOWNER SHOWED US
SURVEY NO NAME WAS
ATTACHED ALTHOUGH
IT LOOKED LIKE A LOT
OF WORK HAD BEEN
PUT INTO THE SURVEY

SURVEY FOR 'AL LINDQUIST'
THOUGHT SURVEYOR FROM
CROSS LAKE

M. LANDMECKER DID SMALL LOT
SURVEY TO EAST BUT DID NOT
DO SECTION WORK ONLY
A LITTLE LAND PIECE WAS
TRADED.

1865 945


D. LANDMECKER
S. MOE

3

10-12-81

T138-R29

D/E-13



EXISTING DOUBLE BLADES
HND PUT DISC IN ALL TIES

2 1/2 mi
T138 R29

MC
COMMON 3+2


FOUND 2" IRON PIPE
FLUSH TO GROUND WITH
PILE OF ROCKS AROUND
IRON.

ONE OLD BLAZE
5" MAPLE WEST

1865 GLS

D. CANDECKER
S. MOG 5
10-12-81

T138 R29
B/C-17



2 1/2 A-

T138 R29

SECTION COK

3/2
10/11

2" IRON WITH 3" CAP
0.20 ABOVE SRND

5' NORTH OF & NEW
LOGGING TRAIL

TWO OLD BT TREES

LOOKS LIKE J. CURD
ALTHOUGH BLAZES ARE
RELATIVELY NEW

Clear CUT AREA TO NE
1 YEAR OLD

1865 GLS

1919 J. CURD

1920 J. CURD 12" POP N 57 3/4° W 44.04'
10" POP. N 30° E 12.58'
15" DEAD W.P. 58 1/2° E 23.22'

D. LANDECKER
SMOE


6

T138 R29

E-17

10-13-81

N



ENOUGH
DOUBLE BLAZES
AND DISC IN ALL
TIE TREES

12-11

T138 R29

MC

COMMON 100 Y

NOTHING FOUND AT
THIS LOCATION

MEASURED SOUTH FROM
E-17 GOVT DIST
FIT LAND BUT NOTHING
WAS TO BE FOUND

1865 GLS


T138 R29

E/F -17

10-13-81

W. LANDECKER
S. MOORE

7



1 1/2 mi

T-138 R-29

1/4 car

Common E-11

FOUND NOTHING AT THIS
LOCATION.

WALKED EAST FROM
E-17 ALONG CLEAR-CUT
THEN USING USGS
SEARCHED SWAMP AREA.

NO MARKS FROM
LOGGING AREA EITHER.

1865 GLS

1919 J. CURRO

3' x 3" x 20" BIRCH STAKE

MIDWAY
BETWEEN E-17 + E-22

SWAMP WAS VERY WET
AND BOGGY

D. CANDECKER
S. MOG

8

10-13-81

T-138 R-29

E-19

12

T138 R29

1/4 CORNER
COMMON 13-10

FOUND 2" PIPE WITH 3" CAP
ALSO FOUND
ALL 45°-42' IRONS

THEY WERE LYING DOWN
WE STRENGTHENED THEM
AND FIRMED UP, THEN USED
AS TIES

OLD FENCE RUNNING
NORTH AND WEST
MOST ALL FENCE LYING
IN GROUND AND HARD TO
SEE

± 500' WEST TO HIGH GROUND

1865 GLS

1920 J. CURRO 3" x 3" x 36" stake

8" TAM, N18°W 45.7'

7" TAM, S60 1/4°W 38.7'

D. LANDECKER
S. MOE


9

10-13-81

F138 R29

E-15

N



DOUBLE BUAES AND DISC
IN TIE TREES

T-138	R29
-------	-----

1/2	cor
-----	-----

3-34	3-34
------	------

FOUND SPIKE 4" LONG
WITH SURVEY RIBBON

5-10	YEAR	OLD	BUSH
LING	TO	WEST	

REMAINING
OLD BARBED WIRE FENCE
NORTH 5' + -

POSSIBLY WHEN SURVEY WAS
DONE FOR PUBLIC ACCESS TO
LIERIE LAKE NORTH IN
CASE COUNTY.

1868	GLS
------	-----


D. CANDICKER
S. MOE

10

T138-1229

51-4

10-13-81



2 hrs

T138 R29

1/4 corner

common 15+14

nothing FOUND AT
THIS LOCATION

FENCE COMING EAST FROM L-13
TO CENTER OF 15
MEASURED SOUTH FROM J-17
AND MATCHED FENCE
AT CENTER LOOKED
IN AREA BUT NOTHING
FOUND.

ROAD AND FENCE BETWEEN
SECTION 14+15 IS NOT
A STRAIGHT LINE AND
HAS SEVERAL ANGLE POINTS.

1865 GLS


D. LANDECKER
S. MOE

11

T138 R29

10-14-81

L-17



T13 R29

SECTION COR

15 14
22 23

FOUND 2" IRON PIPE
OLD CAST STEEL TOP WAS
BROKE COULD POSSIBLY
HAVE BEEN SET BY CURB
AND CAP HAS BROKE OFF

IRON WAS SET IN
CRUISEWAY ROAD ON A
SWAMP CROSSING

NO TIES WITHIN ANY
DISTANCE OF CORNER $\pm 1000'$

1865 GUS
1919 J. CURB 4"x4"x30" STAKE
NO TIES


D. CANDLER
S. MOE

12

T138 R29

N-17

10-14-81



T 138 K29

W.C. COLVER

2	1
11	12

0.40 BELOW GREEN RAIN

FOUND	2" IRON PIPE
WITH	3" CAP. ROUNO.

ALSO 3' 45° 42' 1 ROWS
THE TWO ON SOUTH
SIDE STILL IN GOOD SHA
USED SH 7115 W 600 545


3

D. LANDECKER
S. MATE

10-14-82

7128 P29

F-21



DOUBLE BLADES AND DISC IN ALL TIES.

NO. 447

INTEL

1/2

T138 R29

1/4 CORNER

Common 1-36

NOTHING FOUND AT THIS LOCATION

TALKED TO ADJACENT OWNER ON SECTION 36 CASS COUNTY (FORMER GLOVER) SHE SAID THEY HAVE NEVER SEEN A POST THERE EVER AT LEAST SINCE 1954 ANYWAY.

They BUILT FENCE WEST FROM ROAD USING CENTER LINE OF TWP ROAD TO EAST

1863 925


T138 R29

A-23

DLANDECKER
S. MOE

14

10-14-81



D. LANDECKER
S. MOE

15

10-14-81

T138 R29

A-25

N

FENCE

TRAIL

DRIVE

NO. 447

SEC COR

35 | 36

2 | 1

NOTHING FOUND ACCORDING
TO L. GLOVER LONG TIME
RESIDENT. ROAD GRADER
KNOCK-OUT IRON PIPE AT
E - E OF ROADS

POINTED WHEKE PIPE MIGHT
BE BUT NOTHING COULD
BE FOUND

1803 GLS

T138 R29

1/2

T138 R29
1 1/2 mi

MC
COMMON 2-1

NOTHING FOUND TALKED
TO OWNER OF RESORT
WHICH SECTION LINE
WOULD GO THROUGH THEY
SAID. B. SPAIN, AND
E. SCHULTZ DID SOME
SURVEY FOR THEM BUT
DID NOT THINK THEY
FOUND OR SET ANY
POINT BY THE LAKE.
SAID SPAIN THOUGHT
HIS SECOND CABIN SOUTH
THE SECTION LINE WENT
THROUGH.


1865 GCS

T138

2/D-21

D. LANDECKER
D. LANDECKER
S. MOE
10-14-81
16

JAIL LAKE



1 1/2

T138 R29

4 car

Command 14-23

NOTHING FOUND
LOOKS LIKE THE NEW
ROAD WORK DONE IN
AREA WOULD HAVE
WIPED ANY THING
OUT THAT MIGHT HAVE
BEEN THERE

ROAD RUNNING EAST
TO N-17

TALKED WITH C. TOLLEFSD
AND OWNER SAYS
HE NEVER REMEMBERS ANY
CORNER THERE.

1865 GLS

T138 R29

N-19

POSSIBLE

10-15

SEARCH AREA

±400'

PASTURE

TRAIL

D. LANDECKER
S. MOE

10-15-81

17

T138 R129

SEC CAR

14/13

23/24


NOTHING FOUND.
 MEASURED WEST
 FROM N-17 FOLLOWED
 ROAD WEST THEN FENCE
 LINE EXCEPT FOR LAST
 1000' WHICH WAS IN WOODS
 MEASUREMENT FIT GOOD
 USGS TOPO MAP.

TALKED TO C. TOLLEFRUD
 HE CLAIMS HE HAS SEEN
 AN IRON THERE IN AREA
 WE SEARCHED.
 ALSO SAID THAT IRONS
 HAD BEEN PLACED AT ALL
 SECTION CORNER POINTS.
 NOT AT 1/2 SECTION POINTS.
 EXCEPT A LARGE ROCK MARK
 N-25 WITH X ON TOP

T138 R29

N-21

10-15-81



1865 GLS

1919 JCURD

3"X3"X40" STAKE

SET BY CO. SURVEYOR

2 June

T138 R29


MC

COMMON 10-11

FOUND OLD WAGON STAKE
4' ABOVE GROUND
2' BELOW GROUND

NOT SURE WHAT IT
COULD BE UNLESS DID
ANNUAL SURVEY

DID NOT TIE OUT




D LANDECKER
S, MOE

19

T138 R29

9/H-17

10-15-81



CHOPPED
FIELD

WOODS

1865 925

T138 R29

2 Jan

27 26

34 35

SEC. COR.

2" ABOVE GROUND

2" IRON PIPE 3" ROUND CAP

ALL 45°-42' IRONS IN PLACE
AND WERE TIED TO.

NO EXISTING OLD BM WERE
TO BE FOUND

ZIGMUND SAID FENCE
WAS BUILT 16.5' WEST
OF SECTION LINE
1865 GUS

1908 LE GARRISON SET POST
FROM ORIG BTS.

DLANDECKER
K. MILLER

21

T138 R29

1-17

10-28-81

1-15 10" POPLAR

1-13 HIGH

8000

1-13 HIGH

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

57.41

DOUBLE BLAZES AND DISK IN
ALL THE TREES

T138 R29

2 mi

34 1/4 corner
35

MEASURED NORTH FROM
Z-17

2640. THEN SEARCHED

AREA.

LAND OWNER SIGMUND
SAID FENCE WAS BUILT
1 ROD WEST OF SECTION
LINE. HE HAS NEVER
SEEN CORNER.

NO CORNER FOUND

1865 GLS


T138 R29

X-17

P. CANDECER
K. MILLER

22

10-28-81



D. LANDECKER
R. MILLER

23

10-28-81

T138 R29

X-13

N

WOODS

PASTURE

WOOD

WOOD

1/4 COR

33-34

T138 R29

2

MEASURED SOUTH 264'

FROM V-13

FOUND FENCE CORNER

RUNNING N-S AND WEST

NO PIPE FOUND

NO TIES MADE

STRONG INDICATION THAT

FENCE CORNER WOULD

PROBABLY BE LOCATION

FOR CORNER

1865 SLS

T138 R 29

2 hrs

measured north
from V-17 followed
fence, but didn't
find nothing

FENCE HAD 12' JAG TO
EAST AT
OF T-17 CORNER

1865 GLS

1/4 Cor

27 + 26


D. LANDECKER
K. MILLER

10-28-81

T138 R29

T-17

PASTURE



T138 R29

27

34

FOUND 2" CAST STEEL
PIPE LYING PARTIALLY
ON SIDE NEXT TO SOUTH
EDGE OF OLD DRIVE WAY

PUT BACK IN STRAIGHT
AND BOUNDED IN GROUND

WILL TIE OUT LATER

MEASURE WEST 2647 ± TO V-13

ALL DISTANCE MEASURED WITH
EDM

ONLY LARGE TREES AND
PINE TREES WITH IN 1000'

1865 GCS


T138 R29

V-15

10-28-81

25

D. CANDECKER
K. MILLER



DOUBLE LINES AND DISC IN TIER

D. LANDECKER
K. MILLER

26

T138 R28

10-29


2-5

1/2 in

3" CAPPED IRON FLUSH
WITH BIT SURFACE
CO. RD #1

OLD HWY DEPT TIES
BLAZED TREES AND
RETIED

31 32
6 5



T 138 R 29

2 Jan

21

22

28

27

TALK TO LANDOWNER
WAS NOT SURE OF EXACT
SEEING ANY CORNERS ANYWHERE
SAID 'GOOD LUCK' SHOWED US
ARIEL THAT CONSERVATION
DEPT. HAD SKETCHED ON,
SHOWED CORNER IN SAME AREA
AS USGS.

SEARCHED AREA BUT FOUND ONLY
MANY FENCES RUNNING ALONG
EDGE OF SWAMP
NONE RAN E-W
OK N-S

NO TREES OLDER THAN
20-40 yrs old

1865 GUS


D. LANDECKER
K. MILLER

27

T 138 R 29

R 43

10-29-81



T138 R29

1/4 CORNER

0

~~28~~ 27

COULD NOT SEARCH
CORNER IN SWAMP

HAND OWNER SAID NO
CORNER COULD EVER BE
IN SWAMP, NO BOTTOM

NO FENCE

1865 GUS

T138 R29

7-13

D. LANDECKER
K. MILLER

10-29-81

28

D. LANDECKER
K. MILLER

10-29-81

T138 R29

R-15

1/4 COR.

27

2 in

27

Measured EAST FROM
APPROXIMATE R-13

NOTHING FOUND
LOCATION WOULD BE IN
A SWAMP

1865 GLS

3

10-29-81

R-17

T-138	R-295
-------	-------

22	23
----	----

242. June

27	26
----	----

MEASURED	NORTH FROM
100	100
200	200
300	300
400	400
500	500
600	600
700	700
800	800
900	900
1000	1000

27

W	EAST	FROM
---	------	------

408000. 2-13

Conclusions

OLDEST TREES

20-30 yrs old

no stamps

BEEN BURNT

575	5981
-----	------

1919	J. CURD
------	---------

1920	J. CURR
------	---------

100

N 29 33 E 135.85'

Stamp D.

N. 43° 35' W 55.1'

40"	WH. PINE
-----	----------

N. 43 35 W 37.1

5-Pop.

2015/04/15

71000

379	25 E	12.63
-----	------	-------

BETVOND

0347

2

5

23

D. LANDECKER
K. MILLER

31

10-29-81

T138 R29

R-17

N

SCARS

100' ±
OLD FENCE

1/4 COR.

22-23

T138 R29

2 Jun

MEASURE NORTH FROM
APPROX LOCATION R-17
FOUND TWO LARGE W. PINE
WITH BLAZES (MAYBE FIRE SCARS)
ALSO WITH FENCE ATTACHED
GOING TOWARD NW
NOTHING ELSE TO BE
FOUND

1865 949

T/38 N R29W

33 34
4 3

1 1/2 mi

FOUND 2" IRON FLUSH
WITH GROUND, NORTH
SIDE OF TRAIL

OLD EXISTING BLAZES

BIT TAGS IN BOTH
EXISTING T & BT TREES

ALL TREES HAVE METAL
DISC IN SIDE OF TREE
WHERE DIST. WAS TAKEN
AND DOUBLE BLAZES

T/38 N R29W

2-13

N

8" TP OLD
BLAZES
N 20° E
61.71'
8" TP
N 30° E
20.51' OLD GLAZES
N 20° E
20.51'

TRAIL

PASTURE

PINE

PINE

K. MILLER
S. MOE

11/2/81

32

1/2 in

35	36
2	1

Found County Monument
Q Hwy

FLUSH	WITH	TAR
-------	------	-----

ALL TREES HAVE DOUBLE
BLAZES AND DIS IN SIDE
OF TREES

OLD BLAZES IN TREES
NOTED

k. miller
s. moe
33

11/2/81

T 138 W R 296

34

4" Norway

10" R=0.0AK
... 0L0 0L47F

7

Y Basswood
Old Blazes
Cumulative

6" BAR
DATE

T 138 N R 29 W

36

1/4 COR

1

1/2 mi
E HWY CAST IRON COUNTY
MONUMENT 2" BELOW SURFACE
OF GROUND

OLD BLAZES WHERE NOTED

ALL TREES HAVE DOUBLE
BLAZES AND DISC IN
SIDE OF TREE

PRES. FENCE RUNNING
NORTH IS 10' E WEST OF
MONUMENT

T 138 N R 29 W

36

N

OLD BLAZES
10" BURR OAK

5" BURR OAK

N 50° E
149.111

10' E
10' W

S 10° E
81.23'

9" BURR OAK
OLD BLAZES

5" BURR OAK
OLD BLAZES

K. Miller
S. MOE

34


11/2/81

T 138 W R 29 W

TOWNSHIP LINE

1 1/2 mi

3 1/2



Large nail & of
Two Hwy, flush with surface

TREE IN SE QUADRANT
HAS NO BLAZES BUT
HAS DISC IN SIDE OF
TREE

ALL OTHER TREES HAVE
DOUBLE BLAZES AND METAL
DISC IN SIDE OF TREE

NO EXISTING BLAZES

K. MILLER

S. MOE

11/2/81

35

T 138 W R 29 W

2-24

TOWNSHIP LINE

9" BURR OAK

PASTURE

235°
370.37'

CO. RD. #1

555°
143.87'

WOODED

5" BURR OAK

4" BURR OAK

6" BURR OAK
NO BLAZES

NO. 447

718 W

T138 N R 28 W

1/4 COR

1 h

LARGE NAIL IN JAR

5' S. OF & HWY AT SUMMIT

ALL TREE'S HAVE DOUBLE
BLAZES AND DISC IN SIDE
OF TRUNK

NOTE OLD BT ON SKETCH

31



K. M. IER
S. MOE

11/2/81

T138 N R 28 W

2-3

BT TAG
9" J.P. OLD BLAZES

N 46°
88.9'

4" J.P. TAG

CO. ROAD

HWY

NO. 447

N 46°
59.9'

8" J.P. BT TAG
OLD BLAZES

4" J.P. TAG

GRAVEL ROAD



T 138N R 28W

32-33

4 dig

NAIL IN E OF HWY 3" BELOW
SURFACE

NO EXISTING BLAZES OR
BT

ALL TREES ARE MARKED
WITH DOUBLE BLAZES AND
DISC IN SIDE OF TREE

4/9/83 LANDSCAPERS TIES 3 COR INTERACT
FOUND 3/4" x 24" I.P. OVER A 12" B.S. SPEC
OVER POST REMAINS - TIES (P&H) STILL
HOLD TO PERPETUATE THIS COR.

TDB

K. Miller
S. MOE

37

11/2/81

T 138N R 28W

X-9

WOODED

PASTURE

GRAVEL ROAD

585° E

118.25'

10" SP

54.00'

117.00'

535° E

115.23'

10" SP

11" SP

60 to 40 ft

LOW

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

X

K. Miller

S. MOE

38

11/5/81

T 138 N R 29 W

16

15

21 22

1 1/2" IRON 6" BELOW

GROUND LOCATED 4 ROAD

FROM WEST AND SOUTH EDGES

OF TRAIL EAST

Q OF N-S

ROAD IS 3"

EAST

Trees HAVE DOUBLE

BLAZE UNLESS NOTED.

DISC IN SIDE OF ALL

Trees

T 138 N R 29 W

N-13

19" WAINC NO BLAZE

N 40° W
144'

90°

12" NORWAY BLAZE

N 70° W
135'

E

N 40° E
64.53'

90°

11" J.P. NE

11" J.P. NE

N

WAINC

TRAIL

WOODED

T 138N R29W 1/4

-9-10--


2" IRON BENT 4' W OF
 & DOWN FENCE LINE TO WEST
 TIES ARE TO LARGE SPIKE
 TO WHERE THE END OF
 IRON IS. 2" BELOW SURFACE.

ALL 45°-48' IRON WERE IN
 PLACE BUT ONLY S.W.
 IRON LOOKED UNDISTURBED.

ALL TREES HAVE DOUBLE
 BLAZES AND DISC IN
 SIDE OF TREES

K. Miller
 S. MOE
 11/5/81

40



41

33	34
4	3


T-136 W R 29 W

PLUMBERS
LOPPED 2" PIPE 1 1/2' BELOW SURFACE
ALL TREES HAVE DOUBLE
BLAZE AND DISC IN
SIDE OF TREE.

SOME	OLD	GLAZE	TREY
when	NOTED		

OLD	BLAZES AND	RT TAG
TN	TREE	

LOOKS LIKE COUNTY HWY DEPT
HAS TIED OUT ALSO IN
LAST COUPLE OF YEARS.



T 138N R 29W

1/2 A-

S 1/4 COR

14'

2" IRON ON SURFACE

BENT ALL DISTANCE

ARE FROM WHERE IRON

IS GOING STRAIGHT DOWN

IRON IS 100' SOUTH OF

FENCE THAT IS E + N

OF CORNER

ALL TREES DOUBLED BLAZED

AND HAVE METAL DISC

ON SIDE OF TREE

REPLACED WITH

3/4" IRON PUT IN WHERE

DISTANCE WERE TAKEN

AND WHERE THE ORIGINAL IRON


WOULD HAVE BEEN IF STRAIGHT.

11/5/81

T 138N R 29W

S 1/4

N



NO. 447

K. Miller

S. MOE

43

11/5/81

T138N R29W

1 1/4 Sec

11 12

14 13

(S)


4" CAST IRON CAPED
PIPE 1" ECHING SCAUS OUT
BEING CORNER. FLVSH.

ALL 45° IRON WERE
IN ONLY SW 45°
SEEMED TO BE DISTURBED

ALL TREES ARE DOUBLE
BLAZES AND HAVE METAL
DISC IN SOME OF TREE.

200' to the SW IS OLD
TRAIL

POWER LINE TO EAST ± 50'



T 138N R 28W

27 26

34 35

2 4 1/2' E

2" IRON HAD CAST IRON
CAP ON AT ONE TIME IT
HAS BEEN KNOCKED OFF IT
IS BENT AND A LARGE
SPIKE IS IN WHERE IT
WOULD BE IF STRAIGHT

45° IRONS PRESENT IN
THE NW 1/4 QUADRANT
THAT DON'T APPEAR LIKE
THEY HAVE BEEN
DISTURBED. NETS AND

FENCE TO EAST AND WEST
BLACK TOP ROAD

ALL TREES HAVE DOUBLE
BLAZES AND METAL DISC.
IN SLOPE. NO OLD BLAZES
OR BT PRESENT THAT WERE
FOUND.

K. Miller

44

S. MOE
11/5/81

T 138N R 28W

V-17

#13

5" 31

N 25° W 19'

50' 21"

N 50° E 41'

WOODEN 3" IRON

8' 11"

WOODEN 3" IRON

8' 11"

8" DITCH

4' 30"


8 1/2' E

PASTURE

NO. 447

W. TELSON

K. Miller
S. Moore 45
11/5/81



T 138N R 20W
-26-25-

1/2" IRON FLUSH WITH
GROUND & 1" OF COAR

OLD BLAZES NO BT

ALL TREES HAVE DOUBLE
BLAZES AND DISC IN SID
OF TREES

18/5/11


T 138W R 38W

25	1
30	1

1/2" TROW FLUSH IN & CO #1

ALL TREES HAVE DOUBLE
GLAZES AND DISC IN
SIDE OF TREES

ONE Q LD. BLAZE TREE.



47

T/38N R28 W


4" CAP. 2" CAST IRON
2' ABOVE GROUND

ALL 45° IRON ARE
PRESENT AND LOOK
IN GOOD SHAPE

ALL TREES ARE DOUBLE
BLAZED AND HALF METAL
DISCS. ON THE SIDE OF
TREES

FENCE IS OLD AND DOWN
MOSTLY BUT STILL CAN BE
FOLLOWED

1863	GLS
------	-----



T 133W R 256

22	23
27	26

4. "CAST IRON CAPPIED 2" IRON.
BENT MEASUREMENT ARE
TAKEN WHEN IRON WOULD
BE IF STRAIGHT. FOUND AT
SEQUENCE

ALL 45° 40' FT IRONS
ARE IN PLACE


ALL TREES ARE DOUBLED
BLAZED AND HAVE METAL
0.50 IN. SPACING BASE

T-138 N R 28 W

2-17

2

K. Miller
S. Moore
11/9/81




K. Miller
S. MOE
11/9/81

52

142
T 138N R 28W
5 14
22 23
4" CAP IRON A 2" IRON FLUSH
WITH GROUND
ALL BUT THE SE 45° 40'
IRON ARE IN SE COR
WAS THERE BUT HAD BEEN
COMPLETELY PULLED OUT
ALL TREES HAVE DOUBLE
BUZZES AND HAVE METAL
DISC IN SIDE OF TRUNKS

T 138N R 28W
N-17
N



R.M. Miller
S.MOE
11/9/81

53

1 hr

13	18
24	19

T 138N R 28W
N-25


Solid IRON BAR OLD RIBBON
ON IT 3" Below ground
2" x 1/2" BENT FOUND
IN E TRAIL

ALL TREES HAVE DOUBLE
BLADES AND METAL DISC.

E POWERLINE 100' ± FEET

12" TAMARACK S 15° E POSSIBLE OLD
BLAZE ALSO FENCE IN TREE
FROM N-S FENCE LINE
LOOKS LIKE MAYBE OR 95 FT
1863 S 2° E 38 LK TAM. 4"

1904 Whiteley
1927 Bartholomew
1934 Morse-CC DNR



2 T 138 W R 28 W

23	24
26	25

2" FROM 6" BELOW SURFACE
OF ROAD. E 3' W.

NE 1/4 NW 45° 40' WERE
PRESENT

ALL TREES HAVE DOUBLE
BLAZES AND DISC IN
SIDE OF TREE


K. Miller
S. MOE
11/10/81

T 138 W R 28 W

R-21

GRAVEL ROAD

5' ELM



9' PINE

K. Miller
S. MOE
11/9/81

55

1 1/2 mi

T 138 N R 28 W

NO CORNER FOUND

NO BLAZES

CHAINED 2640' NORTH FROM
SE COR SEC 15. N-17

CLEAR CUT AREA LOOKS LIKE
IT MAY HAVE BEEN
BULLDOZED

1863 GLS

T 138 N R 28 W

A-17

N

WINTER TRAIL

WOODED

CLEAR CUT AREA

NO. 445

WILSON

1 1/2 hrs

T138N R28W

NO CORNER FOUND

NO BLAZED TREES

WALKED UP WINTER

TRAIL TILL FOUND OLD CABIN

LOCATED ON USGS MAP

LOOK 400' TO 600' FEET NORTH OF CABIN

TALK WITH PEOPLE IN OLD CABIN AND SAID THEY HAD COME TO AREA FOR 15 YEARS AND NEVER SEEN ANY CORNERS.

1883 S45

1919 J CURRO

1920 24" STUMP

24" W. PINE

2" SPRUCE

2" POP.

4" BIRCH

2" x 2" x 60' STAKE

N55E 83.0'

N24W 80.3'

S49W 62.2'


S34E 60.0'

12. Miller
S. MOE
11/9/81

56

T138N R28W

J-17



NO. 445

W. B. MOE

24

T138 N Q 28 W

23 - 24

4" CAN ON A 2" IRON PIPE
 MONUMENT WITH CHAINS
 AT END OF TRAIL, 1 1/2'
 ABOVE GROUND.

SE 45° 40' IRON
 IS NOT IN. THE
 REST WERE PRESENT


DID NOT TIE TO NW 45°-40' BENT

ALL TREES BLAZED
 WITH DOUBLE BLAZES
 AND A DISC IN SIDE
 OF TREE

1863 SLS

57

K. Miller
 S. MOE
 11/10/31



NO 445

WTELETYPE

K. MILLER 58
S. MOE 11/10/81

2 hrs

T 138 N R2B W

123

26

4" CAP IRON MONUMENT
FLUSH WITH GROUND NEXT
TO FENCE CORNER POST

45° 40' IRON PRESENT

NW AND SE ARE IN GOOD
EVIDENCE FOR DIST. BUT ARE
STILL BENT. SW IS PULLED
OUT NE IS BENT SO BENT
NO DIST IS TAKEN

ALL TREES MARKED WITH
DOUBLE BLADES AND METAL
DISC IN LINE OF TREES.

1863 GLS

T 138 N R2B W

R-9

WOOD


6' J.P.

6' J.P.

NO. 445

WILSON

FIELD



28 27

33 34

T 138N R 28W

RAILROAD SPIKE 2' NORTH
OF DOWN FENCE LINE FROM
NORTH E ROAD SOUTH.
FLUSH WITH TAIL

TREES HAVE DOUBLE
BLAZES AND METAL DISCS.
IN THE SIDES OF TREE


TELE PEO HAVE METAL
DISC. IN SIDE OF POLE

K. Miller
S. MOE
11/10/81

59

T 138N R 28W

V-13



7138 R28

29 28

32 33

REARCH AREA AT
APPROX. PT. LOCATION
OF COUNTY ROAD #1

LAND VERY MARSHY
WITH STANDING WATER
AND DEAD TREES
LOOKS LIKE BEAVER HAS
DAM CLOSE BY

K. MILLER
S. MOE

11-10-81

7138 R28


U-9

28

29

32

33



240

T 138 R 29

1 6
12 7

MEASURED SOUTH FROM C-25
USING COMPASS.

AREA FITS USGS WELL
ALTHOUGH SEARCH DID NOT
UNCOVER ANY CLUES TO
CORNER, MANY LARGE
BURNT STUMPS.

L. GLOVER LAND OWNER AND
LONG TIME RESIDENT CLAIMS
HE NEVER HAS SEEN CORNER
ALTHOUGH HE REMEMBERS
THAT ALL SECTION CORNERS
IN GAIL LAKE TWP WERE TYPE
AND 1/2 SECTION CORNERS
WERE WOOD STAKES.

12. L. HANDECKER
S. MOE

10-15-81 61

T 138 R 29

E-25

1868 SLS

1919 J CURD

1920 J CURD

5" J.P. N 85 E 31.9'

7" J.P. N 61 W 32.3'

5" P.O.P. S 73 W 43.3'

4" P.O. S 18 E 30.2'

2" x 2" x 20" STAKE