

Crow Wing County Surveyor

No. S-118


INDEX

Contract No.

S-118 No. S-118

Surveyor
Widseth, Smith, Nolting

Page	Corner	Page	Corner
1	M.C. 1/4-44-31	25	N $\frac{1}{4}$, 27-44-31
2	M.C. 7/8-44-31	26	SE, 33-44-31
3	M.C. 7/8-44-31	27	S $\frac{1}{4}$, 34-44-31
4	1/4 + M.C. 13-44-32 18-44-31	28	N $\frac{1}{4}$, 29-44-31
5	NE, 3-44-31	29	N $\frac{1}{4}$, 26-44-31
6	M.C. 3-44-31	30	NE, 33-44-31
7	E $\frac{1}{4}$, 3-44-31	31	E $\frac{1}{4}$, 33-44-31
8	E $\frac{1}{4}$, 10-44-31	32	S $\frac{1}{4}$, 31-44-31
9	N $\frac{1}{4}$, 14-44-31	33	S $\frac{1}{4}$, 32-44-31
10	N $\frac{1}{4}$, 24-44-32	34	S $\frac{1}{4}$, 33-44-31
11	NE, 28-44-31	35	S $\frac{1}{4}$, 35-44-31
12	N $\frac{1}{4}$, 2-44-31	36	N $\frac{1}{4}$, 12-43-31
13	N $\frac{1}{4}$, 16-44-31	37	NE, 11-43-31
14	E $\frac{1}{4}$, 21-44-31	38	S $\frac{1}{4}$, 36-44-31
15	N $\frac{1}{4}$, 28-44-31	39	SE + E $\frac{1}{4}$, 35-44-31
16	NE, 27-44-31	40	N $\frac{1}{4}$, 11-43-31
17	E $\frac{1}{4}$, 23-44-31	41	NE, 10-43-31
18	N $\frac{1}{4}$, 31-44-31	42	E $\frac{1}{4}$, 3-43-31
19	N $\frac{1}{4}$, 33-44-31	43	N $\frac{1}{4}$, 35-44-31
20	E $\frac{1}{4}$, 32-44-31	44	NE, 35-44-31
21	E $\frac{1}{4}$, 14-44-31	45	N $\frac{1}{4}$, 10-43-31
22	N $\frac{1}{4}$, 23-44-31	46	NE, 9-43-31
23	E $\frac{1}{4}$, 34-44-31	47	"
24	SE, 34-44-31	48	E $\frac{1}{4}$, 4-43-31



INDEX

Contract No.

S-118 No. S-118

Surveyor

Widseth, Smith, Nolting

Page	Corner
49	N $\frac{1}{4}$, 36-44-31
50	N $\frac{1}{4}$, 9-43-31
51	WE, 8-43-31
52	N $\frac{1}{4}$, 8-43-31
53	NE, 7-43-31

E-11/12

M.C. between Sec. 4 & 9
T. 44 N., R. 31 W.

No Orig. Gov't Survey Evidence
Exists.

In searching for M.C. projected
the existi. brushline west to River
At river there was evidence of
brush cuttings, but no more.
was found.

Distance from Sec. 4 to west to
low area matches Gov't dist.
Dist. from west edge of low area
to river meas. shorter than Gov't
dist.

Sec. 4
Sec. 9

Time Spent: 2 1/2 hrs.

E-11/12

M.C. between Sec. 4 & 9
T. 44 N., R. 31 W.

75° Subnet

148' Meas.
165' Gov't
Edge of low area
Open water
924' Gov't
927' Meas.
4 3 9 10
Exist brush line
which bogs. 583° W
Woods

11.55.55.10. River

No. S-118

T-314

M.C. between

Secs. 7 & 18

T. 44 N., R. 31 W.

Sec. 1

Sec. 18

No Orig. Gov't Survey Evidence
Evident -

It appears that the river's edge in this has changed due to the fact that 2 high banks above the river exist. The wash out area between supports the idea that the M.C. & its B.T.'s have been obliterated.

There is a fence remnant which runs west of the Sec. cor. approx. 500' long.

Time Spent: 1 1/2 Hrs.

9-11-81 ②


T-314

M.C. between Secs 7 & 18

T. 44 N., R. 31 W

75° Sunny

No. S-118



G-H, 5
M.C. between Sec's
T. 44 N., R. 31 W.

7-8

No Orig. Gov't. Survey Evidence
Evident -

M.C. is evidenced by a 3" I. Pipe
flush with ground with Alum. cap
stamped "Witness to Meander
Cedex" RLS # 3091 inserted in
center. The witness had two
exposed B.T. Trees evident.

No fence/line evident.

Time Spent: 1 1/2 hrs.

G-H, 5

M.C. between Sec's
T. 44 N., R. 31 W.

7-8

No. S-118

171.5

1/2" Bull Oak

7.8
H 25° W
6.70

Witness to M.C.
3" I.P. with Alum. Cap.

14820 W
Hail 7.70
5" Tall
Bull Oak

H 83° E
47.97

Witness B.T. Tag
3" Bull Oak

South
15.25'

Witness B.T. Tag
5" Bull Oak

Woods

Woods

9-11-81
M. Foertsch
T. Converse
75° Sunny

L-11 W. 1/4 Cor. Sec. 18
K-L, 1 - M.C. between Secs. 18-44-31 &
13-44-32.

No Orig. Cont. Survey Evidence; Find:

The W. 1/4 Cor. location, according to Don Pederson, resident of area since 1946, stated that corner was never established to his knowledge. All fence lines in area were put @ edge of woods and not necessarily on '1/4 line.

K-L, 1 - M.C. on west line Sec. 18-44-31 is evidence by a remnant piece of fence only marking only an E-W direction. This fence was an old fence in 1946 when Don Pederson's father purchased the land. He also stated that the shoreline in this area fluctuates 50' to 200' depending upon the season / rainfall.

Time Spent = 2 1/2 hrs.

K-L, 1 & L-1
No. S-118

Mississippi

9-11-81
M. Foertsch
T. Comdese
75° Sunny

River

Remnant Fence

* Since before 1946

* Per Don Pederson

10507

Woods

Potlatch

Plantation

2 Field Rd.

W. 1/4 Cor. location per Don Pederson

Cultivated

Field

A-17

Sec. Corner

34

35

T. 45 N.

R. 31 W.

3

Z

T. 44 N.

R. 31 W.

Found 3" capped pipe in concrete badly bent & concrete broken up. Could still see some numbers in conc. It is 1.4 feet east of new 4' high steel fence post. This is same corner used by Dean Anderson. In 1976 subd. of sec. 2.

We checked for original B.T.s & other resurvey evidence - found none.

There is new growth NW, NE, & SE of corner (4 to 6" trees) - edge of clear cut area appears to run down sec. lines.

Pipe is in bad shape & should be replaced.

time spent = 1 hour

A-17 Sec. Cor.

34 | 35 T. 45 N., R. 31 W.
3 | 2 T. 44 N. R. 31 W.

+55°F

PM, cldy.



windy

9/16/81

No. S-118

D. Rasmussen

C. Nelson



made 3 new B.T.s - top & bottom
blaze on face of tree

A-16/17

$\frac{J}{m}$	
---------------	--

T. 45N, R. 31W

T. 45N, R. 31W

We chained gavit distance from section corner to the east to M.C. location. This distance fit the river good. We found no evidence of original survey or any resurveys.

Section line is clearly evidenced
by short piece of fence + edge
of woods.

$$\text{time spent} = 1 \text{ hour}$$

A-16/17

34

T. 45 N., R. 31 W.,


T. 45 N., R. 31 W.,

9/16/81 No. S-118 + 60°F P44.Cdy.

No. S-118

No. S-118

No. S-118



C-17 1/4 sec. cor.

3-2

T. 44N., R. 31W.

Found Crow Wing Co. cast iron monument set by Dean Anderson RLS 3091 in 1976. Distances to existing B.T.'s match Anderson's. 1 B.T. broken off - made new one.

No original evidence found.

Distance to lake matches closely to govt measure.

Time spent = 1 hour

C-17 1/4 sec. cor.

3-2

T. 44N., R. 31W.

Buffalo Lake

Marsh grass - 50't 1'

allens

12" w. oak

25

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

D. Rasmussen

C. Nielson

9/16/81

+60° Pth. Cldy.

No. S-118

⑦

Wooded all around

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

1.10

top & bottom blaze with nail in disc in bottom blaze

1.10

1.10

1.10

1.10

B-17 $\frac{1}{4}$ sec. cor. 10.71

6-17 1/4 sec. Cor.

U. Washington
U. Michigan

②

6-17 1/4 sec. Cor.


U. Washington
U. Michigan

②

6-17 1/4 sec. Cor.

U. Washington
U. Michigan

②



$$\frac{m}{N} = \frac{1}{2}$$

T. 44 N., R. 32 W.

Don Pederson, landowner in Section 13, stated that his father owned all of sec. 13 at one time. He sold all but the E. 1/4 to Crow Wing State Park.

We ran a compass line to the river - found no evidence of a line after the clearing bends south. He matched goit measure to the bottoms but fell short on running to the river. The distance may fit better if the line was moved south. We may have gotten off a little with our compass line as there is a lot of brush.


time spent = $2\frac{1}{2}$ hours

$$\begin{array}{r} 13 \\ 27 \end{array}$$

9

9/16/81, +60°F P1/y: C1d_x.

No. S-118



A-19, 1/4 Sec. Cor.
T. 44 N., R. 31 W.
Sec. 35
→ Sec. 2

Ho Orig. Gov't. Survey Evidence Fnd.


1/4 Sec. Cor. is evidenced
12" deep reset from ties made at the
time WSH platted "Buffalo Hills"
Prior to this time, the corner was evidenced
by a C. Wing Co. Cast Iron Monu.
Cast Iron Monu. was destroyed during
construction of utilities in this area.

This corner was set by
Dean Anderson in 1976 on
line at proportionate measure
to govt distance between the
Sec. corners east & west of it.

Time Spent: 1 Hr.


A-19, 1/4 Sec. Cor.
T. 44 N., R. 31 W.
Sec. 35
→ Sec. 2
T. 45 N., R. 31 W.
Sec. 35
→ Sec. 2
T. 44 N., R. 31 W.
Sec. 35
→ Sec. 2

No. S-118



All Ties Meas. to Plat. in tree.
Ties have top blades only.

T-11, 1/4 Sec. Cor.
 T. 44 N. R. 31 W
 No. 1118
 Survey Evidence End
 Measured 2640' East from Manu.
 End. @ SW Cor. Sec. 9. End. an old
 Rd. bed North of exist. trap rd. Also
 End. bits & pieces of old bank where
 buried @ this approx. dist. from Sec
 Cor. and North of old rd. bed.
 The old plat at "Central" & Park Additions
 to Burrows are shown to have the N-S
 1/4 line in Sec's. 9 & 16 to be the
 West line of the plat. The rds. &
 lots in this area are not evident.
 Time Spent: 2 hrs.



P-13, 1/4 Sec. Cor.
T. 44 N., R. 31 W.

21-22

No. Orig. Cont. Survey Evidence Find.

Approx. 1/4 Sec. Cor. is evidenced by a line of badly decayed wood fence posts. The line of posts is approx. 500' to 600' long and seems to end 217'± East of N-S Trail. The posts are 2" to 3" dia. above ground, & 5" to 7" dia. below the ground, with a sharpened end. The posts are still standing but no wire was found.


Time Spent: 3 hrs.

P-13, 1/4 Sec. Cor.
T. 44 N., R. 31 W.

21-22

No. S-118

9-17-81
M. Foerisch
T. Converse
650 Cddy



9-17-21
 M. Foerster
 T. Converse
 60° Cldy.

R-11, 1/4 Sec. Cor.
 T. 44 N., R. 31 W.
 Sec. 21
 Sec. 28


No. S-118

No. Orig. Cor. 4 Survey Evidence Find.


1/4 Sec. Cor. is evidenced by an oval top monu. as a witness Monu. to actual 1/4 Sec. Cor. Stamped as being S 45° E - 45 Ft. from 1/4 Sec. Cor. All other witness monu's as well as the 1/4 Sec. Cor. must have been graded out during Rd. construction.

The monu was set @ 1/4 Sec. Cor. location & no rd. excavation was done.

Time Spent: 1 hll.



Woods



Woods

All trees to witness Monu. have top blazes only and dist. meas. to nail in tree.

P-17, 1/4 Sec. Col.
T-44 N. R. 31 W.


T-44 N. R. 31 W.

2. Bitumen

Field	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
-------	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----

[illegible]

P-17, 1/4 Sec. Cor.
T-44 N. R. 31 W.



U-11, 1/4 Sec. Col.
T. 44 N., R. 31 W.

Sec. 28.

50.33

1460 Orig. Court Survey Evidence Encl.

1/4 Sec. Cor.	is evidenced by Spk.
---------------	----------------------

Ind. 0.5' below grade @ Int. of fence

James North West


Time Spent: 2 hrs.

U-11, 1/4 Sec. Col.
T. 44H., R. 31W.

9-18-81 (61)

M. Forestsch
T. Converse
60° Clear

No. 6-118



X-9 1/4 sec corner

32 • 33

T. 44N. R. 31W

No original Gov't Survey Evidence Found.

1/4 sec. cor. is evidenced by a 3/8" spike 0.4' below grade. Also a fence line running west along the edge of a woods. Spk is 6' east of E.

Gov't land ties call for a tamarack swamp 1122' south of corner. We chained to the edge of a Alder swamp 450'± south of corner.

All ties have nails in sides.

Time Spent: 1 1/2 hrs

X-9 1/4 sec cor.

32 • 33

T. 44N. R. 31W



No. S-118

9/30/81

P. Skogen

T. Converse

50° Ground



1105° W

Abut P. Pole

S 85° W X 25.4'

Call P. Post 1122' W

Wap. 1.5

(Find Spk. Old line now)

Grade

5' 10" 5' 10" 5' 10"

4" Pine

6' Aspen

4' drive

150'± 505° E

Edge Low Area



L-21 1/4 SEC. COR.
T. 44N. R. 31W

14 13

FOUND 1 1/2" IRON MON. PROTRUDING
0.50' ABOVE GRADE. WE FOLLOWED A
REMANANT FENCE SOUTH THROUGH SWAMP
AND CHAINED ABOUT DIST. SOUTH FROM
EDGE OF SWAMP TO CORNER, THIS DIST.
FIT VERY WELL. WOODS EXIST ALL AROUND
CORNER. THE TREES WERE GROWN OVER
& WE RE-OPENED BOTH BLAZES & BY TAL
IS STILL EVIDENT ON ALL TIES, WE CHAINED
NEW DISTANCES TO BT'S WHICH WERE
MADE BY DEAN ANDERSON IN BOOK 243.
DIST'S FIT WELL.

NO EVIDENCE OF ORIGINAL GOV'T
SURVEY EXIST.

TIME SPENT : 2 HRS.


L-21 1/4 SEC. COR.
T. 44N. R. 31W

SEC. 14
13

C. NELSON (2)
T. CONVERSE

9/28/81

No. S-118



N-19	1/4 SEC. COR
T-44N	R-31W

N-19 1/4 sec. cor
T44NR31w

14

32

C. NELSON 22


T. convulsa

9/28/81

No. 5-118

FOUND 3/8" SPIKE FLUSH WITH GROUND.
WE FOLLOWED A FENCE LINE AND
RANDOM BRUSH LINE EAST TO FENCE
INTERSECTIONS. IT APPEARS THAT
SOME SURVEYOR BUSHED A RANDOM LINE
ALONG FENCE AND STOPPED AT FENCE
INTERSECTIONS. WE FOUND NO OTHER
BRUSH LINES. DON'T SURVEY CALLS
FOR SWAMP 272' EAST OF CORNER. WE
CHAINED 540' TO A DEFINITE EDGE OF
A CATTAIL SWAMP. NO EVIDENCE OF
ORIGINAL DON'T SURVEY EXIST.
WE MADE 2 TIES WITH TOP BLAZE
AND NAIL ON SIDE OF TREE
WOODS EXIST ALL AROUND CORNER.
FENCE TO WEST IN FAIR CONDITION

TIME	SPENT	: 2 HRS.
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100



NELSON 24
 C. NELSON 23
 T. CONVERSE
 9/28/81

X-17 1/4 SEC COR
 T. 44N R31W


X-17 1/4 COR.
 T. 44N R 31W

No. S-118

NO ORIGINAL GOVT SURVEY EVIDENCE EXISTS
 QUARTER CORNER IS EVIDENCED BY A CROWN WING COUNTY CAST IRON MON FLUSH WITH GRADE 0.5' WEST OF WEST EDGE OF TAIL.
 NO FENCE LINES EVIDENT EAST OR WEST.

NW TIE TREE HAS NAIL ON SIDE - NO BLAZE
 SW AND SE TIES WERE EXISTING WITH BTS
 TAGS - NO BLAZES.
 Q OF COUNTY RD. 21 BEARS NO SOW

TIME SPENT: 1HR.



Z-17 SEC. CORNER

34 35
3 2

T. 44N R. 31W

NO EVIDENCE OF ORIGINAL GOV'T
SURVEY EXISTS, GOV'T SURVEY CALLS
FOR CREEK 132' NORTH OF CORNER.

I BELIEVE DURING THE IRRIGATION PROCESS
OF THE RICE PATTIES THE CREEK GOT
RE-ROUTED. IT NOW MEASURES 250'

IN 1922 CARD PLACED A 5-MON CORNER
ONLY ONE TIE EXISTS NOW WHICH IS THE
NE. THIS TIE WAS FOUND BENT SO WE
STRAIGHTENED IT.

SEC. CORNER IS EVIDENT BY A CROW
WING COUNTY CAST IRON MON 0.8'
BELOW ASPHALT IN E OF COUNTY
ROAD 21.

SE AND SW TIES HAVE BT TAGS.
AND BOTH BLAZES EVIDENT ON SW TIE.

TIME SPENT: 1 1/2 HRS

Z-17 SEC. CORNER

34 35
3 2

T. 44N R. 31W

No. S-118

CREEK

RICE
PATTIES

ROAD

8' WIDE ROAD

2" IRON MON.
DUAL TOP
BROKEN OFF

8' WIDE ROAD

DRAINAGE DITCH
N 85° E

S 45° E
71.07'

PP WITH
BT TAG

20" WHITE
OAK

LOW LAND

AND SCATTERED
TREES

RICE
PATTIES

N 05° E

28'

C. NELSON (24)

T. CONVERSE

9/28/81

R-15 1/4 SEC. COR
T44N R 31W

22
27

WE TALKED TO MR. JACKSON WHO
SAID HE OWNS THE N 1/2 OF SEC. 27
HE SAID TO HIS KNOWLEDGE THIS CORNER
HAS NEVER BEEN SET, ALTHOUGH HE
SAID THAT APPROX. 50 YRS. AGO A MR.
ANDERSON, WHO USE TO OWN THIS LAND,
PUT IN A N-S FENCE AT THIS
LOCATION. ALL FENCES FOUND HERE
ARE REMNANT AND VERY FEW POSTS
ARE STANDING STILL.

MR. JACKSON OWNS SEVERAL PLANES
AND SAID HE USES THIS AS A LANDING
STRIP.

NO EVIDENCE OF ORIG. GOV'T SURVEY
EXISTS.

TIME SPENT: 1 HR.

R-15 1/4 SEC. COR
T44N R 31W

22
27

C. NELSON
T. CONVERSE

9/28/81

No. S-118

FIELD

WOODS

LARGE
ROCK
AT
8000

N 86° E

N 86° E

= 22'

DIRT LANDING STRIP

FIELD

WOODS

Z-13 Sec. Cor

33 34
4 3

T. 44 N. R. 31 W

No evidence of original Gov't Survey Found

Section Corner is evidenced by a 3" Round capped monument 2" above swamp and 0.5 feet northeast of railroad tie fence corner. Fence running South & East.

In 1922 John Curo set a 5" monument corner when he reran the township line. We found and reset the NW, NE and SW monuments.

The SE monument could not be found. We also found 3 other trees with top and Bottom Blazes with 1st tags in bottom blaze. The 8" Tamarack S 45° E at 45.25' had blown over. Also made a new tie to a 6" Brubaker. (see picture.)

There is a 6' wide creek 300' North of Section Corner. Corner is surrounded by swamp with high ground 24' 6" South of corner.

Time Spent: 1 1/2 hrs

Z-13 Sec. Cor

33 34
4 3

T. 44 N. R. 31 W

Rice

Patlies

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

6' wide ditch

P. Skogen

T. Converse

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

P. Skogen

T. Converse

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

P. Skogen

T. Converse

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

P. Skogen

T. Converse

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

P. Skogen

T. Converse

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

9/30/81

Z-15 1/4 corner

34
3

T 44N R 31W

No evidence of original Gov't Survey Found.

1/4 corner is evidenced by a 3" Alum. capped monument with a plastic cork stamped RL's #309. Corner was found in the fence line running North and South.

We found 3 tie-trees with Top and Bottom blazes, with a BT tag in the bottom blaze. These ties were set by Dean Anderson. The spruce tree northeast of the corner is dead so we made a new tie. (see picture)

Cor. is surrounded by swamp with definite high ground 40± south of 1/4 corner along the fence line.

Time Spent: 1 hour


Z-15 1/4 Corner

34
3

T 44N R 31W

P. Stogen @
T. Converse

9/30/81



Definite High Ground

No. S-118

R-7

1/4 sec. cor.

20
29

T. 44 N., R. 31 W.

Found 2" pipe with $3\frac{1}{2}$ " diameter round cap (iron) protruding 18" from 5' diameter mound of dirt in swamp just west of high ground 6 ft. Mound of dirt is 2 ft above swamp level. This monument is similar to those set by Curo & Knudsen in the 1920's & 1930's.

Talked to Mrs. Specht - landowners in SW 1/4 sec. 20. They knew of no markers or fence lines in this area but felt that the ditch cut across the SE corner of their property.

We found no other evidence of property lines or surveys.

There are some rotted pine stumps in the area of the orig. B.T. but we did not measure to any of these.

time spent = 3 hours


11481 T. Converse

29

No. S-118

+ 40°F overcast & windy

T. 44 N., R. 31 W.



All B.T.'s new - Top & bottom blaze on face of tree - measured to bottom blaze.

R-19 $\frac{1}{4}$ sec. con. $\frac{Z3}{Z6}$

T. 44	N. 2, R. 31 W.
-------	----------------

Found 2" pipe $2\frac{1}{2}$ ' high in swamp. Believed to be pipe set by Wadsworth, Smith, Noltling, & Assoc. in 1978 on split between sec. canners to the east & west.

Found 2 existing B.T.s. They have top & bottom blades on face of tree with brass B.T. tag in bottom blade.

No other evidence was found.

time spent = 1 hour


一、

T, 44 W., R. 31 W.

No. 5-118

D. Rasmussen
T. Converse

+40°F, overcast & windy



V-13

Sec. Cor.

28 27
33 3428 27
33 34

V-13 Sec. Cor.

10/12/81

(39)

T. 44N., R. 31W.

T. 44N., R. 31W.


D. Rasmussen
T. Converse

+40°F overcast & windy

No. S-118

Found cast iron man & B.T.'s set by Dean Anderson RLS #3091 in 1976. Also found 2 1/2" pipe set by Roger Mustonen SW of C.L. man. C.L. man. 15' 2" above ground & B.T.'s for it have top & bot. blaze on face with brass B.T. tag in bottom blaze. Mustonen's pipe protrudes from ground 6" & is painted yellow. Mustonen's B.T.'s have top & bottom blaze on face of tree with yellow paint.

There has been dispute over location of this corner.



time spent = 1/2 hr.

X-13

 $\frac{1}{4}$ sec. cor.

33-34

T. 44N., R. 31W.

Found 3" Aluminum capped pipe set by Dean Anderson, RLS #3091, in 1976. Also found 1 1/2" pipe next to wood post - set by Roger Mustonen.

Distance south to edge swamp May, not, be accurate as the slope of ground is very gradual & edge swamp is not very definable.

There has been dispute over location of this corner.

time spent = 1 hour

10/12/81

33-34

X-13. $\frac{1}{4}$ sec. cor.


33-34

D. Rasmussen
T. Converse

T. 44N., R. 31W.

+40°F overcast + windy

No. S-118

edge swamp
indefinite

1

1

1

1

1

1

1

1

1

1

1

1

Z-3

 $\frac{1}{4}$ sec. cor.

3 T. 44N., R. 31W.
6 T. 43N., R. 31W.

Z-3 $\frac{1}{4}$ sec. cor.

31-44-31
6-43-31

10/12/81

D. Rasmussen
T. Converse

(52)

Found 5 monument corner.

$\frac{1}{4}$ corner is 2" pipe with round cap. Witness corners are 2" pipe with oval caps. All mon. flush with ground or just below surface.


This corner is probably the one set by Curo in 1922 as shown on county records. It is similar to other corners he set at that time. All fence lines found were broken up & lying down. No evidence of original B.T.s left.

The entire area is wooded - mostly 6" to 12" Red oaks & Jack Pines.

The trail to north of corner bends sharply from a southeasterly course to a northeasterly course at this location. This is readily seen on a quadrangle or aerial photo.

+40°F overcast, windy

No. S-118



4 Pines are new B.T.s made -
Top & bottom blaze on face of
tree. Measured to bottom blaze

time spent = $2\frac{1}{2}$ hours

Z-7 1/4 sec. Cor.

32-44-31
5-43-31

Found 2" pipe with round cap - on fence line (north-south). This is evidently a 5 monument cor. similar to those set by Guco in the 1920's. 3 witness monuments were found - the NE monument being gone. The SW & SE monuments were found lying down underground & were not straightened up. 2 new ties were made.

Mr. Vickerman, landowner in NW 1/4 section 4, stated that the fence line was his east line & the powerline was his north line. He did not know of any monuments at this location. We told him what we had found & explained the location of the mon. found.


Time spent = 1 1/2 hours

Z-7 1/4 sec. Cor.

32-44-31
5-43-31

10/14/81
D. Rasmussen
T. Converse

No. S-118



$$\begin{array}{r} 33-44-31 \\ + \\ 4-43-31 \\ \hline \end{array}$$

1/4 sec. cor.

We chained into corner from the west from section corner in road. Followed fence line to its intersection with north-south fence. We did not find Curro's corner or any B.T.s.

There is no other evidence left except for the fence corner.


Brush is thick (alders & willows)
Swamp is wet.

time spent	=	$2\frac{1}{2}$ hours
------------	---	----------------------

Z-1174 sec. cor. 35-44-31
4-43-31
+55° F clear

10/14/81
D. Rasmussen
T. Converse

No. 8-118



Note: All fences are old permanent fences

F-23	1/1 sec	con.
------	---------	------

F-23	1/1 sec	con.
------	---------	------

F-23	1/1 sec	con.
------	---------	------

F-23	1/1 sec	con.
------	---------	------

F-23	1/1 sec	con.
------	---------	------

F-23	1/1 sec	con.
------	---------	------

10/14/81
D. Rasmussen
T. Converse
+ 55° Far Clear

36

36



E-21 Sec. Cor.

2 1
11 12

T. 43 N., R. 31 W.


Found no evidence of original govt survey or any resurveys. We had one large dip in road on d-dug down & found large black rock. we made no other excavations in road. we assumed the sec. corner to be in d road & on powerline to the south. We tried to measure to edge of swamp north to check dist. with govt measure but the edge of swamp is not definable.

time spent = 1 1/2 hours

E-21 Sec. Cor.

2 1
11 12

T. 43 N., R. 31 W.



10/14/81 D. Rasmussen
T. Converse

(37)

+55°F

No. S-118

Z-23 1/4 sec. cor. 36-44-31
1-43-31

Found 2" pipe with oval cap - similar to monuments set by Curran in 1920's. This is probably the corner he set in 1919 according to county records. None of his B.T.s on the original gov't B.T.s are remaining. We established 4 new B.T.s.

The distance west to the edge of the swamp matches closely to gov't measure

Mrs. Holtz & her son, landowners in '56 1/4 sec. 36 & NE 1/4 sec. 1 believed the monument to be the 1/4 sec. corner.

New B.T.s have top & bottom blaze on face of tree - measured to bottom blaze.

Time spent = 3 hours

Z-23 1/4 sec. cor. 36-44-31
1-43-31

(38)

10/14/51/81
D. Rasmussen
T. Converse

No. S-118

Fence is woven wire & barbed wire with 3" pipe fence posts 4' high

3x
0.6

2x

Area is thickly wooded all around

with 4"-10" Aspen

Birch & Oaks

gov't = 297'

285'

6" Aspen

West

2.08

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

11.36

No. S-118

T. 44N.

Z-21 sec. cor.

35 36 R. 31 W.

Z 1

T. 43N.

D. Rasmussen
T. Converse

+50°F clear

we ran a compass line west from Z-23 (S. 1/4 sec. 36). The line ran down thru swamp with thick brush - alders & willows - some tamaracks - very wet. When we broke out of brush into open marsh near creek as called for in gull notes we could go no farther. It was too wet & could not walk on bog without breaking thru. I believe the corner is in as Curran set a five man. cor. here & we have found mist of the rest on this township line set by him but a good line will have to be run in to this corner in the winter to locate it.

time spent = 3 1/2 hr.

X-21 1/4 sec. cor.

35 36

T. 44N., R. 31 W.

D. Rasmussen
T. Converse

9/15/81

We did not search for this corner. By looking at the quadrangle & viewing the area in the field we decided this corner was inaccessible at this time. It may be possible to get to this corner in winter when swamp is frozen. There is no evidence of anyone being at this corner since the orig. gull post was set. We observed no fences running to this corner from any direction & no one we have talked to has any knowledge of this corner. I do not believe anything would be found at this cor.

E-19 1/4 sec. cor.

2
11

T. 43 N., R. 31 W.

Found no evidence of original
gov't survey or any resurveys.

We assumed the corner to
be on E of the road and
on fence north & south.

We had some magnetic
dips but these were all
rocks - no road excavation
other than digging up these
rocks was made.

time spent = 1 1/2 hours

E-17 1/4 sec. cor.

4
11

T. 43 N., R. 31 W.

No. S-118

farm
bldgs.

Pasture

583°W Asphalt

assumed
corner

edge road


wooded

alfalfa
field

1715/81

D. Rasmussen
T. Converse

155°E Clear



E-17

Sec. Cor.

3

2

10 11

T. 43 N., R. 31 W.

Found R.R. spike .5' east of & 1.0' north of & on surface of asphalt hwy. Removed spike to dip below it. Nothing else was detected. Replaced R.R. spike & measured to 3 existing ties. No other magnetic dips were found - road was not excavated. No other evidence was found. Curro's S monument corner would fall entirely in road bed & has been removed. None of the previous B.T.'s exists. The military reservation line called for in gov't notes is not in evidence. Road grade is filled above surrounding ground as shown on sketch.

time spent = 1 1/2 hours

E-17 Sec. Cor.

3

2

10/15/81


D. Rasmussen

T. Converse

T. 43 N., R. 31 W.

T. 55° E. Clear

No. S-118



Note: RR spike found .5' east of & 1.0' north of &. All ties were existing.

V-19 1/4 sec. cor.

26
35

T. 44 N., R. 31 W.

Found no evidence of original
goat survey or any resurveys.
I don't believe this corner
has been used or marked for
quite some time. The landowners
by the this corner in both
sections 26 & 35 own the
land both east & west of
this corner so there is no
evidence of any north-
south lines.
There are some large pines &
old stumps north of the
fence but none could be
identified as B.T.s.

time spent = 2 1/2 hours

V-19 1/4 sec. cor.

26
35

T. 44 N., R. 31 W.

No. 8-118

Jackson
house

bean
field

wooded (decid.)

wooded (decid.)

N 12° E

assumed
location
goat meas.

698'

N 80° E

old fence

wooded (mostly on
Ks. aspen)

N

10/16/81

D. Rasmussen

T. Converse

+ 55° F. Clear

43

V-21

Sec. Cor.

26

25

35

36

T. 44 N., R. 31 W.

Found no evidence of original
gav't survey or any resurveys.
We found an old remnant
east-west fence & followed it
east to what appears to be
an old pen (woven wire fence).
The east-west fence ends here.
We projected it east to edge
of swamp & meas. back west
using 'gav't distance to look for
corner. This location falls close
to a trail. The distance east-
west across high ground is very
close to gav't measure but the
dist. south to edge of swamp
is quite a bit long. One of
the gav't land calls appears to
be wrong.
It does not appear this corner
has been marked for quite
some time.

Time spent = 3 1/2 hours

V-21

Sec. Cor.

26

25

35

36

T. 44 N., R. 31 W.

Found no evidence of original
gav't survey or any resurveys.
We found an old remnant
east-west fence & followed it
east to what appears to be
an old pen (woven wire fence).
The east-west fence ends here.
We projected it east to edge
of swamp & meas. back west
using 'gav't distance to look for
corner. This location falls close
to a trail. The distance east-
west across high ground is very
close to gav't measure but the
dist. south to edge of swamp
is quite a bit long. One of
the gav't land calls appears to
be wrong.
It does not appear this corner
has been marked for quite
some time.

Time spent = 3 1/2 hours

V-21 Sec. Cor.

26

25

35

36

T. 44 N., R. 31 W.


No. S-118

10/6/81

D. Rasmussen

T. Converse

5500 F. clear




⑨

nd

(5057)

E-13

743



C-13 1/4 sec. cor. 4-3

T. 43 N., R. 31 W.

Found no evidence of original
gov't survey, or any resurveys.
We assumed corner at E road
and powerline to west which
appears to line up with fence
farther west.

Mr. Ben F. Fleischhacker
landowner in NW 1/4 sec. 4 and area
resident since 1932 stated that
to his knowledge this corner
had never been marked. He
put up fence to west & did not
know if it was in right place.
We did not excavate road.

No magnetic dips.

Time spent = 1 hour


C-13 1/4 sec. cor. 4-3

T. 43 N., R. 31 W.

10/19/81 D. Rasmussen (48)
T. Converse

+55°F Cloudy & windy

No. S-118



Road excavated 30" each side
of & graded up 1'-2' above
ground level

V-23 1/4 sec. Cor. $\frac{25}{36}$

T.44 N., R.31 W.

Found no evidence of original gov't survey or any resurveys. We followed fence line, which appears to be near N's 1/4 line, south into swamp & searched an area south of the end of fence 200'-300' - found nothing. Fence just wanders around after it enters swamp.

Mrs. Brender, owner in sec. 25, did not know of any corners or lines in this area. She said that at sec. cor. to east a fence was run west but stopped when it got too wet. This fence can be seen from C.S.A.H. #5. We did not try to follow it in. Mr. A.

Vohnson, landowner in sec. 31-44-30, and area resident for 47 years. did not know of anything marking this corner. I believe this corner is lost & that nothing is left to mark its location.

Time spent = 2 1/2 hours


V-23 1/4 sec. Cor. $\frac{25}{36}$

1908 D. Kasmussen
T. Converse (49)

T.44 N., R.31 W.

+40° F. P.H.V. Cldy.

No. S-118



E-11 1/4 sec. cor. 4 9

T. 43 N., R. 31 W.

Found 2" road monument 18" below surface of road. It was broken off @ top. We set 1/2" x 18" pipe over this flush with road surface. We found none of Corp's witness monuments set in 1928. Mr. Ben F. Fleischhacker, landowner in N 1/4 sec. 4 and area resident since 1932 stated that when the county graded up this road 25 years ago they removed the witness monuments & laid them by fence on edge of road, but have since disappeared. None of original B.T.s left.

We did not excavate road further.


Made 3 new B.T.s - top & bottom blaze on face - meas. to bottom blaze

Time spent = 2 hours

E-11 1/4 sec. cor. 4 9

T. 43 N., R. 31 W.

No. S-118



E-9 Sec. Con.

T. 43	W.	R. 31 W.
-------	----	----------

Found no evidence of original
gov't survey or any resurvey.
It appears that Curro's 5 man
corner fell entirely in road
limits.

construction. We assumed the corner to be on fence to south & on E. road. This location lines up with fence & road which can be seen about $3/4$ mile north hill. A creek and swamp area falls between this cor. to north.

Mr. DeWayne Tautges lifetime area resident owns property on both sides of section line north of road. He stated that county graded up road 25 years ago. His brother pulled out a stake on south side of road when they were kids - probably a witness man. He has always believed fence to south to be line.

time spent = $1\frac{1}{2}$ hours

E-9 Sec, Cor

5	4
8	9

10/20/81 D. Rasmussen
T. Converse (51)

T. 43 N., R. 31 W.

No. 51130

+40°F: cloudy + windy

