


Crow Wing County Surveyor
No. S-124



D. S. K. 22

Surveyor
W.H. Miller
North

Survey #
S-1214

Index

Page "A" S/4 21-43-31 E-11 ~~23~~

Page #1 Corner

1	E/4 6-43-31	C-5
2	S/4 6-43-31	E-3
3	6-43-31 (cont)	
4	SE 6-43-31	E-5
5	W/4 6-43-31	C-1
6	W/4 7-43-31	G-1
7	SW 7-43-31	J-1
8	SW 7-43-31	J-3
9	SE 7-43-31	J-5
10	E/4 7-43-31	G-5
11	S/4 8-43-31	J-7
12	E/4 8-43-31	G-17
13	E/4 8-43-31	G-9
14	W/4 10-43-31	G-13
15	SE 10-43-31	J-17
16	W/4 10-43-31	L-13
17	SE 15-43-31	N-17
18	SE 17-43-31	N-9
19	E/4 21-43-31	T-17
20	NE 21-43-31	R-17
21	W/4 21-43-31	T-13
22	W/4 34-43-31	X-13
23	SW 34-43-31	Z-13



Index (cont)

Page #	Corner	
24	S 1/4	26-43-31 V-19
25	SE	26-43-31 V-21
26	S 1/4	25-43-31 V-23
27	S 1/4	27-43-31 V-15
28	SW	27-43-31 V-13
29	S 1/4	28-43-31 V-11
30	SW	33-43-31 Z-9
31	S 1/4	32-43-31 Z-3
32	E 1/4	32-43-31 X-5
33	S 1/4	33-43-31 Z-11
34	SE	14-43-31 N-21
35	E 1/4	14-43-31 L-21
36	SE	13-43-31 N-25
37	S 1/4	13-43-31 N-23
38	E 1/4	24-43-31 P-25
39	S 1/4	24-43-31 R-23
40	N 1/4	14-43-31 J-19
41	E 1/4	11-43-31 G-21
42	E 1/4	13-43-31 L-25
43	N 1/4	13-43-31 J-23
44	NW	13-43-31 J-21
44-A	S 1/4	23-43-31 R-19
45	SE	23-43-31 R-21
46	E 1/4	26-43-31 T-21

Tuesday (cont.)

Page #	Cont.	
17	E/4 23-43-31	P-21
18	S/4 24-43-31	R-23
19	E/4 25-43-31	T-25
20	SE 36-43-31	Z-25
21	SE 31-43-31	Z-S
22	34-43-31 (cont.)	—
23	E/4 31-43-31	X-S
24	SE 34-43-31	Z-17
25	34-43-31 (cont.)	—
26	S/4 31-43-31	Z-3
27	SW 31-43-31	Z-1
28	31-43-31 (cont.)	—
29	S/4 31-43-31	Z-15
30	S/4 35-43-31	Z-19
31	SE 35-43-31	Z-17
32	1/4 36-43-31	Z-23
33	36-43-31 (cont.)	—
34	E/4 36-43-31	X-25
35	36-43-31 (cont.)	—
36	S/4 35-43-31	N-15
37	SW 35-43-31	N-13
38	SE 36-43-31	9 N-9
39	S/4 36-43-31	N-11
40	36-43-31	N-7

C-21 E 1/4 2-43-21

C-19 E 1/4 5-43-21

J-15 S 1/4 10-43-21

J-19/20 ^{West 1/4} 11-43-31

These corners were
to wet to get at
under the bridge.

④

5/4 Cor. 5. 21-43-31

42/4

NO. 447

NAME _____

10

55

65206

54508
DO.

3/3/72

...

303

260.01

24



C-5 1/4 sec. cor. 6+5

T.43N., R.31W.

Found no evidence of original
gov't survey or any resurveys.
There are no east-west fences
in this area & no east-west
property lines as the owners
on both sides of the road
own the land both north & south
of the corner.

From observation of aerial photos
and the quadrangle we assumed
the corner to be in the road
& on edge of field & brush to
east. The measure from edge
of swamp to north to this
location matches very closely
to orig. gov't meas.
Road is 1' above surrounding
ground.

No magnetic dips - did not
excavate road.

time spent = 1 1/2 hours


10/22/81 D. Rasmussen

T. Converse

C-5 1/4 sec. cor. 6+5

T.43N., R.31W.

+20°F Snow & Windy



E-3 1/4 sec. cor. 6/7

T.43 N., R.31 W.


Found no evidence of original govt survey or any resurveys. Mr. Perlinger landowner in sec. 7 had no knowledge of the 1/4 corner location. He owns the land both east & west of N-S 1/4 line. He bought the land in 1937 from H. Anderson, brother of Gov. C. Elmer Anderson. Anderson's father owned the land before that. Mr. H. Anderson lives in Brainerd on Oak St. The old remnant fence to south was in place when Mr. Perlinger became the owner. Mr. Perlinger also stated that R. Koering who owns sec. 14-south sec. 6 put in fence to north & it may not be accurate. This is newer fence. We assumed corner to be on E road & on fence to south. At this location the road bed is cut 10'± from bank (continued)

E-3 1/4 sec. cor. 6/7

T.43 N., R.31 W.

10/22/81 D. Rasmussen
T. Converse

+25°F Snow & windy



E-3

(continued)

on south side of road &
filled 1'-2' above ground level
on north side of road. It
appears at the existing
road grade is cut 5' from
natural ground level.
We had no magnetic dips
No road excavation was
made.

time spent = 1 hour

E-1 Sec. Cor.
R. 32W. 1 6 R. 31W.
12 7
T. 43N.

Found maze nail in & road intersection on surface of asphalt.

There has been considerable road work done @ this intersection + None of the old B.T.s listed on county records is left as they fall within construction limits. Road has been filled in some areas & cut from natural ground in others as shown on sketch.


No other magnetic dips were found & no road excavation was done.

We made 3 B.T.s for nail found. They have top & bottom blaze on face of tree - measured to bottom blaze.

time spent = 1 1/2 hours.


E-1 sec. Cor.

T. 43N. R. 32W. 1 6 R. 31W.
12 7



1921/21 D. Rasmussen
T. Converse

+25°F Snow & Wind



C-1	1/4 sec.	Cor.
1	1	1
2	2	2
3	3	3
4	4	4
5	5	5
6	6	6
7	7	7
8	8	8
9	9	9
10	10	10
11	11	11
12	12	12
13	13	13
14	14	14
15	15	15
16	16	16
17	17	17
18	18	18
19	19	19
20	20	20
21	21	21
22	22	22
23	23	23
24	24	24
25	25	25
26	26	26
27	27	27
28	28	28
29	29	29
30	30	30
31	31	31
32	32	32
33	33	33
34	34	34
35	35	35
36	36	36
37	37	37
38	38	38
39	39	39
40	40	40
41	41	41
42	42	42
43	43	43
44	44	44
45	45	45
46	46	46
47	47	47
48	48	48
49	49	49
50	50	50
51	51	51
52	52	52
53	53	53
54	54	54
55	55	55
56	56	56
57	57	57
58	58	58
59	59	59
60	60	60
61	61	61
62	62	62
63	63	63
64	64	64
65	65	65
66	66	66
67	67	67
68	68	68
69	69	69
70	70	70
71	71	71
72	72	72
73	73	73
74	74	74
75	75	75
76	76	76
77	77	77
78	78	78
79	79	79
80	80	80
81	81	81
82	82	82
83	83	83
84	84	84
85	85	85
86	86	86
87	87	87
88	88	88
89	89	89
90	90	90
91	91	91
92	92	92
93	93	93
94	94	94
95	95	95
96	96	96
97	97	97
98	98	98
99	99	99
100	100	100

R.32w. 6 R.31w.

Z. 43 W.

Found no evidence of original govt survey or any resurveys. Early new road construction appears to have destroyed corner. New fill put on road - may have graded old road down, dug out ditches & hauled in new fill. We assumed corner to be on E road & on fence to east. This location falls right on the north edge of swamp as called for in govt notes.

time spent = 1 hour


C-1 $\frac{1}{4}$ sec. cor.

R.32w.1 + 6 R.31w.

T.432.

10/22/81 D. Rasmussen (5)
T. Converse

+25°F cldy. & windy



G-1 1/4 sec. cor.

Found spike in E road & on fence east & west - 2" below grade. Spike was bent - removed - no magnetic dip below - replaced with new 8" spike. Made 3 new B.T.s. Fence lines are old. There are some good size trees growing up along these fences. The width of road construction is 36' ± - does not appear to have been much road work recently. Road grade is at surrounding ground level ± - no ditches. Stopped @ R. Koering farm to inquire about corner - no one home.

No road excavation.
No other mag. dips

Time spent = 1 hour

G-1 1/4 sec. cor.

+25°F Cloudy & Windy

R. Koering farm

hail in east side of 12" W. oak

Gas 23.30


5" 6' oaks

6" R. oak

12-43-32
7-43-31

10/22/81

D. Rasmussen
T. Converse



NE & NW B.T.s have top & bottom blades in face - meas. to bottom

$$\begin{array}{r} 18 \\ 7 \end{array}$$

T. 43 N. , R. 31 W.

Found no evidence of original survey or any resurveys. Found fence lines running north-south of road in this location. Fence to south appears to be oldest fence.

Doug Gilson
sec. 18 said the fence was
his west boundary line. He did
not have knowledge of any
corner in road. All property
around here fenced in.
The construction width of
road is 60' $\pm$ road grade is
level with surrounding
ground.

No magnetic dips other than rocks.

No road renovation done.

Time Spent = 1 hr.

$$J-3 \frac{1}{4} \text{ sec. cor.}$$
$$7 - \frac{00}{1}$$

T. 43 N., R. 31 W.

old straight + *
fence thru middle
to" = 12" R. Oaks

Gilson house

D. Rasmussen (8)
T. Converse

+25°F. Cloudy & windy

const. limit

assumed per.	2854E
--------------	-------

Book

const. limit

25

G-5 1/4 sec. Cor.

7+8

T. 43 N., R. 31 W.

Found no evidence of original survey or any resurveys. We found pieces of an old remnant fence in the swamp lying down. There were a few old posts still standing. We were able to locate an old fence corner lying down & parts of a fence running west. A fence running south along edge of woods was also found. Mrs. Cash, landowner to south of corner said that fence running south along woods just went around field & was not necessarily line. She did not know of any corner or where the section line ran. She did not know of old fence in swamp.


Time spent = 2 hours

G-5 1/4 sec. Cor.

7+8

T. 43 N., R. 31 W.

o = standing fence posts



10/22/81 D. Rasmussen
P. Skogen

+25°F Cloudy

$$\sqrt{-7} \quad \frac{1}{4} \text{ sec. cor.} \quad \frac{8}{17}$$

T. 43 N., R. 31 W.

Found no evidence of original survey or any resurvey. We located a fence corner in swamp. There are several posts lying down or leaning at this corner. The fence running west has new steel posts. The fence running east has old wood posts. The fence running north has wood iron pipe posts.

The gov't notes do not call for this swamp, but the edges are definite, its wet, or I'm sure it was here at the time of orig. gov't survey. we could not find orig. B.T.s. They're gone.

time spent = $1\frac{1}{2}$ hours

J-7 $\frac{1}{4}$ sec. cor. $\frac{8}{17}$

T.43N, R.31W.


Found no evidence of original survey or any resurveys.

The gov't notes do not call for this swamp, but the edges are definite, its wet, or I'm sure it was here at the time of orig. gov't survey. we could not find orig. B.T.s. They're gone.

time spent = $1\frac{1}{2}$ hours

10/23/81 D. Kasmussen
P. Skogen ⑪


+ 25°F. Cloudy.



G-17 1/4 sec. Cor. 10 11
T. 43 N., R. 31 W.

Found no evidence of orig. gault survey.
We found a broken off Aspen with a lath on it facing SW. The tree had grown around lath. We assumed this to be one of the counties 1959 B.T.s for their approximate 1/4 corner. We set a 3/8" x 8" spike in road at the cor. dist. from the Aspen tree. This location fell on a fence west we did not find Curio's 5 min. cor. It was evidently destroyed during road const. between 1936 & 1959.
Road has been filled 5' 6" in area where we set spike. North of this it has been filled 15' & south of this it has been cut to grade. No mag. dips other than rocks. No road excavation done.
Time spent = 2 1/2 hours

G-17 1/4 sec. Cor. 10 11
T. 43 N., R. 31 W.



G-9 1/4 sec. Cor. 8+9

T. 43 N., R. 31 W.

Found no evidence of original
gov't survey or any resurveys.
The fence corner we found is
properly corner according to
Robert Anderson, landowner is
NW 1/4, sec. 9.
The fences are straight-steel
iron pipe posts 4' high with
occasional old wood posts. Some
old wire lying down - must have
been an older fence here before.
There are some old rotted &
charred ^{pine} stumps in area - none
fit any B.T.s. on records.
Must have fire here at one
time.

Swamp to south not called for
in gov't notes but is very
evident.

No mag. dips other than racks.


time spent = 1 1/2 hours

G-9 1/4 sec. Cor. 8+9

T. 43 N., R. 31 W.

10/26/81 D. Rasmussen (13)
P. Skogen

#40°F P.tly. Cldy. & windy



G-13 1/4 sec. cor. 9+10


T. 43N., R. 31W.

Found no evidence of original govt survey or any resurveys. We tried to contact the landowners around this cor. Most of them were not around. We did learn that Mr. Elmer White whose land runs up to E-W 1/4 line in sec. 10 owns the ball field & the north side of ball field should be close to 1/4 line. We assumed the corner to be on E of road & on fence west. This location puts the E-W 1/4 line sec. 10 just north of backstop. The dist north to sec. cor. is close to govt. No mag. dips - No road excav. Road grade is at surrounding ground level - ditches are shallow.

Time spent = 2 hours.

G-13 1/4 sec. cor. 9-10

T. 43N., R. 31W.



10/26/81 D. Rasmussen (P) P. Skogen

+40°F P'tly. cloudy & windy

15th Mathias
Stake

Gravel
road

Wooded

Backstop

Ball field

51-41

T43N, R31W

Found no evidence of original gov't survey

Found a Crow Wing County Cast Iron Monument 86 feet below existing grade. Corner is 2 feet south of east fence line

Pulled land ties to the creek and edge of swamps. The creek to the south of $\frac{1}{4}$ corner has been routed through the culvert 390' from the $\frac{1}{4}$ corner. Both low areas have definite edges.

when they put the road in they had to fit it 5 to 7 feet in spots. when they did it they must have rerouted both creeks to there present location. Consider the width of the road is 95 feet

Time Spent - 1 1/2 hrs

L-17 1/4 Corner

51


T43N, R31W

2 boxes of
11/2 boxes of

T. Converter

1812101

1-50° Clear and Windy



N-17 Section Corner
T43N, R31W

15 14
22 23

Found no evidence of govt survey

Found a round capped monument 14" below existing grade. Monument is 3' south of E ext. west road and 2' east of E north, south road. We placed a 1" x 8" iron pipe over the monument. 611 below existing grade.

All previous tie monuments and lines were wiped out when the county came through and re-did the rail. Found an existing nail in a power pole. We measured 53.91' feet and the county records call for a power pole at 55.00' southeast.

There were no land ties to the govt. notes. The land is flat to the west and slopes up towards the east. The road ditches are approx 2 to 3 feet deep.

Time Spent - 1 1/2 hours


N-17 Section Corner

15 14
22 23

T43N, R31W

P. Skogen
T. Converse
10/27/81

+51° clear



T-17 1/4 corner 27-26

T43N-R31W

Found no evidence of original gov't survey
Found a "solid pin in the E North South road and E of road to the west. Iron pin is 0.5' below existing grade. Could not find any of the S monuments that John Caro set in 1923. Must have been graded out when they put the road in.

Talked to Mr. Kleinschmidt and he said, "that the fence line is on the 1/4 line." The fence line runs in a straight line up with the monument.

County had to fill in the area North of the corner to build the road. The road is level with the ground to the south of the 1/4 corner.

Time Spent - 1 1/2 hours


T-17 1/4 corner

27-26

T43N-R31W

P Skogen
T. Conliffe
10/27/81

+50' Survey



Construction Limits: 65 feet

X-17 T43N, R31W

34-35

Found the location of original
 county corner road. We returned E of the county
 Road and fence line to the original
 as being the 1/4 corner. It remained
 corner 111 on the south side of
 a 250' wide county. There were no
 land claim in the lot. It
 was a lot to the south follows
 section 111 and 112. It is
 corner.


The lot was many years old
 and in the original survey
 (6000 ft) dug. The road was
 in 3404 feet above the
 road level.

Time spent - 1 hour

X-17 1/4 Corner
 T43N, R31W

34-35

P. S. 10/28/61
 110° 0' 0"



V-19 1/4 Gen Rev - 28

THIRTY-NINE

Found no evidence of a
gov't survey.

For Xerox

I found a record captioned "Bourbon
10' Below existing 10' depth. The
monument is slightly later."

In 1921, John Curo came through and set up 5 permanent cells. The result to the outbreak was laid over by a demand to all keep up.

used. The one to the North will
be topped out by a hill. The
one that lies to the west will

falls 2 ft. E. of front topped man.

The City of New York

WILLIAM L. GORDON

of the present

Mr. C. C. Jones the North

res of Sec 35. (MATH) The

off camp for the night. The next morning

and you'd make

1. EPT 111

V-19 1/2 Corner

T43N, R31W

12-13-2019

P. S. K. 1. 1. 25

Taylor's Theorem

This page contains
201 of 201 pages
of the document
The document is
a PDF file
The document is
a PDF file

92 Dec 26
545
Oval - covered in padding

X
NAME
Wife

1000
 1000
 1000

Gravel

1201

Sub

100

T. 43, R. 31	S. 45, T. 40
--------------	--------------

found 1.0' above

land

[illegible]

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

—

$$\frac{25}{25}$$

T43H, B31V

Found no evidence of any
gov't survey or any survey.
Assumed & of road and E of
same assumed to all E. 41)
to be the 1/4 corner.

INDEX

The	1001	1-20
-----	------	------

[illegible]

June 2nd - 1965


V-23 / 400111

P. S. 11. 26

१५

T43N, R31W

+45° Clear, visibility



V-25 1/4 Corner
V-15 1/4 Corner

27
34

T43N, R31W

Found monument
gone & empty

Found a 1/2" iron pipe
exposed below the
surface

Found a 1/2" iron pipe
exposed below the
surface

Found the monument to the
NW and SE monument

was fully bent over and the
NW and SE monument were
burned by the fire when
the monument was by fields

The monument was by fields
and the 1/2" iron pipe
was exposed below the
surface

The monument was 1/2 above
the ground and

Found a 1/2" iron pipe

V-15 1/4 Corner

27
34

T43N, R31W

Cultivated
Field

1/2" Iron pipe filled with
concrete with iron cap
beside pipe

Gravel
Road

Egg Rock

small capped monument
badly bent over
did not get a chance
to it

Cultivated
Field

Correlation
Limits = 60'

P. Skarn 2D
T. Convergence

10/29/81

+43° 0' 0" wind

old run down
cut into it

Cultivated
Field

WOODS
1/2" Asphalt
top of iron pipe
plate (new tire)

1/2" Bar Oak
with top of
location (new tire)

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° W
40' 0"

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

N 81° E

Found 1/2" Iron pipe filled
with concrete 10' below
surface of field

1/2" Iron pipe filled with
concrete


V-13 Section 14147

25

100

100

133-243-1



Z-9 Section Corner

TURN 32
RAIL 33
TURN 33
RAIL 34

Township Line


Found no evidence of original govt survey.

Found a Morrison County Cast Iron Monument 0.8' below existing Road Grade. Monument is 10' feet north of east, west road and 1.0' east and 0' north road.

Talked to Paul Monkowski the NE 1/4, Sec 33, T42N, R31W. He said that he had his land surveyed one month ago and that he put the corner in place. He also said that the corner had to be set in place to do so. He said that the corner was set in place by the surveyor. He said that the corner was set in place by the surveyor. He said that the corner was set in place by the surveyor. All the trees were existing with Brass tag stamped RLS # 10832. Road is level with the existing ground elevation.

Time Spent - 1 1/2 hours

Z-9 Section Corner
TURN 32
RAIL 33
TURN 33
RAIL 34
P. Slooten
T. Converse
10/29/81
+57° Clockwise



2	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72	73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96	97	98	99	100
---	---	---	---	---	---	---	---	---	---	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	----	-----



2-2 1/4 corner


A vertical line with labels N, S, E, W and numbers 1, 2, 3, 4.

P Skogen
T Converter
10/29/81

Topic: _____

Found no evidence of erosion
gave survey on only 200 yd.
Paul Monk found the NE $\frac{1}{4}$,
S25.5° T42N R6W, he plotted the
the $\frac{1}{4}$ line is on his 1/4. E. line
road is a little farther
by monument, but a 200
line is on his 1/4
survey.

Note swamp trees on the diagram.
Note that we don't make
the river the dip in the valley
no road was made
The road was built on the
top of the ridge. The
valley floor was ground level
The north and south
slopes were level to the south



$$X - q \frac{1}{4} \text{corr } r$$

T-43N, R31W

27.1

Found no evidence of original
gov't survey or original survey.
We assumed a distance of
2640' from the section corner
to the well to be the $\frac{1}{4}$ corner
Tried to talk to area
farmer but they had no
knowledge of well location
place or knew nothing about
it.

The ground didn't like the
water and the ivy
field the only place the area
was the one to the east of
the road.

Many magnetic rocks in the area. Some even have iron.

Did road in local with the
curved the any location

The Gift of Love


1/4 Corner

T43N, R31W

32 : 33

P. Sk341. Q2
T. Converse
10/29/81

+HS Cloudy & Windy



Z-11 1/4 corner
Township Line

T 42 N
R 31 W
T 42 N
R 31 W


Found no evidence of or and
gov't survey or div. reserve
Assumed 1/4 corner to be E
road and fence line to the
south.

Found remnants of an old
driver; 28 feet west of assumed
corner

See diagram for exact and
exact location to the
road and fence line. Leave the
road and fence line to the
south. (See sketch of
road and fence line)
Found 1/4 corner - road
and fence line to the
south. Road and fence line
were found
Road is level in places and
above to the north and
below just below the
road and fence line.

Time Spent - 1 hour

Z-11 1/4 corner
P. 83
T. 42 N
R. 31 W
10/29/91
45 Clover



L-21 1/4 Corner

14-13

T43N, R31W

Found no evidence of original
gov't survey.
Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

In 1928 John A. Curo came
through with a logging
cabin in the road cut
about 1/2 mile west of the
road cut.

The logging road cut
had been in the road cut
about 1/2 mile west of the
road cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

1 1/2 hours

L-21 1/4 Corner

14-13

T43N, R31W

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

1 1/2 hours

P. Seeger (35)
10/30/81

14-13

T43N, R31W

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.


Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

Found a round capped iron nail
of iron from L-21. Found 15 feet
west of the trail, a few feet
west of the original 18 foot road
cut.

1 1/2 hours




P. S. Grogan
T. C. Grogan
10/2/81

N-25
Section 13
Center
Township Line
T13N R25W
T14N R25W
T15N R25W

N-25
Section 13
Center
Township Line
T13N R25W
T14N R25W
T15N R25W

For J. J. Grogan
govt survey
Found a 1/8" circle 2 feet south of
E. of road, west end of road 2 feet
south of E. East West road. We
replaced bird stake with 1 1/2" x
18" Iron pipe in the hole.
over the line.

Time Spent - 1 1/2



三

100%	100%
100%	100%

T 4214, 1214

The road crosses the
the ground level will
be about 10 feet above
the ground level.
The road is level with
the ground level to the
south and 1-2 feet below


1

N-1/4 corner

T-13N, B31W

+45 Rain

P Skogen 39
T. Conners
10/26/81



D-17, 18 Meander
Corner

11
14

T43N, R31W

Found no evidence of original
gov't survey or any resurvey.

From observation of the quad-
rangle we scaled a distance of
250 feet south of the creek to
be the section line.

There are no fence lines in
the area.

Talked to Mrs. Marvin Falk (owns
the SW $\frac{1}{4}$ of the NE $\frac{1}{4}$ and the
NW $\frac{1}{4}$ of section 14, T43N, R31W)
and she knew of nothing in
the area.

The dam was built in 1937 and
is holding back approx. 2 feet of
water.

The corner could possibly be
underwater because of the dam.


No magnetic dips in the
area. No excavation was made.

Time Spent - 1 1/2 hours

D-17-18 Meander
Corner

11
14


T43N, R31W



Dam built in
1937

Assumed distance
from scale off the
quadrangle

Round
LAKE



NO. 447

REBLIND

11
14

11
14

P. G. G. G. G.
T. G. G. G. G.
11/2/81

FSS Survey

D-17, 1/8 Meander

G-21 1/4 corner

11-12

TURN, R31W

Found no evidence of original
gov't survey or any resurvey.
Assumed the E. of north line
fence and edge of Norway
plantation to the east.
The fence line running north
and east was old Norway
plantation. It was
There is a 15-20 year old
Norway plantation to the
south of the a small
corner.

Dipped in the area and
nothing was found. No
excavation was made in
the area.

Time 1 hour


G-21 1/4 corner

11-12

TURN, R31W

D Skogen
T Corner
11/2/81

155° survey




T43N
13
R31W

Tourship Line

Found no evidence of the original gov't survey.
Found a $\frac{3}{8}$ " bent spike 0.3' below grade and in line of North/South road. We replaced the bent spike with a $\frac{1}{2}$ " x $\frac{1}{8}$ " x 18". Iron pipe 0.2' below grade.
See the county record for the history of this corner.
The fence line to the east lines up with the original survey. The fence is the best is 25 feet south of the assumed corner.

We took all needed things
with us. I carried
See the picture for how
we built the wall. The wall
and my. Box #2.
The wall is level with
the surface of a ground

Time Spent - 1 1/2 hours



L-21, 4/21/12

T-23 4/21/12

12
13

THAN ROW

Found no evidence of the original gov't survey or any remnant.

Assumed the gate distance from the public road they fit within 26 feet of the fence.

The fence running north-south was not over 10' wide.

The fence was made of brush and was not over 10' wide.

At the swamp tie distance to the old beat.

We did not see the fence corner by the swamp tie distance but found nothing but pieces of fence.

Time Spent - 1 1/2 hours

T-23 4/21/12

12
13

THAN ROW

Fence is 10' East of woods

Cultivated

Field

WOODS


WOODS

Low Area

R Skogen (43)

T. Co. 11/2/81

+ 600' ONLY



Remnant Line

Remnant Fence

235' N 84° E

175' 0"

Remnant

80' 0"

NO. 447

RELEVANCE

J-21 Section
corner
T43N R31W

11 12
14 13

Found no evidence of the
original govt survey or any
other key

Assumed a bearing from
J-23 down the fence line of
N 81° E (S 81° W) and it runs
about the edge of the
Sailed a line from the
intersection of the
from the J-23. went to
the J-23. Also put a
line from the J-23 to the
J-23.

Found no evidence of any
other lines, the
of a survey, be
in that area.


Time spent = 2 hours

J-21 Section
corner
T43N R31W

11 12
14 13

NOTE CLAYTON EISEL
C.H.D. MAINT. SUP.
Found I.P. at this

Cox. Will show
C.S.O. @ LATER DATE
T43S 11/18/81



P. Smith (41)
T. Conley (50)
11/2/81
+50° Sunny

R-19 1/4 corner

23

T43N R31W

26

Found no evidence of the original go/A survey.

In 1923 John and Edna S. purchased from original BT owner 10 1/2 of call west road. We found the road capped 0' below grade.

All well settled. road is in good condition. Monarch falls in line with the fence to the south and falls 6 feet west of the fence to the north. The fence to the north could possibly be the old military reservation line.

At 200 feet to the road we measured 520' and up to the road 100'.

Road is kept with the fence and is well settled and shallow.


Three Corners 1/4 corner

R-19 1/4 corner

23

T43N R31W

26



Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

12'

Edge Road

12'

12'

12'

12'

12'

12'

12'

T-21 1/4 Corner

26+25

TH2N, R31W

Found no evidence of the original gov't survey
 Found a 1 1/2" Bent iron pipe 30 feet below & existing road center. We replaced it with a 1" x 24" iron pipe where the old pipe went straight into the ground.

In 1921 John Auro set a 5 monument corner. We found the NW and SW monuments. The NE and SE monuments were ripped out and badly bent. Made tie to the oak tree.

There is a women wire fence line to the east.


Saw picture for swamp ties to the north. No landfills in the gov't track.

Road is 2 feet above the surrounding ground grade. Ditches are 2-3 deep clearing to the east of corner. Clearing is 12' wide and 300' and of pipe (over)

T-21 1/4 Corner

26+25

TH2N, R31W



Construction Width 54'

P. Skogren

T. Converse

11/3/81

+150° Survey

could possibly have been
on old road bed at one
time

Time Spent - 1 hour

NO. 447

W. TELSONE

$$\frac{R-23}{1/2}$$

T43N R31W

Found no evidence of the original gov't currency

Assume $\frac{1}{4}$ to be 2640 feet from each corner to the west. The distance from the fence line to the north

Tried to talk to her by properly answering, but nobody was home.

No magnetic dips in the
core + no magnetic field

The road is level to 2 feet higher than the surrounding area.

The cost = $\frac{1}{2}$ hour

R-23 1/4 Corner-

T43N, R31W

$$\frac{1}{2}$$


25

P. Skogen

T. Converse

11/3/81

11/11/15



Constructing
Lifting = 45

The fence line west of the
road has 2 poles
the R&G are in
the road and
Gaul's are for
a swamp 330' west of the
section corner. We measured
345'.

All the trees were
with a road in
showed R&G # 10232.

The road is 1-2 feet wide
the entire green track
width we 2-3' deep

Time spent — 1 hr

X-5 1/4 corner

31-32

T43N R31W

Found no evidence of the

original govt survey or any

other survey

Talked to Stanley Morgan (owns

the SE 1/4, NE 1/4, Sec. 31, T43N

R31W). As far as he knew

nothing was set in the area,

and the base corner is what

he called the SE corner of

the 1/4 section. So we assumed

the base corner was the

SE corner.

We govt notes call for

swamp then see diagram.

Govt calls for a swamp 360'

south of the corner. We measure

200' to the edge of a 100 feet

wide swamp.

Fence was grown into trees.

Fence post have either fallen

down or abraded.

Note: trail runs along the

edge to the N.

Time spent - 2 hours

X-5 1/4 corner

31-32

T43N R31W

WOODS

Low Area

(Brush and

Swamp

WOODS and

Brush

Low Area

Area

WOODS

T Convergence

11/12/81

150° Survey

Assume Railroad
The Fence Corner

N 85° W
10' wide trail

360'

200'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

100'

He said the county
resurfaced the road to
the west by removing
the crack and building the
new road south of the crack.

The wash pit area might
have wiped up my evidence
that might have been there.

The fence line to the east
is 60 feet south of the
ruined corner.

We assumed the gov't
notes to be all put up
because the fence has
been changed when the
county put the road in.

This road is 15-20 feet
above the existing creek.

The wash pit area is all
back. There is a lot
of construction in the
area. It has been used
many times.

No magnetic dips in area
The area has 2 hrs


Z-1 Section Corner
T43N 31 R32W T42N 6

Township Corner

Found no evidence of the original gravel pit. We found 2 spikes flush with the existing line to the east. We pulled these free and if the spikes in the road are the same as the ones we pulled, we will have no doubt. In the road, spikes bark in the proper spot. The spike to the east is 100 feet out of the ground corner. The ground is situated in a field. We made a new tie to the 4" Iron pipe. The tie to the south of the well is a new down line. See diagram for details. (New Tie)

Z-1 Section Corner
T43N 31 R32W T42N 6

Township Corner



P. Stogers
T. Gonsse
11/2/81
+50° Sunny

Z-1 (cont.)

The road is 6 feet above the ground grade to the North. I leveled with the ground grade to the North - each 2 feet below the ground grade to the southwest and 2 feet above the ground grade to the Southwest.

Time Spent - 1 1/2 hr

Z-23

Z-23

Township Line

TH3N	TH3N
TH3N	TH3N
TH3N	TH3N

Found no evidence of the original gov't survey or any recovery.

Talked to Mr. Robert Bjornson
owns the east $\frac{1}{2}$, NW $\frac{1}{4}$, and the
NE $\frac{1}{4}$. He also has his east
half corner on the NE $\frac{1}{4}$. He
said that this was his current
and the north $\frac{1}{4}$ corner is
1320' north.

We chained 1320 feet up hill
from here. The 1320 ft. fell
out in the top area. We found
a fence corner that intersects
the North-South fence and
then goes left. We also found
a fence that comes in from
the west (220 ft. south from
our starting point) to inter-
sect the fence. See diagram.
The only good land there that
we have are the one to
the west of the diagonal
corner. We introduced 15 bull
(Next Page.)

Z-23 1/4 corner

Z-23 1/4 corner


T 43 N	R 31 W
T 43 N	R 31 W
T 42 N	R 31 W

Township Line

R 31 W	R 32 W
--------	--------

P. Skogen
T. Converse
11/16/81

Township Line R3 v. +50 Supply



to the swamp - edge, gov't
will for swamp - edge at
low water. We left the
swamp at 2:00 feet, gov't
note. The swamp at
1320 feet
There were no gov't land
ties for the swamp to the
edge, so the track to
the north.
The 1320 feet was measured
from the fence corner - fell
50 feet south of the edge.
The diagonal land ties to
the north of the fence
corner
All fences in the area are
remnant fences.
Mr. Bjornson knows of
nothing being set or any
recovery in the area.
No, I regret, did so
no excavation was made.

Time spent - 2 hrs

NO. 447

W. E. D. V. E.


NEHL	TUHL
360	31
REHW	REOW

T-431
ZL
REOW

... of the ...
... ..
... ..
... ..
... ..
new to ... to ...
In 1944 the ...
Donnell ...
at ... to 7"
... ..
... ..
... ..
the county ...
the ...
... ..
... ..
and ...
... ..
(Meyers)

TH3N	31	R30W
TH3N	36	R31W

T. Converse
11/16/81
+500 Sunny



The gov't. note call for
a swamp 244 feet south
of the corner. We measured
215'. Gov't. notes will locate
a creek 140 feet south of the
swamps corner. We measured
265 feet.

The road is 112 feet above
the road with ditches 1-2
feet deep.

Time spent. — 1 1/2 hrs

N-15 1/4 Corner
T43N, R22W


T43N
R22W
15
22

N-15 1/4 Corner
T43N, R31W

T43N
R31W
15
31

P Skogen
T. Conner
11/16/81
+50° Survey

Found no evidence of the
original survey line in the
area.
Assumed E of County Road
#2 and 1/2 mile is the
line.
The mile is 800 ft. long.
The original line is the
line and 4 ft. long is the
section. The distance is 2
feet deep.
The line is 10 ft. long.
The line is 10 ft. long.
The line is 10 ft. long.
The line is 10 ft. long.



[illegible]


N-9 Section Corner
T43N-R31W

11	10	11	10
11	10	11	10

P. Skogen
T. Converse
11/17/81
+ 35° Cloudy

N-9 Section Corner
T43N-R31W

11	10	11	10
11	10	11	10



P. Skogen
T. Carvel, C

T43N, R31W

Hand-drawn map of a farm area. The map is oriented with a north arrow pointing towards the top right. The map is drawn on a grid of lines. The top section is labeled "Farm" and "House". The middle section is labeled "Farm" and "House". The bottom section is labeled "Farm" and "House".

A child's drawing on lined paper. At the top, the word "Road" is written twice, once on the left and once on the right. In the center, the word "County" is written. Below "County", there is a large, stylized figure that looks like a person or a creature with a long neck and a large head. To the left of this figure, the word "Bush" is written. At the bottom, there are several small, dark, irregular shapes that look like rocks or bushes. The drawing is done in black ink on a piece of lined paper with dashed midlines.

